

Americans With Disabilities Act (ADA) Transition Plan for the Public Right-of-Way



Snoqualmie, WA

Draft July 2023

Appendix B1

Public Right-of-Way GIS Inventory and Prioritization

Prepared by



Curb Ramp GIS Inventory with Prioritization

APS/RRFB/HAWK GIS Inventory

CURB RAMP GIS INVENTORY WITH PRIORITIZATION

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
408	Point M	20230382	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
407	Point M	20230381	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
406	Point M	20230380	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
405	Point M	20230379	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
349	Point M	20230303	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
348	Point M	20230302	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
347	Point M	20230301	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
389	Point M	20230364	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
390	Point M	20230365	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
391	Point M	20230366	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
392	Point M	20230367	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
388	Point M	20230363	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
385	Point M	20230324	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
386	Point M	20230325	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
387	Point M	20230362	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
331	Point M	20230285	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
330	Point M	20230284	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
325	Point M	20230318	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Unknown	Up to or equal to 8.3%
324	Point M	20230319	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Unknown	Up to or equal to 8.3%
329	Point M	20230320	C	Very Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
328	Point M	20230321	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
327	Point M	20230322	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
326	Point M	20230323	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
454	Point M	20230422	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
455	Point M	20230423	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
456	Point M	20230424	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
457	Point M	20230425	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
303	Point M	20230136	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
302	Point M	20230134	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
301	Point M	20230133	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
300	Point M	20230132	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
304	Point M	20230138	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
305	Point M	20230140	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
306	Point M	20230142	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
307	Point M	20230144	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
293	Point M	20230269	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
292	Point M	20230360	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
299	Point M	20230317	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
298	Point M	20230274	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
294	Point M	20230270	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
295	Point M	20230271	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
296	Point M	20230272	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
297	Point M	20230273	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
564	Point M	20230559	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
563	Point M	20230558	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
562	Point M	20230557	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
561	Point M	20230556	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
565	Point M	20230560	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
566	Point M	20230561	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
559	Point M	20230554	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
560	Point M	20230555	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
580	Point M	20230575	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
579	Point M	20230574	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
578	Point M	20230573	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
577	Point M	20230572	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
573	Point M	20230568	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
574	Point M	20230569	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
575	Point M	20230570	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
576	Point M	20230571	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
4	Point M	20230001	C	Very Poor	36" to > 48"	No DWS (Non-Compliant)	Unknown	Up to or equal to 8.3%
5	Point M	20230002	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
6	Point M	20230003	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
7	Point M	20230004	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
8	Point M	20230005	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
9	Point M	20230006	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
10	Point M	20230007	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
11	Point M	20230008	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
12	Point M	20230153	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
13	Point M	20230009	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
14	Point M	20230010	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
15	Point M	20230011	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
16	Point M	20230012	C	Very Poor	60" or greater	No DWS (Non-Compliant)	Parallel-Single Direction	Up to or equal to 8.3%
17	Point M	20230432	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
18	Point M	20230013	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
19	Point M	20230014	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
20	Point M	20230015	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
21	Point M	20230016	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
22	Point M	20230017	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
23	Point M	20230018	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
24	Point M	20230019	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
25	Point M	20230020	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
26	Point M	20230021	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
27	Point M	20230022	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

[illegible]

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
74	Point M	20230433	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
75	Point M	20230067	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
76	Point M	20230068	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
77	Point M	20230069	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
78	Point M	20230107	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
79	Point M	20230070	C	Very Poor	48" to >60"	No DWS (Non-Compliant)	Parallel-Single Direction	Up to or equal to 8.3%
80	Point M	20230108	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
81	Point M	20230071	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
82	Point M	20230072	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
83	Point M	20230073	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
84	Point M	20230434	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
85	Point M	20230109	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
86	Point M	20230074	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
87	Point M	20230435	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
88	Point M	20230075	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
89	Point M	20230076	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
90	Point M	20230436	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
91	Point M	20230077	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
92	Point M	20230078	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
93	Point M	20230079	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
94	Point M	20230110	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
95	Point M	20230080	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
96	Point M	20230111	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
97	Point M	20230081	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
98	Point M	20230082	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
99	Point M	20230083	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
100	Point M	20230084	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
101	Point M	20230112	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
102	Point M	20230085	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
103	Point M	20230113	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
104	Point M	20230086	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
105	Point M	20230437	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
106	Point M	20230438	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
108	Point M	20230440	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
109	Point M	20230087	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
110	Point M	20230088	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
111	Point M	20230114	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
112	Point M	20230089	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
113	Point M	20230090	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
114	Point M	20230091	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
115	Point M	20230115	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
116	Point M	20230092	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
117	Point M	20230093	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
118	Point M	20230094	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
119	Point M	20230095	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
120	Point M	20230116	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
121	Point M	20230096	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
122	Point M	20230097	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
123	Point M	20230441	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
125	Point M	20230098	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
126	Point M	20230099	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
127	Point M	20230117	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
128	Point M	20230118	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
129	Point M	20230100	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
130	Point M	20230119	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
131	Point M	20230101	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
132	Point M	20230102	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
133	Point M	20230103	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
134	Point M	20230104	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
139	Point M	20230150	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
140	Point M	20230151	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
141	Point M	20230152	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
142	Point M	20230154	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
143	Point M	20230155	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
144	Point M	20230149	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
145	Point M	20230156	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
146	Point M	20230157	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
147	Point M	20230159	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
148	Point M	20230160	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
149	Point M	20230161	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
150	Point M	20230162	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
151	Point M	20230163	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
152	Point M	20230164	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
153	Point M	20230165	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
154	Point M	20230166	D	Missing (Needed but does not Exist)	48" to >60"	No DWS (Non-Compliant)	Blended Transition	Up to or equal to 8.3%
155	Point M	20230167	D	Missing (Needed but does not Exist)	60" or greater	No DWS (Non-Compliant)	Blended Transition	Up to or equal to 8.3%
156	Point M	20230168	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
157	Point M	20230169	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
158	Point M	20230170	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
159	Point M	20230171	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
160	Point M	20230172	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
161	Point M	20230173	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Unknown	Up to or equal to 8.3%
162	Point M	20230174	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
163	Point M	20230175	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
164	Point M	20230176	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
165	Point M	20230177	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
166	Point M	20230178	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
167	Point M	20230179	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
168	Point M	20230180	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Unknown	Up to or equal to 8.3%
169	Point M	20230181	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
170	Point M	20230182	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
171	Point M	20230183	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
172	Point M	20230184	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
173	Point M	20230185	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
174	Point M	20230186	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
175	Point M	20230187	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
176	Point M	20230188	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
177	Point M	20230189	D	Missing (Needed but does not Exist)	60" or greater	No DWS (Non-Compliant)	Blended Transition	<Null>
178	Point M	20230190	D	Missing (Needed but does not Exist)	60" or greater	No DWS (Non-Compliant)	Blended Transition	<Null>
179	Point M	20230120	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
180	Point M	20230451	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
181	Point M	20230191	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
182	Point M	20230192	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
183	Point M	20230193	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
184	Point M	20230194	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
185	Point M	20230195	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
186	Point M	20230196	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
187	Point M	20230198	D	Missing (Needed but does not Exist)	<Null>	<Null>	Blended Transition	<Null>
188	Point M	20230199	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
189	Point M	20230200	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
190	Point M	20230201	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
191	Point M	20230202	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
192	Point M	20230203	D	Missing (Needed but does not Exist)	48" to >60"	No DWS (Non-Compliant)	Blended Transition	<Null>
193	Point M	20230204	D	Missing (Needed but does not Exist)	48" to >60"	No DWS (Non-Compliant)	Blended Transition	<Null>
194	Point M	20230205	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
195	Point M	20230206	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
196	Point M	20230207	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
197	Point M	20230208	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
198	Point M	20230209	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
199	Point M	20230210	C	Very Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
200	Point M	20230211	C	Very Poor	48" to >60"	No DWS (Non-Compliant)	Unknown	More than 8.3%
201	Point M	20230212	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
202	Point M	20230213	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
203	Point M	20230214	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
204	Point M	20230215	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
205	Point M	20230216	D	Missing (Needed but does not Exist)	48" to >60"	No DWS (Non-Compliant)	Blended Transition	<Null>
206	Point M	20230217	D	Missing (Needed but does not Exist)	48" to >60"	No DWS (Non-Compliant)	Blended Transition	<Null>
207	Point M	20230218	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
208	Point M	20230219	D	Missing (Needed but does not Exist)	48" to >60"	No DWS (Non-Compliant)	Blended Transition	<Null>
209	Point M	20230220	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
210	Point M	20230221	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
211	Point M	20230222	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
212	Point M	20230223	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
214	Point M	20230224	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
215	Point M	20230225	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
216	Point M	20230226	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
217	Point M	20230227	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
218	Point M	20230228	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
219	Point M	20230229	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
220	Point M	20230230	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
221	Point M	20230444	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
222	Point M	20230231	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
223	Point M	20230232	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
224	Point M	20230445	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
225	Point M	20230121	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
226	Point M	20230122	D	Missing (Needed but does not Exist)	60" or greater	No DWS (Non-Compliant)	Blended Transition	Up to or equal to 8.3%
228	Point M	20230123	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
229	Point M	20230124	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
230	Point M	20230125	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
231	Point M	20230126	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
232	Point M	20230447	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
233	Point M	20230127	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
234	Point M	20230448	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
235	Point M	20230128	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
236	Point M	20230129	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
237	Point M	20230130	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
238	Point M	20230233	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
239	Point M	20230234	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
240	Point M	20230235	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
241	Point M	20230236	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
242	Point M	20230237	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
243	Point M	20230449	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Unknown	<Null>
244	Point M	20230450	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
245	Point M	20230238	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
246	Point M	20230239	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
247	Point M	20230240	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
248	Point M	20230241	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
249	Point M	20230242	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
250	Point M	20230243	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
251	Point M	20230244	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
252	Point M	20230245	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
253	Point M	20230246	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
254	Point M	20230247	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
255	Point M	20230248	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
256	Point M	20230249	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
257	Point M	20230250	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
258	Point M	20230251	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
259	Point M	20230252	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
260	Point M	20230253	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
261	Point M	20230254	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
262	Point M	20230255	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
263	Point M	20230326	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
264	Point M	20230327	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
265	Point M	20230328	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
266	Point M	20230329	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
267	Point M	20230330	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
268	Point M	20230331	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
269	Point M	20230131	C	Very Poor	36" to > 48"	No DWS (Non-Compliant)	Unknown	Up to or equal to 8.3%
270	Point M	20230332	C	Very Poor	48" to >60"	No DWS (Non-Compliant)	<Null>	More than 8.3%
271	Point M	20230333	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
272	Point M	20230334	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
273	Point M	20230455	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
274	Point M	20230335	C	Very Poor	Less than 36"	No DWS (Non-Compliant)	Unknown	More than 8.3%
275	Point M	20230336	C	Very Poor	Less than 36"	No DWS (Non-Compliant)	Unknown	More than 8.3%
276	Point M	20230148	C	Very Poor	36" to > 48"	No DWS (Non-Compliant)	Unknown	More than 8.3%
277	Point M	20230337	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
278	Point M	20230338	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
279	Point M	20230339	C	Very Poor	36" to > 48"	No DWS (Non-Compliant)	Unknown	More than 8.3%
280	Point M	20230340	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
281	Point M	20230341	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
282	Point M	20230342	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
283	Point M	20230343	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
284	Point M	20230344	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
285	Point M	20230345	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
286	Point M	20230453	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Unknown	Up to or equal to 8.3%
287	Point M	20230347	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
288	Point M	20230452	A	Fair or Better	<Null>	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
289	Point M	20230454	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
290	Point M	20230458	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
291	Point M	20230351	C	Very Poor	36" to > 48"	No DWS (Non-Compliant)	Unknown	More than 8.3%
308	Point M	20230146	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
309	Point M	20230147	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
310	Point M	20230256	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
311	Point M	20230257	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
312	Point M	20230258	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
313	Point M	20230259	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
314	Point M	20230261	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
315	Point M	20230262	C	Very Poor	Less than 36"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
316	Point M	20230263	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
317	Point M	20230264	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
318	Point M	20230265	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
319	Point M	20230430	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
320	Point M	20230266	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
321	Point M	20230267	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
322	Point M	20230268	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
323	Point M	20230346	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
332	Point M	20230286	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
333	Point M	20230287	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
334	Point M	20230288	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
335	Point M	20230289	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
336	Point M	20230290	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
337	Point M	20230291	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
338	Point M	20230292	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
339	Point M	20230293	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
340	Point M	20230294	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
341	Point M	20230295	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
342	Point M	20230296	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
343	Point M	20230297	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
344	Point M	20230298	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
345	Point M	20230299	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
346	Point M	20230300	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
350	Point M	20230276	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
351	Point M	20230277	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
352	Point M	20230304	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
353	Point M	20230305	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
354	Point M	20230306	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
355	Point M	20230307	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
356	Point M	20230308	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
357	Point M	20230309	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
358	Point M	20230310	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
359	Point M	20230311	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
360	Point M	20230312	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
361	Point M	20230313	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
362	Point M	20230314	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
363	Point M	20230315	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
364	Point M	20230316	C	Very Poor	Less than 36"	No DWS (Non-Compliant)	Unknown	More than 8.3%
366	Point M	20230137	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
367	Point M	20230139	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
368	Point M	20230141	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
369	Point M	20230143	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
370	Point M	20230145	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
371	Point M	20230033	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
372	Point M	20230028	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
373	Point M	20230348	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
374	Point M	20230349	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
375	Point M	20230350	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
376	Point M	20230260	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
377	Point M	20230352	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
378	Point M	20230353	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
379	Point M	20230354	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
380	Point M	20230355	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
381	Point M	20230356	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
382	Point M	20230357	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
383	Point M	20230358	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
384	Point M	20230359	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
393	Point M	20230368	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
394	Point M	20230369	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
395	Point M	20230361	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
396	Point M	20230370	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
397	Point M	20230371	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
398	Point M	20230372	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
399	Point M	20230373	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
400	Point M	20230374	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
401	Point M	20230375	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
402	Point M	20230376	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
403	Point M	20230377	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
404	Point M	20230378	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
411	Point M	20230383	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
412	Point M	20230384	B	Poor	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
413	Point M	20230385	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
414	Point M	20230386	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
415	Point M	20230387	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
416	Point M	20230388	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
417	Point M	20230389	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
418	Point M	20230390	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
419	Point M	20230391	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
420	Point M	20230392	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
421	Point M	20230393	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Blended Transition	More than 8.3%
422	Point M	20230394	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Blended Transition	More than 8.3%
423	Point M	20230395	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
424	Point M	20230396	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
427	Point M	20230397	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
429	Point M	20230399	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
430	Point M	20230400	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
431	Point M	20230401	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
432	Point M	20230402	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
433	Point M	20230403	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
434	Point M	20230404	B	Poor	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
435	Point M	20230405	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
436	Point M	20230406	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
437	Point M	20230407	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
440	Point M	20230410	B	Poor	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
441	Point M	20230411	B	Poor	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
442	Point M	20230412	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
443	Point M	20230413	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
444	Point M	20230414	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
445	Point M	20230415	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
446	Point M	20230416	B	Poor	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
447	Point M	20230417	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
448	Point M	20230418	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
449	Point M	20230419	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
452	Point M	20230420	C	Very Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
453	Point M	20230421	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
458	Point M	20230426	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
459	Point M	20230427	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
460	Point M	20230428	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
461	Point M	20230429	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
462	Point M	20230459	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
463	Point M	20230460	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
464	Point M	20230461	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
465	Point M	20230462	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
466	Point M	20230463	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
467	Point M	20230464	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
468	Point M	20230465	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
469	Point M	20230466	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
470	Point M	20230467	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
471	Point M	20230468	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
472	Point M	20230469	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
473	Point M	20230470	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
474	Point M	20230471	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
475	Point M	20230472	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
476	Point M	20230473	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
477	Point M	20230474	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
478	Point M	20230475	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
479	Point M	20230476	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
480	Point M	20230477	C	Very Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
481	Point M	20230478	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
482	Point M	20230479	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
483	Point M	20230480	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
484	Point M	20230481	C	Very Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
485	Point M	20230482	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
486	Point M	20230483	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
487	Point M	20230484	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
488	Point M	20230485	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
489	Point M	20230486	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
490	Point M	20230487	C	Very Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
491	Point M	20230488	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
492	Point M	20230489	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
493	Point M	20230490	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
494	Point M	20230491	C	Very Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
495	Point M	20230492	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
496	Point M	20230493	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
497	Point M	20230494	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
498	Point M	20230495	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
499	Point M	20230496	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Diagonally Oriented	Up to or equal to 8.3%
500	Point M	20230497	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
501	Point M	20230498	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
502	Point M	20230499	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
503	Point M	20230500	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
504	Point M	20230501	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
505	Point M	20230502	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
506	Point M	20230503	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
507	Point M	20230504	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
508	Point M	20230505	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
509	Point M	20230506	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
510	Point M	20230507	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
511	Point M	20230508	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
512	Point M	20230509	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
513	Point M	20230510	C	Very Poor	Less than 36"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
514	Point M	20230511	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
515	Point M	20230512	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
516	Point M	20230513	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
517	Point M	20230514	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
519	Point M	20230515	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
520	Point M	20230516	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
521	Point M	20230517	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
522	Point M	20230518	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
523	Point M	20230519	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
524	Point M	20230520	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
525	Point M	20230521	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
526	Point M	20230522	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
527	Point M	20230523	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
528	Point M	20230524	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
529	Point M	20230525	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
531	Point M	20230526	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
532	Point M	20230527	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
533	Point M	20230528	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
534	Point M	20230529	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
535	Point M	20230530	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
536	Point M	20230531	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
537	Point M	20230532	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
538	Point M	20230533	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
539	Point M	20230534	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
540	Point M	20230535	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
541	Point M	20230536	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
542	Point M	20230537	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
543	Point M	20230538	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
544	Point M	20230539	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
545	Point M	20230540	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
546	Point M	20230541	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
548	Point M	20230543	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
549	Point M	20230544	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
550	Point M	20230545	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
551	Point M	20230546	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
552	Point M	20230547	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
553	Point M	20230548	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
554	Point M	20230549	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Parallel-Single Direction	<Null>
555	Point M	20230550	D	Missing (Needed but does not Exist)	<Null>	Old Standard (Diamond/Exposed Aggregate)	Blended Transition	<Null>
557	Point M	20230552	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
558	Point M	20230553	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
567	Point M	20230562	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
568	Point M	20230563	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
569	Point M	20230564	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
570	Point M	20230565	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
571	Point M	20230566	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
572	Point M	20230567	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
582	Point M	20230576	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
583	Point M	20230577	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

[illegible]

City of Snoqualmie
2023 ADA Curb Ramp Inventory

[illegible]

City of Snoqualmie
2023 ADA Curb Ramp Inventory

[illegible]

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
706	Point M	20230700	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
708	Point M	20230701	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
709	Point M	20230702	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
710	Point M	20230703	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
711	Point M	20230704	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
712	Point M	20230705	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
713	Point M	20230706	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
714	Point M	20230707	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
715	Point M	20230708	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
716	Point M	20230709	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
717	Point M	20230710	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
718	Point M	20230711	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
719	Point M	20230712	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
720	Point M	20230713	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
721	Point M	20230714	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
722	Point M	20230715	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
723	Point M	20230716	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
724	Point M	20230717	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
725	Point M	20230718	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
726	Point M	20230719	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
727	Point M	20230720	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
728	Point M	20230721	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
729	Point M	20230722	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
730	Point M	20230723	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
731	Point M	20230724	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
732	Point M	20230725	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
733	Point M	20230726	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
734	Point M	20230727	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
735	Point M	20230728	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
736	Point M	20230729	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
737	Point M	20230730	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
738	Point M	20230731	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
739	Point M	20230732	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
740	Point M	20230733	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
741	Point M	20230734	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
742	Point M	20230735	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
743	Point M	20230736	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
744	Point M	20230737	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Diagonally Oriented	More than 8.3%
745	Point M	20230738	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
746	Point M	20230739	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
747	Point M	20230740	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
748	Point M	20230741	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
749	Point M	20230742	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
750	Point M	20230743	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
751	Point M	20230744	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
752	Point M	20230745	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
753	Point M	20230746	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
754	Point M	20230747	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
755	Point M	20230748	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
756	Point M	20230749	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
757	Point M	20230750	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
758	Point M	20230751	C	Very Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
759	Point M	20230752	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
760	Point M	20230753	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
761	Point M	20230754	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
762	Point M	20230755	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
763	Point M	20230756	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
764	Point M	20230757	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
765	Point M	20230758	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
770	Point M	20230761	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
771	Point M	20230762	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
772	Point M	20230763	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
773	Point M	20230764	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
774	Point M	20230765	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
775	Point M	20230766	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
776	Point M	20230767	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
777	Point M	20230768	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
778	Point M	20230769	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
779	Point M	20230770	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
786	Point M	20230777	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

[illegible]

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
839	Point M	20230823	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
840	Point M	20230824	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
841	Point M	20230825	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
842	Point M	20230826	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
843	Point M	20230827	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
844	Point M	20230828	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
845	Point M	20230829	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
846	Point M	20230830	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
847	Point M	20230831	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
848	Point M	20230832	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
849	Point M	20230833	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
852	Point M	20230836	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
853	Point M	20230837	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
854	Point M	20230838	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
855	Point M	20230839	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
856	Point M	20230840	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
857	Point M	20230841	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
858	Point M	20230842	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
859	Point M	20230843	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
860	Point M	20230844	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
861	Point M	20230845	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
862	Point M	20230846	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
863	Point M	20230847	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
866	Point M	20230850	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
867	Point M	20230851	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
868	Point M	20230666	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
869	Point M	20230852	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
870	Point M	20230853	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
871	Point M	20231369	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
872	Point M	20230855	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
873	Point M	20230856	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
874	Point M	20230857	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
875	Point M	20230858	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
876	Point M	20230859	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
877	Point M	20230860	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
880	Point M	20230861	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
881	Point M	20230862	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
882	Point M	20230863	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
883	Point M	20230864	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
884	Point M	20230865	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
885	Point M	20230866	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
886	Point M	20230867	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
887	Point M	20230868	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
888	Point M	20230869	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
889	Point M	20230870	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
890	Point M	20230871	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
891	Point M	20230872	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
894	Point M	20230873	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
895	Point M	20230874	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
896	Point M	20230875	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
897	Point M	20230876	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
898	Point M	20230877	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
899	Point M	20230878	C	Very Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
900	Point M	20230879	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	More than 8.3%
901	Point M	20230880	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
902	Point M	20230881	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	More than 8.3%
903	Point M	20230882	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
904	Point M	20230883	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
905	Point M	20230884	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
906	Point M	20230885	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
907	Point M	20230886	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
908	Point M	20230887	C	Very Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
909	Point M	20230888	C	Very Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
910	Point M	20230889	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
911	Point M	20230890	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
912	Point M	20230891	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
916	Point M	20230892	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
917	Point M	20230893	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
918	Point M	20230894	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
919	Point M	20230895	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
920	Point M	20230896	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
921	Point M	20230897	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
922	Point M	20230898	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
923	Point M	20230899	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
924	Point M	20230900	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
925	Point M	20230901	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
926	Point M	20230902	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
927	Point M	20230903	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
928	Point M	20230904	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
929	Point M	20230905	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
930	Point M	20230906	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
931	Point M	20230907	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
932	Point M	20230908	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
933	Point M	20230909	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
934	Point M	20230910	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
935	Point M	20230911	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
936	Point M	20230912	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
937	Point M	20230913	C	Very Poor	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
940	Point M	20230916	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
941	Point M	20230917	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
942	Point M	20230918	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
943	Point M	20230919	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
944	Point M	20230920	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	More than 8.3%
945	Point M	20230921	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
946	Point M	20230922	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
947	Point M	20230923	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
948	Point M	20230924	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
949	Point M	20230925	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
950	Point M	20230926	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
951	Point M	20230927	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
952	Point M	20230928	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
953	Point M	20230929	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
954	Point M	20230930	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
955	Point M	20230931	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
956	Point M	20230932	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
957	Point M	20230933	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
958	Point M	20230934	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
959	Point M	20230935	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
960	Point M	20230936	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
961	Point M	20230937	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
962	Point M	20230938	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
963	Point M	20230939	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
964	Point M	20230940	C	Very Poor	60" or greater	No DWS (Non-Compliant)	Unknown	Up to or equal to 8.3%
965	Point M	20230941	C	Very Poor	60" or greater	No DWS (Non-Compliant)	Unknown	Up to or equal to 8.3%
966	Point M	20230943	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
967	Point M	20230942	C	Very Poor	60" or greater	No DWS (Non-Compliant)	Unknown	Up to or equal to 8.3%
968	Point M	20230944	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
969	Point M	20230945	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Unknown	Up to or equal to 8.3%
970	Point M	20230946	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
971	Point M	20230947	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
972	Point M	20230948	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
973	Point M	20230949	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
974	Point M	20230950	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
975	Point M	20230951	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
976	Point M	20230952	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
977	Point M	20230953	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
978	Point M	20230954	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
979	Point M	20230955	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Unknown	Up to or equal to 8.3%
980	Point M	20230956	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
981	Point M	20230957	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
982	Point M	20230958	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
983	Point M	20230959	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
984	Point M	20230960	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
985	Point M	20230961	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
986	Point M	20230962	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
987	Point M	20230963	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
988	Point M	20230964	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
989	Point M	20230965	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
990	Point M	20230966	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
991	Point M	20230967	C	Very Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
994	Point M	20230970	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
995	Point M	20230971	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
996	Point M	20230972	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
997	Point M	20230973	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
998	Point M	20230974	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
999	Point M	20230975	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
1000	Point M	20230976	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1001	Point M	20230977	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1002	Point M	20230978	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1003	Point M	20230979	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1004	Point M	20230980	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1005	Point M	20230981	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1006	Point M	20230982	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1007	Point M	20230983	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1010	Point M	20230986	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
1011	Point M	20230987	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1012	Point M	20230988	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1013	Point M	20230990	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1014	Point M	20230991	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1015	Point M	20230992	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1016	Point M	20230993	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1017	Point M	20230989	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
1018	Point M	20230994	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1019	Point M	20230995	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1020	Point M	20230996	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1021	Point M	20230997	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1022	Point M	20230998	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1023	Point M	20230999	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1024	Point M	20231000	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1025	Point M	20231001	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1027	Point M	20231002	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1028	Point M	20231003	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1029	Point M	20231004	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1030	Point M	20231005	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1031	Point M	20231006	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1032	Point M	20231007	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1033	Point M	20231008	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1034	Point M	20231009	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1035	Point M	20231010	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1036	Point M	20231011	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1037	Point M	20231012	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1038	Point M	20231013	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Unknown	Up to or equal to 8.3%
1039	Point M	20231014	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1040	Point M	20231015	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1041	Point M	20231017	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1042	Point M	20231018	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1043	Point M	20231019	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1044	Point M	20231020	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1045	Point M	20231021	B	Poor	36" to > 48"	<Null>	Perpendicular (triangular wings)	Up to or equal to 8.3%
1046	Point M	20231022	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1047	Point M	20231023	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1048	Point M	20231024	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1049	Point M	20231025	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1050	Point M	20231026	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1051	Point M	20231027	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1052	Point M	20230609	C	Very Poor	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1053	Point M	20231028	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1054	Point M	20231029	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1055	Point M	20231030	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1056	Point M	20231031	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1057	Point M	20231032	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1058	Point M	20231033	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	<Null>	Up to or equal to 8.3%
1059	Point M	20231034	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1060	Point M	20231035	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1061	Point M	20231036	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1063	Point M	20231037	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1064	Point M	20231038	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1065	Point M	20231039	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1066	Point M	20231040	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1067	Point M	20231041	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1068	Point M	20231042	A	Fair or Better	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Unknown	Up to or equal to 8.3%
1069	Point M	20231043	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1070	Point M	20231044	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1071	Point M	20231045	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1072	Point M	20231046	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1073	Point M	20231047	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1074	Point M	20231048	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Combination	Up to or equal to 8.3%
1075	Point M	20231049	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1076	Point M	20231050	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1077	Point M	20231051	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1078	Point M	20231052	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1080	Point M	20231053	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1081	Point M	20231054	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1082	Point M	20231055	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1083	Point M	20231056	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
1084	Point M	20231057	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1085	Point M	20231058	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
1086	Point M	20231059	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1087	Point M	20231060	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1088	Point M	20231061	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1089	Point M	20231062	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1090	Point M	20231063	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1091	Point M	20231064	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1092	Point M	20231065	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1093	Point M	20231066	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1094	Point M	20231067	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1095	Point M	20231068	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1096	Point M	20231069	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1097	Point M	20231070	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1098	Point M	20231071	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1099	Point M	20231072	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1100	Point M	20231073	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1101	Point M	20231074	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1102	Point M	20231075	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
1103	Point M	20231076	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1104	Point M	20231077	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1105	Point M	20231078	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1106	Point M	20231079	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1107	Point M	20231080	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1108	Point M	20231081	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1109	Point M	20231082	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1110	Point M	20231083	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1111	Point M	20231084	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1112	Point M	20231085	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1113	Point M	20231086	C	Very Poor	Less than 36"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1114	Point M	20231087	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1115	Point M	20231088	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1116	Point M	20231089	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1117	Point M	20231090	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1118	Point M	20231091	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1119	Point M	20231092	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1120	Point M	20231093	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1121	Point M	20231094	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1122	Point M	20231095	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1123	Point M	20231096	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1124	Point M	20231097	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1125	Point M	20231098	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1126	Point M	20231099	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1127	Point M	20231100	C	Very Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1128	Point M	20231101	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1129	Point M	20231102	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1130	Point M	20231103	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1131	Point M	20231104	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1132	Point M	20231105	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1134	Point M	20231106	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1135	Point M	20231107	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1136	Point M	20231108	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1137	Point M	20231109	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1138	Point M	20231110	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1139	Point M	20231111	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1140	Point M	20231112	C	Very Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1141	Point M	20231113	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1142	Point M	20231114	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1143	Point M	20231115	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1144	Point M	20231116	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1145	Point M	20231117	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1146	Point M	20231118	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
1147	Point M	20231119	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
1149	Point M	20230607	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1150	Point M	20230599	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1151	Point M	20231120	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
1152	Point M	20231121	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1153	Point M	20231122	C	Very Poor	Less than 36"	No DWS (Non-Compliant)	Unknown	More than 8.3%
1156	Point M	20231123	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1157	Point M	20231124	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
1158	Point M	20231125	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1159	Point M	20231126	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1160	Point M	20230439	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1163	Point M	20230398	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1164	Point M	20230456	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1166	Point M	20231127	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Blended Transition	Up to or equal to 8.3%
1167	Point M	20231128	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
1168	Point M	20231129	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1169	Point M	20231130	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1170	Point M	20231131	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1171	Point M	20231132	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1172	Point M	20231133	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1173	Point M	20231134	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1174	Point M	20231135	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1175	Point M	20231136	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1176	Point M	20231137	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1177	Point M	20230442	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1178	Point M	20230282	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1179	Point M	20231138	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1180	Point M	20231139	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1182	Point M	20230854	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1183	Point M	20231016	D	Missing (Needed but does not Exist)	36" to > 48"	No DWS (Non-Compliant)	Blended Transition	<Null>
1184	Point M	20231140	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
1185	Point M	20231144	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1186	Point M	20231141	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
1187	Point M	20231142	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	Blended Transition	<Null>
1189	Point M	20231143	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1190	Point M	20231146	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1191	Point M	20231145	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1192	Point M	20231152	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1193	Point M	20231151	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1194	Point M	20231150	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1195	Point M	20231149	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1196	Point M	20231148	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1197	Point M	20231147	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1198	Point M	20231153	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1199	Point M	20231154	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1200	Point M	20231155	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1201	Point M	20231156	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1202	Point M	20231157	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1203	Point M	20231158	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1204	Point M	20231159	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1205	Point M	20231160	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1206	Point M	20231161	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1207	Point M	20231162	C	Very Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1208	Point M	20231163	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1209	Point M	20231164	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1210	Point M	20231165	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1211	Point M	20231166	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1212	Point M	20231167	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1213	Point M	20231168	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1214	Point M	20231169	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1215	Point M	20231170	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1216	Point M	20231171	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1217	Point M	20231172	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1218	Point M	20231173	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1219	Point M	20231174	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1220	Point M	20231175	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1221	Point M	20231176	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1222	Point M	20231177	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1223	Point M	20231178	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1224	Point M	20231179	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1225	Point M	20231180	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1226	Point M	20231181	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1227	Point M	20231182	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1228	Point M	20231183	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1229	Point M	20231184	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1230	Point M	20231185	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1231	Point M	20231186	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1232	Point M	20231187	B	Poor	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
1233	Point M	20231188	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1234	Point M	20231189	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1235	Point M	20231190	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1236	Point M	20231191	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1237	Point M	20231192	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1238	Point M	20231193	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1239	Point M	20231194	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1240	Point M	20231195	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1241	Point M	20231196	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1242	Point M	20231197	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1243	Point M	20231198	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1244	Point M	20231199	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1245	Point M	20231200	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1246	Point M	20231201	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1247	Point M	20231202	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1248	Point M	20231203	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1249	Point M	20231204	A	Fair or Better	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1250	Point M	20231205	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1251	Point M	20231206	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1252	Point M	20231207	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1253	Point M	20231208	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1254	Point M	20231209	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
1255	Point M	20231210	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1256	Point M	20231211	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1257	Point M	20231212	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1258	Point M	20231213	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1259	Point M	20231214	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1260	Point M	20231215	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1261	Point M	20231216	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1262	Point M	20231217	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1263	Point M	20231218	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1264	Point M	20231219	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1265	Point M	20231220	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1266	Point M	20231221	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1267	Point M	20231222	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1268	Point M	20231223	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1269	Point M	20231224	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1270	Point M	20231225	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1271	Point M	20231226	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1272	Point M	20231227	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1273	Point M	20231228	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1274	Point M	20231229	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1275	Point M	20231230	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1276	Point M	20231231	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1277	Point M	20231232	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1278	Point M	20231233	C	Very Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1279	Point M	20231234	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1280	Point M	20231235	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1281	Point M	20231236	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1282	Point M	20231237	C	Very Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1283	Point M	20231238	B	Poor	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1284	Point M	20231239	C	Very Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1285	Point M	20231240	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1286	Point M	20231241	B	Poor	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1287	Point M	20231242	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1288	Point M	20231243	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1289	Point M	20231244	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1290	Point M	20231245	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1291	Point M	20231246	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1292	Point M	20231247	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1293	Point M	20231248	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1294	Point M	20231249	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1295	Point M	20231250	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1296	Point M	20231251	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1297	Point M	20231252	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1298	Point M	20231253	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1299	Point M	20231254	B	Poor	36" to > 48"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1300	Point M	20231255	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1301	Point M	20231256	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1302	Point M	20231257	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1303	Point M	20231258	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1304	Point M	20231259	A	Fair or Better	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1305	Point M	20231260	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1307	Point M	20231261	B	Poor	60" or greater	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1308	Point M	20231262	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1309	Point M	20231263	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1310	Point M	20231264	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1311	Point M	20230792	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1312	Point M	20231265	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1313	Point M	20231266	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1314	Point M	20231267	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1315	Point M	20231268	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1316	Point M	20231269	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1317	Point M	20231270	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1318	Point M	20231271	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1319	Point M	20231272	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1320	Point M	20230791	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1321	Point M	20231273	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1322	Point M	20230789	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1323	Point M	20231274	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1324	Point M	20231275	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1325	Point M	20231276	C	Very Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1326	Point M	20231277	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1327	Point M	20231278	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1328	Point M	20231279	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1329	Point M	20231280	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1330	Point M	20230788	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1331	Point M	20231281	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1332	Point M	20231282	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1333	Point M	20231283	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1334	Point M	20231284	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1335	Point M	20231285	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1336	Point M	20231286	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1337	Point M	20231287	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1338	Point M	20231288	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1339	Point M	20231289	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1340	Point M	20231290	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1341	Point M	20231291	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	More than 8.3%
1342	Point M	20231292	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1343	Point M	20231293	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1344	Point M	20231294	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1345	Point M	20231295	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1346	Point M	20231296	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1347	Point M	20231297	B	Poor	36" to > 48"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1348	Point M	20231298	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1349	Point M	20231299	C	Very Poor	Less than 36"	Old Standard (Diamond/Exposed Aggregate)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1350	Point M	20231300	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Unknown	More than 8.3%
1351	Point M	20231301	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	Up to or equal to 8.3%
1352	Point M	20231302	B	Poor	48" to >60"	Old Standard (Diamond/Exposed Aggregate)	Parallel-Single Direction	More than 8.3%
1354	Point M	20231303	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
1355	Point M	20231304	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1356	Point M	20231305	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1357	Point M	20231306	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1358	Point M	20231307	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
1359	Point M	20231308	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1360	Point M	20231309	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1361	Point M	20231310	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1362	Point M	20231311	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
1363	Point M	20231312	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
1364	Point M	20231313	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
1365	Point M	20231314	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
1366	Point M	20231315	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1367	Point M	20231316	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1368	Point M	20231317	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1369	Point M	20231325	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1370	Point M	20231318	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1371	Point M	20231319	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1372	Point M	20231320	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	More than 8.3%
1373	Point M	20231321	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1374	Point M	20231322	B	Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1375	Point M	20231323	A	Fair or Better	<Null>	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1376	Point M	20231324	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1377	Point M	20231326	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1378	Point M	20231327	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1379	Point M	20231328	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1380	Point M	20231329	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1381	Point M	20231330	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1382	Point M	20231331	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1383	Point M	20231332	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1384	Point M	20231333	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1385	Point M	20231334	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1386	Point M	20231335	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1387	Point M	20231336	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1388	Point M	20231337	C	Very Poor	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1389	Point M	20231338	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1390	Point M	20231339	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1391	Point M	20231340	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1392	Point M	20231341	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1393	Point M	20231342	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1394	Point M	20231343	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1395	Point M	20231344	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1396	Point M	20231345	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1397	Point M	20231346	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1398	Point M	20231347	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1399	Point M	20231348	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1400	Point M	20231349	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
1401	Point M	20231350	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	More than 8.3%
1402	Point M	20231351	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1403	Point M	20231352	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1404	Point M	20231353	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1406	Point M	20231355	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1407	Point M	20231356	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1408	Point M	20231358	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1409	Point M	20231357	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope
1410	Point M	20231359	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Combination	Up to or equal to 8.3%
1411	Point M	20231360	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1412	Point M	20231361	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1413	Point M	20231362	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1414	Point M	20231363	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1415	Point M	20231364	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1416	Point M	20231365	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1417	Point M	20231366	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%
1420	Point M	20230784	D	Missing (Needed but does not Exist)	<Null>	<Null>	<Null>	<Null>
1421	Point M	20230783	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1422	Point M	20230782	C	Very Poor	36" to > 48"	No DWS (Non-Compliant)	Unknown	More than 8.3%
1424	Point M	20230408	C	Very Poor	48" to >60"	No DWS (Non-Compliant)	Parallel-Single Direction	Up to or equal to 8.3%
1427	Point M	20230790	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1428	Point M	20230409	D	Missing (Needed but does not Exist)	<Null>	No DWS (Non-Compliant)	<Null>	<Null>
1429	Point M	20230275	A	Fair or Better	48" to >60"	Compliant (Truncated Domes with contrasting color)	Parallel-Single Direction	Up to or equal to 8.3%
1430	Point M	20230281	C	Very Poor	Less than 36"	Compliant (Truncated Domes with contrasting color)	Unknown	Up to or equal to 8.3%
1432	Point M	20230135	A	Fair or Better	60" or greater	Compliant (Truncated Domes with contrasting color)	Perpendicular (triangular wings)	Up to or equal to 8.3%

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230382	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.7%. Remove ramp or provide accessible crossing	No	{5E651BFD-8115-46F6-BB0A-5493E9B101D0}
20230381	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes 5%. Landing panel upheaval	No	{0F8E59A2-2206-4DDB-8752-50C0A000A890}
20230380	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. PAR running slope 5.4%.	No	{FC3FECAC-1FBF-4F32-96DC-A9C8BE3FE630}
20230379	Up to or equal to 2%	4 x 4 feet or greater	Remove ramp or provide accessible crossing	No	{79A0592D-28F4-480B-9FEA-04C9F6929F9E}
20230303	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{866579EC-96F4-4FD7-9605-C5B79A75B00C}
20230302	More than 2%	4 x 4 feet or greater	Running slope 8.5%. Landing cross slopes 3%. PAR running slope 7%.	No	{6E36092B-0620-45B9-9FAC-919FD63CDCE3}
20230301	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR cross slope 3%.	No	{04E25838-9CBD-4117-8DA9-71B5E73C12EC}
20230364	More than 2%	4 x 4 feet or greater	Cross slope 2.8% matches roadway grade.	Yes	{CEF9B882-1F52-4CAC-87FF-475256BCF8C2}
20230365	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2%. DWS deterioration.	No	{0BF18710-4CDA-45F0-BDB8-63CF058079D7}
20230366	More than 2%	4 x 4 feet or greater	Cross slope 5.8%. PAR running slope 10%. Landing running slope 4.6% with PAR cross slope 5.6%. DWS deterioration.	No	{06BF2B82-6610-4DDA-BA0A-86836BFB19E6}
20230367	More than 2%	4 x 4 feet or greater	Cross slope 5.7%. Landing slopes 4%. DWS deterioration.	No	{EE6B21CA-4844-4FE8-B64E-52C8DBDBFCC5}
20230363	More than 2%	4 x 4 feet or greater	Landing cross slope 6% matches roadway grade. Mud debris.	Yes	{7DDE9120-269A-4978-BDCA-D396A6B036FF}
20230324	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. PAR running slope 5.8% matches roadway grade.	Yes	{0F71C820-E523-4883-80AA-AA8E1E6F5AA3}
20230325	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. Landing cross slope 6% matches roadway grade.	Yes	{7FAE7A27-FC66-4560-A8C5-6CC86142D9A1}
20230362	More than 2%	4 x 4 feet or greater	Cross slope 3% matched roadway grade.	Yes	{A4CCFE8B-43E0-4738-B3D6-6D211AFC88B9}
20230285	More than 2%	4 x 4 feet or greater	Curb ramp should be removed. Cross slope 3%. Matches roadway grade. PAR cross slope 6%.	No	{E2D6351C-CD14-40C2-BF2B-8537C74AB44A}
20230284	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{A0A81973-1D70-4B42-8295-50FB0B8CF2E4}
20230318	Up to or equal to 2%	4 x 4 feet or greater	Cross slope 2.3%. Matches roadway grade	Yes	{08481CDA-5D71-4787-B86E-492E68BC6CD7}
20230319	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade	Yes	{BD708614-077C-4B4D-94C8-7E66141C61A7}
20230320	More than 2%	4 x 4 feet or greater	Curb ramp should be removed. Running slope 8.8%. Cross slope 4%. PAR cross slope 4%. Corner panel upheaval	No	{48A8128A-265F-42B4-9689-F8CCBBCC24E1}
20230321	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR cross slope 4%. PAR running slope 6%.	No	{C4D8B177-F6CB-4CE5-884E-5614AAA31C4D}
20230322	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{41851187-41E0-4CB6-B694-4087273406D6}
20230323	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D0CE4BBF-F770-431F-8E98-A0E74A4F4B4B}
20230422	More than 2%	4 x 4 feet or greater	Cross slope 3.4%. Matches roadway grade	Yes	{D8EFACA7-A1DE-48BF-BFD0-9F9E63AD67B5}
20230423	More than 2%	4 x 4 feet or greater	Cross slope 7.3%. Matches roadway grade. PAR cross slope 8%. PAR running slope 9%.	No	{A09AB27B-493F-4ED9-8429-FEAE52FFA267}
20230424	More than 2%	4 x 4 feet or greater	Cross slope 9%. Matches roadway grade. Landing cross slope 9%. PAR running slope 13%.	No	{8616B475-EA81-4E97-AAF1-08FB1B6EABDF}
20230425	More than 2%	4 x 4 feet or greater	Cross slope 8.3%. Matches roadway grade. PAR cross slope 8.3%. PAR running slope 13%.	No	{142AC49C-18F8-4FD3-843B-ACA024FA8F0F}
20230136	Up to or equal to 2%	4 x 4 feet or greater	Running slope 8.7%.	No	{B76217BC-F996-4FD9-8B0C-BD20DE32E238}
20230134	Up to or equal to 2%	4 x 4 feet or greater	Utility access within Landing	No	{6D445CA6-42A3-4D0C-A092-2D3F84C0437E}
20230133	More than 2%	4 x 4 feet or greater	Cross slope 3%. PAR cross slope 3%.	No	{4B9865FD-0163-45A8-9C73-6351962B72FC}
20230132	More than 2%	4 x 4 feet or greater	Cross slope 2.3%. PAR cross slope 4%.	No	{8B19F297-357B-4895-8AB5-1FD3B403F3AE}
20230138	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{1175D71E-6A26-488F-AC38-0A00A82C8AF4}
20230140	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{689D9DB1-1A21-4A6E-947B-CADC0FD5E2F2}
20230142	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{FB0AAC58-B6D3-4E42-8381-A5130B164296}
20230144	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{F473506A-1E48-4B34-B7CF-E3128EA302B8}
20230269	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. APS pole slope 9.3%.	Yes	{9C48007D-191B-4B90-8859-CF252A6EAB9C}
20230360	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade	Yes	{D5B18752-DEDE-4D8F-BAA0-DD01EC613A2F}
20230317	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{08F28D24-538E-4F93-A580-F70199DCF554}
20230274	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9A5B0C22-E811-455E-AAB9-96394A77B53D}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230270	More than 2%	4 x 4 feet or greater	Cross slope 2.3%. Matches roadway grade	Yes	{DAB155DB-F0F1-466E-8F02-302D6B9F3E99}
20230271	Up to or equal to 2%	4 x 4 feet or greater	APS pole slope 6%.	Yes	{74F51992-6DB3-4623-BF81-7C29D062636B}
20230272	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{616ADDD9-F428-4AD6-B2C9-04FF461A5F7E}
20230273	Up to or equal to 2%	4 x 4 feet or greater	APS pole slope 5%.	Yes	{8121069C-9D6A-48BB-95EE-BF5575A9BEDB}
20230559	More than 2%	4 x 4 feet or greater	Cross slope 2.8%. Matches roadway grade. PAR running slope 3.3%.	Yes	{4F35C8DD-97E8-43BB-A403-623A36A9EC3B}
20230558	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D2BF69C8-225B-4D58-9506-3D5FEB2D3018}
20230557	More than 2%	4 x 4 feet or greater	Cross slope 9%. Matches roadway grade. PAR running slope 8.4%.	Yes	{AA460B28-4395-4633-B767-A537916B684C}
20230556	More than 2%	4 x 4 feet or greater	Cross slope 9%. Matches roadway grade. PAR cross slope 9%	No	{A5EF47F7-57FD-4EF2-B13D-B982083698D5}
20230560	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 4%.	Yes	{49B99CC1-4658-4BD2-9DEF-1D6B89D68E32}
20230561	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 8%.	Yes	{CFA4C983-419B-4203-A9E8-69A6C8B31834}
20230554	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EE5181D8-B277-4A27-8E28-684C494956A1}
20230555	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 6%. PAR cross slope 3%.	No	{AD1721C2-7A78-4121-B0DF-3210C7D21917}
20230575	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.5%	No	{9074A139-28D9-4310-A62B-E2E80056A7E4}
20230574	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation at back of landing.	Yes	{DFD3C495-DDB9-4195-980C-E5A547526081}
20230573	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes 2.5%	No	{27279599-37AE-46C8-A929-48DA0A91D8A9}
20230572	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. Landing slopes 2.3%.	No	{8BB215C0-6406-4DE0-9546-BEB8E2253F9E}
20230568	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B873F49C-6621-4C51-ADC1-FD200012D4C3}
20230569	More than 2%	4 x 4 feet or greater	Cross slope 2.7%. Landing cross slope 2.7%.	No	{3CB1DF88-E012-4E7D-AB37-9C22BA560D54}
20230570	More than 2%	4 x 4 feet or greater	Cross slope 4.5%. PAR running slope 4.5%. Pedestrian pushbutton pole within landing	No	{FAF1D898-1634-4074-B011-2A4EAC7A0E68}
20230571	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes 2.5%	No	{5D7FE0CE-64C7-41B1-8015-39C530D1219B}
20230001	More than 2%	Less than 4 x 4 feet	No landing. Cross slope 13%. Ramp services non-ADA parking.	No	{A3146B5E-2D96-425B-88A6-46A21411B312}
20230002	Up to or equal to 2%	Less than 4 x 4 feet	No landing. Side flare 12%.	No	{7D69D5FD-A1C1-4C2F-AD01-F51854BA4369}
20230003	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9F605B68-D7F3-4F8A-B3DA-A8BFB9490634}
20230004	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{F3A269AE-430A-4B39-A150-8610D1EBD652}
20230005	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{036ECE5E-A2F0-4A0D-8A10-DFF7F3DC4225}
20230006	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{07706A2C-CBB8-47F3-9222-5FA69A2556DB}
20230007	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A92021C6-871C-4372-848D-8E57434C73AF}
20230008	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9D28145E-2EAA-4CCE-A5FD-AE59E80F4515}
20230153	Up to or equal to 2%	4 x 4 feet or greater	Adjacent business product blocking PAR	Yes	{78393F0F-5E9E-47A8-B05C-1466370812E6}
20230009	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{24D94B6A-9336-4D25-B254-F2F954A55F83}
20230010	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{A0F47367-0B82-4BF0-B3C7-F600DCEA09C3}
20230011	Up to or equal to 2%	Less than 4 x 4 feet	Landing area 42" wide PAR	No	{0AC3DC93-41BF-479B-AD49-E876E322545E}
20230012	Up to or equal to 2%	4 x 4 feet or greater	No DWS for transition to roadway	No	{ACC6F90E-A0A7-40E3-A9FE-982AB3379270}
20230432	<Null>	<Null>	Provide blended transition to shoulder parking.	No	{9BFB453C-2B49-4860-9904-E38FCCDE00C6}
20230013	Up to or equal to 2%	Less than 4 x 4 feet	No landing. Curb lip.	No	{01AA6C3B-0EBF-4FD4-8FD5-8A725CF969E2}
20230014	Up to or equal to 2%	Less than 4 x 4 feet	Overgrown vegetation.	No	{0D677446-A612-44D5-86C2-3939398BE645}
20230015	Up to or equal to 2%	4 x 4 feet or greater	Running slope 12%	No	{C7172BDE-E720-437F-97F6-95BA14E4F67A}
20230016	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%	No	{94F149B5-E12D-40A9-9D7A-C7D2D1723C32}
20230017	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9.3%	No	{B076BBAB-DC1F-46C2-95E1-FC7E6F92EB94}
20230018	Up to or equal to 2%	4 x 4 feet or greater	Running slope 8.7%	No	{97F56CB1-58E3-4F8A-BA50-7F2BC8EC31E7}
20230019	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{43D0E465-412B-45C1-B965-3650848B77E9}
20230020	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{1A06CF5B-42D5-403F-9083-7EE166661E33}
20230021	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{0089E51C-A554-4869-ACA0-7461477E0025}
20230022	Up to or equal to 2%	4 x 4 feet or greater	Ramp has incline slope.	Yes	{DBFDA127-5F38-46DF-B811-5EBF5142581B}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230023	Up to or equal to 2%	4 x 4 feet or greater	Ramp has incline slope.	Yes	{77252CB8-E9AE-4828-8FE6-43D56C89561C}
20230024	Up to or equal to 2%	4 x 4 feet or greater	Ramp has incline slope.	Yes	{63AE94E4-B8B7-4CFF-A219-B3198705C354}
20230025	Up to or equal to 2%	4 x 4 feet or greater	Ramp has incline slope.	Yes	{57843258-175F-435B-9F44-3776E702A935}
20230026	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DB956917-A442-4AD1-A1A0-8FC3248821A2}
20230027	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AAAFD08C-D952-4E48-9FE8-5FBBCEE7B83}
20230029	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D26D8B4B-5EB9-4961-8241-BB7BC14D5C63}
20230030	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D711C4DF-1FD1-4D20-9B65-3B70CF36814B}
20230031	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{62B8A994-2116-4C91-B08A-E0B0AD135509}
20230032	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B105CB05-BC8F-4C1F-BAFD-854DA3A1857E}
20230034	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A05A8FFC-00F8-4C52-B6C5-0A544FC6A678}
20230035	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{96ED40D8-5C42-4BF1-A152-6582B508500D}
20230158	Up to or equal to 2%	4 x 4 feet or greater	Utility access within landing	Yes	{FF838AF4-FAA1-410A-B64B-4BD69AD82792}
20230036	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C2C16530-1F2A-4068-A0AD-A048803785B1}
20230037	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E5F05E1A-CDAC-4C44-9433-FEA6E69760C9}
20230197	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{2A1087C5-D739-4093-ABEA-D63018F6E7F8}
20230038	Up to or equal to 2%	4 x 4 feet or greater	Recycling cans blocking ramp	Yes	{E2EE3171-33C5-4B77-87F1-81647E39B2A2}
20230105	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{FB66657C-56D9-4F79-8F90-9DDC34C524BE}
20230039	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{8BEC69AB-C501-4E65-B611-AB42B0270D21}
20230040	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AA110815-0782-4D2A-96C3-0CFC47832CFD}
20230041	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AC64927D-68A8-4BCC-A24B-E24DD4F3B1EF}
20230043	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EEB80825-D71C-4DC7-BF49-250D97A8D630}
20230042	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation.	Yes	{A61DD1AD-5134-4B53-8CF3-D52605F12FF6}
20230044	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{94791AAB-30B5-4A0F-A3C4-357A873FA691}
20230045	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EF4B6588-3CA9-4A3D-B234-77DBE78DD903}
20230046	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{5D9417C7-00C6-451F-BD88-5ED013F59A2D}
20230047	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{FB932433-97A9-4B3F-A265-E40F94D606C5}
20230048	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DF2970B8-CD8C-4A6F-B2AB-618BE6B2F8F1}
20230049	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{52220C58-B2D3-4BC9-9FB3-3893781D77A4}
20230050	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{94706405-C3D5-4EE4-B83C-BFCD566A9EC6}
20230051	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{71815A8A-5E40-4A84-A84D-3D1E12EB381E}
20230052	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{73FC6B51-315E-4BC1-ABD4-E572AF5D8C01}
20230053	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{1829CF42-6FC5-46F0-938B-28E4F918633A}
20230054	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{29234918-0378-4ED7-B2FE-0789B4C505C6}
20230055	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{0AF02F75-E145-4D3F-B241-10F99A4FB409}
20230056	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{41CC1616-47C7-414B-842A-6C4E723F02B2}
20230057	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C5BD1327-9605-4B71-90D7-B936E9DD9562}
20230058	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9AA9417D-5271-4D34-99F8-5ABAD704498A}
20230059	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{5E4FFD60-7255-452A-A368-0975B4D6163B}
20230060	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{FFBAC6FC-DF9D-460C-91A0-784523821F7B}
20230061	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{63DC56A7-3A9F-4F8B-BAE7-59BDD92C1484}
20230062	Up to or equal to 2%	4 x 4 feet or greater	Gravel debris	Yes	{44509C3E-D0C9-49CC-8C37-039F8E8EB24F}
20230063	Up to or equal to 2%	4 x 4 feet or greater	Gravel debris	Yes	{E5503A52-9DF4-46C2-8BFA-091602E22C81}
20230064	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{12D12483-D3BD-494F-85D4-01697D19AE06}
20230065	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{0B3BE55B-65A8-4E72-9327-5E37A06F2789}
20230066	Up to or equal to 2%	4 x 4 feet or greater	Construction cones within landing.	Yes	{AD7EE5B1-4A5E-4BAB-85A0-7E3B21466C2B}
20230106	Up to or equal to 2%	4 x 4 feet or greater	Driveway interface	Yes	{C6363B3B-C919-470F-B740-0D4F2AB93B4A}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230433	<Null>	<Null>	<Null>	No	{BF93BE51-7598-46B7-89F3-B727424CCA93}
20230067	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{211CB599-5125-4EB0-959E-F1AB3324D2D1}
20230068	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing. Overgrown vegetation.	Yes	{98474A56-BAD4-4622-8FF8-3A99593F040E}
20230069	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{8FACE03E-96FD-48B6-BFE0-BB0336054F09}
20230107	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E7FFDF45-163F-4DF2-A259-91F4C8D5B538}
20230070	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{8D90F91A-A391-4069-AE88-34D402EA53BA}
20230108	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A03F3AB8-255C-4BE2-AFBE-B9EC32FC4683}
20230071	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{494F4A2A-F104-47B3-A603-79FAEB075917}
20230072	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{F543160B-166E-4BC3-9EF1-EE725BDFD6A8}
20230073	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{50010016-D59D-4A37-A66C-441798B88B57}
20230434	<Null>	<Null>	<Null>	No	{8CBB2C47-B3D9-4A55-A8C5-0C6F52BCA646}
20230109	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DA863907-E103-4CD4-8FA9-E83413AF2295}
20230074	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{4EF6C74E-AA04-4A61-B1E8-2F6E125BEEFE}
20230435	<Null>	<Null>	<Null>	No	{36D478EB-CCC7-479E-98A7-4D4950E3E3FE}
20230075	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{040CEB22-0DC2-4088-840E-BEF4D8698E59}
20230076	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DDD45697-31E9-43E2-B887-5F3DFEF24757}
20230436	<Null>	<Null>	<Null>	No	{F2731E31-7277-4952-A466-77FB5B892F5D}
20230077	Up to or equal to 2%	4 x 4 feet or greater	DWS should only serve North-South crossing.	No	{6F342C3F-488F-4D2D-A170-38933704D28A}
20230078	Up to or equal to 2%	4 x 4 feet or greater	DWS should only serve North-South crossing	No	{8409D266-1CE3-410A-989E-DEC242496D37}
20230079	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C8BCC968-497B-419F-A411-A4F2E8F0DB7D}
20230110	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{339543AE-0C35-4F26-9CE3-FD96CF8469E3}
20230080	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6871D2FB-3826-4FAA-848E-CC23D1FBCE2F}
20230111	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C01A90B7-4E77-4362-9D31-AB5BF17793A6}
20230081	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9F9AD01E-A0C0-48C4-82C7-4DEC59C36B4A}
20230082	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EE086A77-CEA8-4FA6-955C-D6C376973DB7}
20230083	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{7AC3A70A-4A31-42D4-8AD9-20386924A8DB}
20230084	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{25114DBA-D301-4591-803C-9E744993E38C}
20230112	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{75959843-E8CB-4D26-B0BE-0408FBE3A6B1}
20230085	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing. Discoloration.	Yes	{FC37B5C9-C147-442D-B750-A1126238A8E7}
20230113	Up to or equal to 2%	4 x 4 feet or greater	Debris	No	{1CEBE652-77A1-42E8-81F0-2DF860AE5823}
20230086	Up to or equal to 2%	4 x 4 feet or greater	Landing slope 2.5%	No	{A1A9A4C0-ECE2-42CA-B97F-1B9E5C68893D}
20230437	<Null>	<Null>	<Null>	No	{EF4CBC30-7349-4B31-9C7C-8025D430F7B5}
20230438	<Null>	<Null>	<Null>	No	{0F6B850F-FC97-4561-B1C5-74DAA2DD023C}
20230440	<Null>	<Null>	<Null>	No	{64267B0F-02CF-4885-9059-14C89DEADD65}
20230087	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{7C88D4C7-41F5-49BE-857C-ED056044C501}
20230088	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{5BF27871-0F52-4B91-841D-6683114CC3FD}
20230114	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%	No	{3B5C04F9-E78B-45BD-BA82-CDC17A2F4C3D}
20230089	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{49357912-082D-45C2-9D2A-4D41E7C79EC4}
20230090	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{C6B53772-1F0E-4BFE-9E94-7C79933C3EFC}
20230091	Up to or equal to 2%	Less than 4 x 4 feet	No landing	No	{AF5C70DE-9E83-4B61-AD28-40489D5B7B32}
20230115	More than 2%	Less than 4 x 4 feet	Landing slope 9%. Running slope 4%.	No	{E2923559-3508-4FBE-9138-7E90EA017834}
20230092	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{7ED18A91-1168-48FF-8FC4-578C282EC1FC}
20230093	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{F59123F9-FF3A-4CD8-BA2B-23CDC4F42B46}
20230094	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{35638761-EF11-46C2-8C6C-E99A2D00D0D5}
20230095	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{227FA4DF-01B0-4F09-A04A-6584A1FE5CD7}
20230116	Up to or equal to 2%	4 x 4 feet or greater	Running slope 8.5%	No	{2900F7C9-23A6-4A5F-9418-8BD36B96E6DC}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230096	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{41414703-238A-4924-9158-FFA3381649C8}
20230097	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%	No	{5530D2BE-1360-4406-A88A-5B52C8E87D63}
20230441	<Null>	<Null>	NO DWS transition to roadway	No	{B5028920-0F3A-49AE-967B-8D42B4DF73F8}
20230098	Up to or equal to 2%	4 x 4 feet or greater	Debris	No	{DE98706D-4573-448C-9802-A11AA918D8E7}
20230099	Up to or equal to 2%	4 x 4 feet or greater	Debris	No	{121E347D-96A7-4D1B-AA8E-916203F821DB}
20230117	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C0E01461-D9F2-415A-883A-6A46E24EE621}
20230118	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{8AB91C93-DB1A-41FC-95EB-DF35E9164A3F}
20230100	Up to or equal to 2%	4 x 4 feet or greater	Cracks within landing	No	{B9E5BE0E-F2C2-4C62-A085-9CCBE20AB013}
20230119	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{9828D93F-32F0-4674-8157-68EE92D3F1CE}
20230101	Up to or equal to 2%	Less than 4 x 4 feet	Running slope 10%	No	{0F8E7793-0B70-4398-B65A-9C12AD15E81F}
20230102	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%	No	{67078C96-3F2E-432F-90F7-7055E6FE3C94}
20230103	Up to or equal to 2%	4 x 4 feet or greater	Curb at angle to approach. Running slope 9.3%.	No	{58C1C61D-CA08-4FB4-8E96-EE60D1DF9ED6}
20230104	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{1B48A7F5-45B1-440B-A7A4-FCF773F3C918}
20230150	Up to or equal to 2%	4 x 4 feet or greater	Landing slope, 2.25%.	No	{E96F20D7-9E66-4637-8503-C820885114F5}
20230151	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{9E4FF289-36F0-422B-89F6-9BBFF67BF2C1}
20230152	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{4A857BB0-AC42-43F4-A206-B4E2BE553BE2}
20230154	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{C3E4A780-642D-4D7D-AC24-83546EAB18C8}
20230155	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6DFE0F37-3DCD-4C2F-BB08-54CF4927B81B}
20230149	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{5C3D80E2-8628-4C59-B97D-4E254614DE5A}
20230156	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gaps	Yes	{81B1F8A5-EB69-43A2-A81E-7629BBB9E3A4}
20230157	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gaps	Yes	{FBAB0395-EE67-4646-9B12-E3E20A6D19CF}
20230159	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{D65EFD63-A44C-44F9-B01B-D26FAF18D00E}
20230160	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{D88FB8AE-5F8F-4BDF-8EAB-70E5A509E333}
20230161	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{89C355BE-EAB4-4F52-A44A-EC1FD6AAD2A9}
20230162	Up to or equal to 2%	4 x 4 feet or greater	Right side cross slope 3%	No	{495D1402-CEA9-424C-A295-F68B0FC51720}
20230163	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{1149E799-3519-496D-B212-20B702832923}
20230164	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap and left corner upheaval.	Yes	{36B50382-B64B-4D17-A2D5-90217806608E}
20230165	Up to or equal to 2%	4 x 4 feet or greater	DWS to railroad 6 feet. Monitor sidewalk gap	Yes	{BCE42B14-01BC-471A-BB4C-4545F814E550}
20230166	Up to or equal to 2%	4 x 4 feet or greater	No DWS at railroad crossing. Cracked landing	No	{75EDB371-BA97-43D0-AC6D-552B5696DA14}
20230167	Up to or equal to 2%	4 x 4 feet or greater	No DWS at railroad crossing. PAR slopes and dips and humps	No	{924EBEB0-D952-4BD3-BDFB-65CC0BC3EB77}
20230168	Up to or equal to 2%	4 x 4 feet or greater	DWS to railroad 6 feet	Yes	{E7F90A98-865F-4C57-A53D-79CAD76CD2E4}
20230169	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{E96813AB-9787-4939-AB65-0DD0A9AD747F}
20230170	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation. Landing slope 3%	No	{6E675DD9-A0E3-4A18-9786-0D7CFEC50497}
20230171	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation	No	{A171BEBB-B394-4F6A-A8F8-3F5C9D874C06}
20230172	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{530D5D59-884E-4EBF-AF01-60F2B0574B35}
20230173	Up to or equal to 2%	4 x 4 feet or greater	Two DWS panels	Yes	{2C308126-C4D1-4E09-8D0C-D863E7AAA73B}
20230174	Up to or equal to 2%	4 x 4 feet or greater	DWS deterioration	No	{AA0599B2-E44D-4944-95FB-570B7AAC4574}
20230175	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%	No	{9E003174-A55B-4DC9-BB69-080D02122547}
20230176	Up to or equal to 2%	4 x 4 feet or greater	DWS has lip	No	{E55AA25E-D64F-4446-8106-AC6D9C505606}
20230177	Up to or equal to 2%	4 x 4 feet or greater	Running slope 8.7%. Landing slope 2.8%	No	{731B6122-C58C-455B-842B-2334A0F3345E}
20230178	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{6F535905-6D8A-426A-9D97-FC592B62E25C}
20230179	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{6A0260D4-B382-4694-AB1C-0508BCEB9FFE}
20230180	Up to or equal to 2%	4 x 4 feet or greater	Two DWS panels	Yes	{847326DC-68EA-466A-911C-00A56819A53E}
20230181	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{008EE6B8-5392-4B95-B2B6-56291A5F6227}
20230182	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D88A1AA6-A8CE-41E7-844D-9803E684443C}
20230183	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D96F6918-1CD6-4D85-8913-C2349CA54654}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230184	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EDB4A182-6D5C-4833-8C6D-910B8808E23D}
20230185	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{BB334CDF-51BD-4782-9576-A6EC233DF904}
20230186	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{13258A43-43CB-4B19-9F4C-0F3117B66110}
20230187	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{953F33D9-BA6A-439F-88CD-068099E295DB}
20230188	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{2B208A21-176C-455C-A52C-43C8FDC6360D}
20230189	<Null>	<Null>	No DWS at railroad crossing	No	{6A5C7075-CE96-4BC3-A875-DAC189B1B94F}
20230190	<Null>	<Null>	No DWS at railroad crossing	No	{7177AEE1-91D4-40B1-823D-D8FCD7F7F765}
20230120	Up to or equal to 2%	4 x 4 feet or greater	Monitor sidewalk gap	Yes	{6E464129-4EE8-4A01-96FF-336EC4C42F64}
20230451	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A706B110-D41D-467A-8E31-A56D6A7D48A7}
20230191	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C3BCD287-4B4C-4954-96DC-775068AD85BE}
20230192	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AD3156EA-2B10-407C-AE5C-A68F2F7656D4}
20230193	<Null>	<Null>	Crossings feed into parking lot. Need to define PAR with DWS.	No	{82C25429-B973-4D1F-8D23-90199DC1826A}
20230194	<Null>	<Null>	No DWS at railroad crossing. Asphalt lip.	No	{F925C230-9B30-4713-AF9F-C8DB09FB46F9}
20230195	<Null>	<Null>	No DWS at railroad crossing	No	{115E424C-322F-4CDD-9DAC-B5BB372BDE93}
20230196	<Null>	<Null>	No DWS at railroad crossing	No	{580544CE-C59A-4221-8B8C-321D08F69172}
20230198	<Null>	<Null>	NO DWS at railroad crossing. Aslphalt lip.	No	{7F861F84-50B7-4110-BEF8-1FA561C5FA67}
20230199	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6BC0FF9B-2A3F-4EE6-9935-711777F71448}
20230200	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{2A5A78F7-3973-4627-88A3-655192EDDD22}
20230201	Up to or equal to 2%	4 x 4 feet or greater	Consider adding PAR barricade for adjacent ditch	Yes	{EECEC9EA-58FE-498F-BAA6-80CCE808A402}
20230202	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{06FE73EA-CE58-4077-98A8-7F22BF069421}
20230203	<Null>	<Null>	No DWS at railroad crossing	No	{2637D1D9-2186-4AA5-AF98-846C76BD2A68}
20230204	<Null>	<Null>	No DWS at railroad crossing. Asphalt lip.	No	{ECE59744-B387-4F9D-AFD9-B7432D628359}
20230205	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C37F768D-9D45-4F05-80E8-E64930E04935}
20230206	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{829FCCC4-00DF-4975-A9FD-60E83FCBFE3D}
20230207	Up to or equal to 2%	4 x 4 feet or greater	DWS leads to ditch in PAR	Yes	{72515659-E72D-47B0-AF4A-CE3D44D149D0}
20230208	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{FB2EAED6-FD00-418C-86AC-460F736B40B4}
20230209	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DEE788EB-DBB7-4A38-9E39-00C4189E1529}
20230210	Up to or equal to 2%	Less than 4 x 4 feet	No landing. Running slope 11%. Gravel debris	No	{CA120ED5-1533-4F75-A0E5-0B7F26EF3EC5}
20230211	More than 2%	Less than 4 x 4 feet	No landing. Running slope 8.5%. Cross slope 2.5%.	No	{600C8804-6EF8-4EDE-83F4-BF6B8DC3BDF4}
20230212	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B1B7A6AF-B5B1-49A1-B3C2-45C4A6EAAF69}
20230213	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D575B70A-93FF-4040-ABCC-8E64185294D8}
20230214	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EC42ACBA-83DF-4477-92E7-550B7758A08E}
20230215	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{3F0CF6A3-7492-4391-A76C-B9E2197389BF}
20230216	<Null>	<Null>	No DWS transition to roadway	No	{2173A888-28E2-4A54-A80E-36480DAA8401}
20230217	<Null>	4 x 4 feet or greater	No DWS transition to shoulder	No	{158DB8F7-76A2-4BC3-80FA-28A713C346F3}
20230218	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DC74FB55-DE74-488E-B0F1-93A893A7B401}
20230219	<Null>	4 x 4 feet or greater	No DWS transition to roadway	No	{7FF4564D-3221-4DB1-8750-78FB8595B754}
20230220	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D4571561-8E4E-4D0C-80B5-2C732880C360}
20230221	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D3A0C949-08F0-47BA-907D-04637A281DE0}
20230222	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E8DD8C27-543F-4107-894F-0945E46588F8}
20230223	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B8C1C0BA-7FA4-4D9A-95A5-476A3A02FBE8}
20230224	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{155F916D-B032-4794-B095-97512A7A01CF}
20230225	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{284F3927-9EFD-49F4-92FD-DF282E21E1C2}
20230226	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{646A6438-8598-4FFF-91C2-2807736E1C9B}
20230227	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AF06C83E-6772-4EE9-BB10-D78B1A06AC18}
20230228	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D21084CB-C53F-4B3A-A59A-B7D38815E941}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230229	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C4FBEE7A-BB63-4654-A5BE-F7262B42895B}
20230230	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C4A7045E-FF4A-404D-9A12-CC7D40E4AE88}
20230444	<Null>	<Null>	No receiving ramp at intersection	No	{6A90A135-D880-4D0E-BD70-9BABBCF67DD7}
20230231	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6D3F0445-E960-4231-92EB-A6AA578AAC76}
20230232	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B12767AC-5C49-47F4-BB08-F8E919B5F13E}
20230445	<Null>	<Null>	No receiving ramp at intersection	No	{3715AC94-3979-4128-85B9-F9103B3BB2BF}
20230121	Up to or equal to 2%	4 x 4 feet or greater	Debris	Yes	{679186E9-A2D1-4151-BB36-F8C170E647D2}
20230122	Up to or equal to 2%	Less than 4 x 4 feet	No DWS at shared use path crossing	No	{08116E13-6182-4D29-A972-95ABD0189F1A}
20230123	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{0E044AB2-585B-46FC-8A09-9207FAD86700}
20230124	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing. Minor curb lip.	No	{148117D2-F4A1-4405-891A-8AE8D87834E0}
20230125	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{EEF052B3-0A76-413C-BFEF-0CFA47ED537C}
20230126	Up to or equal to 2%	4 x 4 feet or greater	DWS within Landing	Yes	{C42047C5-5211-42AE-844C-A09BE3745329}
20230447	<Null>	<Null>	No DWS transition to roadway	No	{06C4A31C-087E-4FC1-8999-DCA82D11075B}
20230127	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E2B68442-DAB7-4111-AB46-402843893746}
20230448	<Null>	<Null>	No DWS transition to roadway	No	{489126E0-7EC8-43FB-A78C-EBD2F3311D8D}
20230128	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D913E383-5C44-4668-92DC-EC7B9E6F4BF9}
20230129	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{3A25E7AD-9ABC-4031-8D88-390489BDB3B5}
20230130	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{4E580E79-5205-410A-B4D1-2B0F0AC68C3C}
20230233	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{4DB389EA-2F09-4903-A632-02E7CE310906}
20230234	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{B9750816-6B19-45B0-B9F2-2C37BD5535DD}
20230235	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing. Running slope 9%	No	{085BFD97-9A97-4E05-BEE6-F10878EAED93}
20230236	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{B95F32B7-8388-44D3-9EC8-7C9785C02D2B}
20230237	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{5AAAD078-8C23-497A-A9AA-BFDF8BDF09E2}
20230449	<Null>	<Null>	No DWS transition to roadway	No	{A4BC217C-DCC1-47DD-A795-2F33747E24A4}
20230450	<Null>	<Null>	No DWS transition to roadway	No	{1578668B-1A12-4788-A147-5AE196F203A5}
20230238	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{343E5A32-D737-4201-8F0A-C19953BBA710}
20230239	Up to or equal to 2%	4 x 4 feet or greater	PAR to asphalt transition could be improved	Yes	{B9B5ADCA-7A56-4CA8-9ACF-23F20A465C10}
20230240	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{86E63F05-C5ED-4F34-A008-BFD34EF347CD}
20230241	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. Minor curb lip.	No	{7424B652-6C93-440E-AA73-81E3D362161D}
20230242	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{8AEDEEDA-6492-4887-9A73-8B4977ECE704}
20230243	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{3B0C11DF-84C1-4834-8BC5-24582696CDED}
20230244	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation	No	{259B575B-9679-42C1-97F7-59A14F203066}
20230245	Up to or equal to 2%	4 x 4 feet or greater	Running slope 14%. Overgrown vegetation.	No	{1A0DE680-1BC9-4849-9947-541C6D584B80}
20230246	Up to or equal to 2%	4 x 4 feet or greater	Running slope 14%.	No	{964F54EC-6C49-4979-85C6-7799B1152B32}
20230247	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10.5%.	No	{D1D17398-6825-4A3E-9CA1-1C7786891C92}
20230248	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{05D620D8-AE05-4A8F-B059-06BA0B6567DA}
20230249	Up to or equal to 2%	4 x 4 feet or greater	Flare slope 10%	No	{2A0D5CDC-04B1-47C4-9B70-35CE5B3F12AE}
20230250	Up to or equal to 2%	4 x 4 feet or greater	Running slope 8.5%.	No	{5D67D497-FF39-42F9-B7DA-F8E5011D04F1}
20230251	Up to or equal to 2%	4 x 4 feet or greater	Running slope 14%	No	{442CAC4D-B1DC-4139-844B-4FCD30D64588}
20230252	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{665126D4-8A5E-4E29-8A96-6858F3192450}
20230253	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DB3DEBB5-C099-4661-A237-7996693E787B}
20230254	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9B4D3D1A-4884-4B00-9139-80F3DA5116F3}
20230255	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{2D1A99E0-14AB-4EBB-B132-1EA377B0954B}
20230326	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B6F4F63A-537C-4F72-97F8-E46A1077AFAD}
20230327	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{CE21965D-B4B2-4404-AD86-57E28A6FBBFF}
20230328	Up to or equal to 2%	4 x 4 feet or greater	DWS deterioration	Yes	{11186A39-B3F2-4FF0-9758-746CB6C5F3C7}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230329	Up to or equal to 2%	4 x 4 feet or greater	DWS deterioration	No	{C1A05C10-5F6B-4317-8DD3-C81F6DCF3915}
20230330	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EA0FB17F-F688-496B-B4A6-C196D9F0E8C9}
20230331	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EADFBB94-4AE8-430C-8925-2F73B156F66D}
20230131	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{2964455A-9488-4840-90BD-814049E98186}
20230332	Up to or equal to 2%	4 x 4 feet or greater	Running slope 12%	No	{B3DAE20B-7B03-4AC0-81C1-23CDB4445AD0}
20230333	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9A9C18E5-AB3A-4F20-AA9B-962A26810E58}
20230334	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A76E0C34-4D5A-4E57-A0B9-EA50C220F072}
20230455	<Null>	<Null>	No receiving at intersection	No	{80D9FC77-784F-4CAC-9B0C-06660D891D18}
20230335	Up to or equal to 2%	4 x 4 feet or greater	Running slope since 8.5%	No	{A7408873-9C97-43E3-9A9E-503C75463C8F}
20230336	More than 2%	Less than 4 x 4 feet	32 inch ramp. No Landing. Running slope 9.5%.	No	{B3C6DA90-4B8A-40DA-9937-F6F46DC4480C}
20230148	Up to or equal to 2%	4 x 4 feet or greater	Running slope 11%	No	{A3C3D809-D73A-4B52-A0E9-27BC96B24E75}
20230337	<Null>	<Null>	<Null>	No	{7D21F6A4-FC4A-4A7F-8D18-0187A9CFFECD}
20230338	More than 2%	4 x 4 feet or greater	Cross slope 2.8%. Minor curb lip.	No	{E268AF1F-1534-4445-B525-E33571FAEB3F}
20230339	Up to or equal to 2%	Less than 4 x 4 feet	Running slope 18%	No	{B0496DDB-A5A3-4EC4-A246-045CF3E5B042}
20230340	<Null>	<Null>	Utility pole within 48 inch PAR	No	{91521AD6-844A-4086-B671-2D55DAD6FB45}
20230341	<Null>	<Null>	<Null>	No	{CA6D0E1F-D412-42B6-924A-C597D77BEDA5}
20230342	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{81F48A88-27AD-4B66-9160-4DA1D4F784EE}
20230343	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A4F52DCE-85F7-48C7-B1D1-4C42568CA349}
20230344	<Null>	<Null>	No DWS at railroad crossing	No	{9497B797-026A-4DF2-98D2-A788B9C356F0}
20230345	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{FB52519D-25C1-4CF3-801F-2BB7B563C170}
20230453	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{BFB9DE79-EB6F-476A-BC38-C3D111D0DBB7}
20230347	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{51E41A2E-C962-4079-A56D-A0C267E0C7D1}
20230452	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{DCEB3967-F2E7-45FD-B366-43415611F613}
20230454	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{165A6EB2-B0F8-4264-B884-76FDEAEBE616}
20230458	<Null>	<Null>	No DWS at railroad crossing.	No	{3897D45D-25F1-497E-8616-8FAA539E1A43}
20230351	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{E49CF2B7-A1AD-4694-891D-0217DA748162}
20230146	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{3507513E-20C4-4B48-A56E-B39FB2CC29E4}
20230147	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EBAA6FCF-EEFD-4A2C-9EDA-4775E205B73F}
20230256	More than 2%	4 x 4 feet or greater	Cross slope 3%.PAR cross slope 4% . Minor curb lip.	No	{BC466A9C-7BB9-4A53-929E-5F1FB67C23DB}
20230257	More than 2%	4 x 4 feet or greater	Cross slope 3%. PAR cross slope 4%. Minor curb lip.	No	{659E4532-0F9C-4BBA-926D-AB401B21A450}
20230258	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip.	No	{5B666CD8-4EAE-4543-9B1A-4E9E4DF2348A}
20230259	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%. Minor curb lip.	No	{449A192E-EB8C-4063-87E6-0A6BE2B64A9E}
20230261	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes 2.5%. Minor curb lip.	No	{9461E06D-3029-448E-B52F-DFBDE29710E9}
20230262	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%. Minor curb lip.	No	{883C7B59-032D-4FA3-9799-C9E91AFD782F}
20230263	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{2BEE906A-2A82-4757-9A1E-7DDE67F08B8E}
20230264	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9D55DD66-3C3E-4562-8ED2-CF59A35C34D0}
20230265	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E7EC70B5-4AF1-4C27-9641-361185495865}
20230430	<Null>	Less than 4 x 4 feet	Add DWS and landing ahead of unpaved trail	No	{D8A6619C-DBE2-4F5C-83AB-4FA0E9306FE3}
20230266	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.5%.	No	{858C856A-3AFA-4AAB-8E9D-A297373143FD}
20230267	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{76C089C2-EAAB-4C7A-8CBE-EF728877F910}
20230268	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A539D420-57F6-4704-9175-9C3C4FE71A35}
20230346	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{4025764C-328B-4A47-9EF2-38919B5B4123}
20230286	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR cross slope 4%.	No	{213461E5-B2FA-4747-9CF5-5A2E0896B49A}
20230287	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%.Monitor gap between ramp and landing	No	{C1A2014B-12AE-41D0-A829-638674A9A67B}
20230288	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 6%	No	{C32BFFBB-4A67-41F4-B8EB-F53F8AB687C7}
20230289	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.3%.	No	{46EDB82C-B357-4EC7-9F6C-4C9D7EE93B32}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230290	More than 2%	4 x 4 feet or greater	Running slope 8.5%. Cross slope 2.6%.	No	{F652E5D2-0E9D-493C-BF99-77B31D4A8A80}
20230291	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{066195D2-29D2-4F74-81E0-CD5E213D7CC8}
20230292	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Matches roadway grade. Landing running slope 3.5%.	No	{6B50FD9E-EF45-42B3-B9AA-E69EF0B8C53C}
20230293	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Matches roadway grade. Landing running slope of 3.5% within PAR.	No	{155E436F-90B3-4E9F-865C-4351322F0C4F}
20230294	More than 2%	4 x 4 feet or greater	Cross slope 7%. Matches roadway grade. Landing cross slope 7%	No	{01808B5E-F373-40EF-840A-7AEE1417889E}
20230295	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 7%. Matches roadway grade. PAR running slope 6%.	No	{A4A55C10-0E1F-459A-A8C2-9C1632FDC5EB}
20230296	More than 2%	4 x 4 feet or greater	Cross slope 6%. Landing running slope 6%.	No	{AFB5138F-A4D9-46E1-A126-8BF7B06889DD}
20230297	More than 2%	Less than 4 x 4 feet	Cross slope 6%. Landing running slope 7%	No	{B2C2EB28-CEDA-4904-A104-B777D3C33E69}
20230298	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{7BC9F918-72F7-4667-BE2F-9B42E5EE10AF}
20230299	Up to or equal to 2%	4 x 4 feet or greater	Curb lip	No	{C83F1DB0-F64B-44B9-9D46-BE49FC8F0B11}
20230300	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 5%.	No	{37B29AD8-50F9-46E0-8C0C-F7FFBF0C45D3}
20230276	<Null>	<Null>	Consider providing formal accessible bus platform	No	{DDA7A41E-77DB-47E8-A1C1-8DEE2DD82629}
20230277	<Null>	<Null>	Reconsider bus stop location and/or provide accessible pedestrian crossing.	No	{E38921BC-15A9-4AF8-8283-F23FE77949E4}
20230304	More than 2%	4 x 4 feet or greater	Cross slope 6%. Landing within PAR. PAR running slope 10%.	No	{31049418-94F8-4830-8A4D-16DA510F5C99}
20230305	More than 2%	4 x 4 feet or greater	Potential MEF. Cross slope 7% . Landing running slope 9%. Landing cross slope 10%	No	{55E9A958-0701-4E78-9053-BB46DD0C49BF}
20230306	More than 2%	Less than 4 x 4 feet	Cross slope 3.5%. Landing slopes 3.5%.	No	{BD6C0438-3379-4AF4-B592-99982C65B6BD}
20230307	More than 2%	4 x 4 feet or greater	Cross slope 6%. Landing running slope 6%. Landing cross slope 4%. Curb lip.	No	{BAD41FDF-06EF-4FBD-8A7A-35B0EC88D0BC}
20230308	More than 2%	Less than 4 x 4 feet	Cross slope 9%. Landing within PAR. PAR running slope 9%. Minor curb lip.	No	{2EFB9E59-0F90-444B-AE6C-702D291E7C3F}
20230309	Up to or equal to 2%	Less than 4 x 4 feet	Minor curb lip	No	{8D0ABB4C-B666-4170-8B21-9729D6E0D0B9}
20230310	More than 2%	Less than 4 x 4 feet	Cross slope 8%. Landing running slope 11%	No	{606D937D-26A9-4C2B-AFE4-CBEBF2716A0E}
20230311	More than 2%	Less than 4 x 4 feet	Cross slope 9%. Landing within PAR. PAR running slope 12%	No	{6B049540-C47C-46D3-9F2A-71AA679072CE}
20230312	More than 2%	4 x 4 feet or greater	Cross slope 2.5% . Landing cross slope 2.6%. Curb lip.	No	{BF547A0A-F2DF-4576-B750-8CA653FFE14D}
20230313	More than 2%	4 x 4 feet or greater	Cross slope 3%. Landing running slope 3%. Landing cross slope 2.5%.	No	{F28151DD-346D-4053-99EC-2825A07F5DB9}
20230314	More than 2%	4 x 4 feet or greater	Cross slope 12%. Landing Runng slope 7%. Landing within PAR.	No	{E4BA90AB-92DF-4277-B8A3-26B47FA83EF3}
20230315	More than 2%	4 x 4 feet or greater	Cross slope 9%. Running slope 12%. Minor curb lip. Landing within PAR.	No	{C73F85A9-4B55-4068-920D-08AB8B18FEFF}
20230316	Up to or equal to 2%	Less than 4 x 4 feet	Reorient ramp North-South.	No	{B4D68A78-8235-4879-A601-336BF95810CF}
20230137	<Null>	<Null>	Add ramp to cross intersection	No	{C42B0CF7-C0EB-409A-961F-A1FB8F2659A3}
20230139	More than 2%	4 x 4 feet or greater	Cross slope 3%. Landing running slope 4%.	No	{DDAC95CF-3003-4249-8A43-1E173741F551}
20230141	More than 2%	4 x 4 feet or greater	Cross slope 5%. Landing running slope 6%. Landing cross slope 5%.	No	{5082C334-4E7A-4EF1-90AA-9CD2F31F2C91}
20230143	More than 2%	4 x 4 feet or greater	Cross slope 2.6%. Landing running slope 6%. Landing cross slope 2.6%.	No	{FFF3A240-6918-4E4E-A1B0-23395530F7BC}
20230145	More than 2%	4 x 4 feet or greater	Running slope 8.6%. Cross slope 3.5%.	No	{38C6C48F-50A4-4AD0-8057-243C95CF9E7E}
20230033	More than 2%	4 x 4 feet or greater	Running slope 9%. Cross slope 2.3%. Landing cross slope 2.3%.	No	{34652EB0-5C80-4B85-A2AF-27B3229E31CF}
20230028	More than 2%	4 x 4 feet or greater	Cross slope 2.8%. Landing running slope 4%.	No	{CBD4EADD-474F-44E0-8C51-FAD10F227920}
20230348	More than 2%	4 x 4 feet or greater	Cross slope 8% matches roadway grade.. Landing with PAR. PAR running slope 9%.	Yes	{476BFAAA-2EA7-4428-9E07-520CE9393452}
20230349	More than 2%	4 x 4 feet or greater	Potential MEF. Cross slope at 6% matches roadway. Landing Reading slope 9%. Landing cross slope 4%.	Yes	{4B7F81CA-9887-4D63-93DE-B8F85556887C}
20230350	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2%	Yes	{5F852F55-955D-403F-9088-612E0AC8D825}
20230260	Up to or equal to 2%	4 x 4 feet or greater	Landing running slope 3.6% within PAR. Minor curb lip.	No	{74C8239D-31D1-4B36-A96B-3313C88A3D2B}
20230352	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. Landing running slope 6.6%. Landing cross slope 2.5%. Minor curb lip.	No	{362F7B91-26CB-46E3-9FA0-71BA909738D5}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230353	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. Landing slopes within 1%. DWS deterioration.	No	{BA00B2EE-5583-44D5-A50B-F2074C0D46EC}
20230354	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. Monitor sidewalk gaps.	Yes	{EB47AC95-B389-4278-BC2F-96E0F8F4C2D6}
20230355	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. Landing slopes within 2%. Running slope 8.8%.	No	{6DEF2E2C-D4C7-408E-B36C-413707280845}
20230356	Up to or equal to 2%	4 x 4 feet or greater	Cross slope 3.8%. Landing running slope 3.7%. DWS deterioration. Minor curb lip.	No	{B31B21CF-8794-4914-918C-44B51A05E9A8}
20230357	Up to or equal to 2%	4 x 4 feet or greater	Cross slope 4%. Landing within PAR. Landing running slope 3.4%. DWS deterioration. Minor curb lip..	No	{3B2FDF5E-3CC4-4A6F-A039-B3A63C437890}
20230358	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. Landing running slope 2.8%. Monitor sidewalk gaps. DWS deterioration. Minor curb lip.	No	{82D7B61F-EF0C-4C8E-B9D7-C6A3974A094E}
20230359	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. Landing cross slope 4%. Monitor sidewalk gaps. DWS deterioration. Minor curb lip.	No	{0667D148-F1FC-4796-A8B1-8F20B593488E}
20230368	Up to or equal to 2%	4 x 4 feet or greater	Landing slope 3%. Ramp diagonally offset to receiving ramp. Monitor landing to curb ramp upheaval	No	{A15701F4-1037-474E-AA1D-D2274906B57F}
20230369	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2%. Ramp not aligned with receiving ramp.	No	{F04DDE1C-93FE-4439-8796-CF211C77927A}
20230361	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 1%	Yes	{D488602E-8F37-433F-A28B-3161595939EA}
20230370	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2%	Yes	{1CAF7C7D-50E7-4988-A015-BA0E74BE2293}
20230371	<Null>	<Null>	<Null>	No	{C16DCDCF-7E75-489E-9AC3-CD5853DE173F}
20230372	<Null>	<Null>	No receiving ramp	No	{830E5006-7EC7-4DDF-AAAA-3BB13C8D5489}
20230373	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 10%. PAR running slope 10%. Landing cross slope 2%.	No	{76062937-92E0-423D-825D-5CCB61C1256A}
20230374	More than 2%	4 x 4 feet or greater	Cross slope 9%. Landing running slope within PAR 7.5%. Asphalt deterioration.	No	{0272690D-2E0D-4115-841A-E909104DE539}
20230375	More than 2%	4 x 4 feet or greater	Cross slope 7%. Landing running slope 7.5%. Matches roadway grade.	No	{0AEFF2F7-8714-449C-BD6B-D607EF6A5CBE}
20230376	More than 2%	4 x 4 feet or greater	Cross slope 8%. Landing running slope within PAR 11%.	No	{9C652BF5-4CC5-4B3B-88E8-17201DA8228B}
20230377	More than 2%	4 x 4 feet or greater	Cross slope 3.6% matches roadway grade.Landing within PAR running slope 5.5%. Landing cross slope 4.6%.	No	{7461B009-F302-4934-991A-6AC6C9C1FF27}
20230378	More than 2%	4 x 4 feet or greater	Cross slope 4.3% matches roadway grade. anding running slope within PAR 6.3%.	No	{8BCC5883-9CFD-4FD7-8C73-B3617A0D9DB0}
20230383	Up to or equal to 2%	Less than 4 x 4 feet	Landing cross slopes within 3%	No	{FC59D197-F1B4-4870-B7E1-37FC4DBB551E}
20230384	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{F755216F-8AAE-4EE5-8949-1E044AE2D13A}
20230385	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%.	No	{62F9C875-84E1-4BCF-AA51-24B2C89DFC69}
20230386	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 3%. Matches roadway grade. PAR running slope 4%.	Yes	{BBCEC53E-E6C6-435C-92DC-7B6676324AC8}
20230387	More than 2%	4 x 4 feet or greater	Cross slope 8%. Matches roadway grade. PAR running slope 10%.	Yes	{59081A81-5BF8-4D1E-B7DA-2FEF84F327D6}
20230388	More than 2%	4 x 4 feet or greater	Cross slope 9.7%. Matches roadway grade. PAR running slope 11%. PAR cross slope 8.5%.	No	{98BE6D35-44AA-4AAD-8ECE-8E09AACF989B}
20230389	More than 2%	4 x 4 feet or greater	Running slope 9%. Cross slope 7%. Matches roadway grade. Landing Runng slope within PAR 5%. Landing cross slope 2.7%.	No	{602EF597-1047-4E0C-B379-BCDE2801A1C4}
20230390	More than 2%	Less than 4 x 4 feet	Cross slope 2.3%. Landing slopes 3%.	No	{4175F9C6-AAC0-4268-8A5F-E1CCA8892DFB}
20230391	Up to or equal to 2%	Less than 4 x 4 feet	Landing cross slope within PAR 3%	No	{F5E16FB7-8115-49D6-AC4A-C51608DAB573}
20230392	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 4%. Matches roadway grade. Landing cross slope 2.7%	No	{9C5A10A5-613B-4F66-BB0A-6910662652BA}
20230393	More than 2%	4 x 4 feet or greater	Running slope 12%. Cross slope 4%. PAR running slope 10%. Monitor upheaval.	No	{4927BFAE-20C9-415F-9318-AE534128C0A3}
20230394	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. PAR running slope 10%	Yes	{FFD89A3A-46D9-474C-8783-D2E6EBB79848}
20230395	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. Matches roadway grade. PAR running slope 2.6%.	Yes	{608EB677-A824-4EF1-9396-553A8846BCF2}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230396	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{28337E29-72D6-4A2B-A0F3-4597544A7E38}
20230397	<Null>	4 x 4 feet or greater	Instead of adding mid-block ramp crossing, extend PAR to the east to existing ramp	No	{149A382B-DDC0-4F99-966E-D3E73FD32513}
20230399	More than 2%	Less than 4 x 4 feet	Cross slope 4%. Matches roadway grade. PAR running slope 5.6%	No	{96621C72-DDB8-4CD0-A90F-9F4A27B31FA1}
20230400	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 5%.	Yes	{D416562C-D451-4FF3-9ED2-7BC118A50D5B}
20230401	More than 2%	4 x 4 feet or greater	Cross slope 10%. Matches roadway grade. PAR running slope 8%.	Yes	{94998084-2533-4D8C-973A-9688421EAE60}
20230402	More than 2%	4 x 4 feet or greater	Cross slope 8.3%. Matches roadway grade. PAR running slope 9.8%.	Yes	{E1B428E4-C223-4A28-A99C-FOA8FCDE71A6}
20230403	More than 2%	Less than 4 x 4 feet	Cross slope 16%. PAR running slope 17	No	{1FD75372-D567-4EDC-B10C-39AF65724E99}
20230404	More than 2%	Less than 4 x 4 feet	Cross slope 3.6%. PAR running slope 6.5%. PAR cross slope 9.8%.	No	{7BEBA95E-2E64-4DC9-9281-45F3D3A74A41}
20230405	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D45178FA-7FA7-4931-B541-FA8076EA46EA}
20230406	More than 2%	4 x 4 feet or greater	Cross slope 8%. Matches roadway grade. PAR running slope 10%. PAR cross slope 2.3%.	No	{9ADEE68E-E014-433C-8A4E-61FC0A37F0AF}
20230407	More than 2%	4 x 4 feet or greater	Cross slope 8.2%. Matches roadway grade. PAR running slope 7.6%.	Yes	{13EA2ED9-7D8C-481B-98B8-36FDFE2E0DE5}
20230410	More than 2%	Less than 4 x 4 feet	Running slope 9%. Cross slope 13%. Matches roadway grade. PAR running slope 15.8%. PAR cross slope 3.7%.	No	{8A03E540-8CA8-41A2-9536-26B2DA88E405}
20230411	More than 2%	Less than 4 x 4 feet	Cross slope 6.2%. PAR running slope 10%	No	{465E11E8-3DCC-47F7-89D7-99452BEA5E6D}
20230412	More than 2%	4 x 4 feet or greater	Cross slope 12%. Matches roadway grade. PAR running slope 16%. PAR cross slope 5%.	Yes	{CB185E55-DCE4-4FE8-B8EA-1740A460E9F0}
20230413	More than 2%	4 x 4 feet or greater	Cross slope 12%. Matches roadway grade. PAR running slope 12%.	Yes	{ABD67B98-F5F0-4C19-9A26-631550D5EFE5}
20230414	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 5%	Yes	{9C7C2E1E-DEEF-4FB8-941D-333274C7C17D}
20230415	More than 2%	4 x 4 feet or greater	Running slope 9%. Cross slope 4%. Overgrown vegetation. Landing slopes within 2.5%.	No	{EDEBF84A-2CB7-41AD-8E27-8B0EABC9428E}
20230416	More than 2%	Less than 4 x 4 feet	Cross slope 8.3%. Matches roadway grade. PAR running slope 12%.	No	{455D19B5-05D9-442B-9674-D3C58A4B1DD5}
20230417	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{11317DCA-8BA0-4E89-A242-B7E19FBEDE66}
20230418	Up to or equal to 2%	Less than 4 x 4 feet	Overgrown vegetation	No	{3B8D2F3D-24A6-4237-8EBF-56CEFEED5DC2}
20230419	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AD30DD1A-6F17-41FF-A15B-3B0EF77F6992}
20230420	More than 2%	Less than 4 x 4 feet	Cross slope 5.5%. No landing.	No	{624CA1A2-7849-4569-B454-628EE7D370C5}
20230421	More than 2%	Less than 4 x 4 feet	Cross slope 3%. PAR running slope 5%.	No	{3D56955B-62F5-4DF3-B0AD-76198582DD8D}
20230426	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9.4%.	No	{303F03EB-895A-4929-9672-622EFC1E6F4B}
20230427	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 5%	No	{E3832C15-39D3-4BD9-B551-372099E05B5F}
20230428	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. PAR running slope 3.9%. Sidewalk upheaval at curb panel.	No	{411AB885-31B5-46D3-AF88-56778A3A1682}
20230429	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. PAR running slope 5%.	No	{11A5944F-712D-4671-93F2-3AE918336E71}
20230459	More than 2%	4 x 4 feet or greater	Monitor panel gaps. Cross slope 3%. PAR running slope 3%.	No	{D3F8E065-6C35-4548-B27E-8889768711B4}
20230460	Up to or equal to 2%	4 x 4 feet or greater	Patio table and chairs within PAR	Yes	{692DBA98-EB50-46A1-A902-DC4096A0488E}
20230461	More than 2%	4 x 4 feet or greater	Monitor panel gaps. Cross slope 3%. PAR running slope 3%.	No	{E648BB62-047C-4C5F-8A4E-636BB0E87A1C}
20230462	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9093420F-7F7E-4645-A86B-C224EB57026D}
20230463	Up to or equal to 2%	4 x 4 feet or greater	Monitor panel gaps	No	{9A7D8CD7-D624-4F6C-9AEB-00E3BD0EEFE2}
20230464	More than 2%	4 x 4 feet or greater	Cross slope 3%. PAR running slope 2.7%. Monitor panel gaps.	No	{61FD7D64-DE14-4183-A656-7E15C0415C71}
20230465	More than 2%	4 x 4 feet or greater	Running slope 9.3%. Cross slopes 3%. Landing within PAR. Landing cross slope 2%. Monitor panel gaps.	No	{6FD102F6-E777-4D61-A424-5A35AD165946}
20230466	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 4.5%.	No	{851E65FB-FA7C-4F55-A4E0-02C07082B7E4}
20230467	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 3%. PAR cross slope 4%. Monitor panel gaps	No	{25D8DCB0-E752-47E7-AF18-B2E76F42F60F}
20230468	Up to or equal to 2%	4 x 4 feet or greater	Monitor panel gaps.	No	{587AE0E2-307F-4097-B75C-C274F8A574E2}
20230469	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 5%. Monitor panel gaps.	No	{50AC88EB-7B3B-4822-997F-8A64BE10F148}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230470	More than 2%	4 x 4 feet or greater	Cross slope 4.3%. PAR running slope 5%. Monitor panel gaps.	No	{C3B87BA1-ECA7-4A39-9807-9E7F262AE4BB}
20230471	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{E8DA4290-8943-4ADE-B4F2-3EE5FFAF6818}
20230472	More than 2%	4 x 4 feet or greater	Cross slope 2.6%. PAR running slope 2.5%. Monitor panel gaps.	No	{B9F45ACF-2AA4-49AE-89C7-C248B03A64C9}
20230473	More than 2%	4 x 4 feet or greater	Cross slope 8%. PAR running slope 8%. Monitor panel gaps.	No	{D00E9827-947D-464F-B548-B22729E0B796}
20230474	Up to or equal to 2%	4 x 4 feet or greater	Monitor panel gaps.	No	{07F7E970-50C8-4543-BECC-455391302A9B}
20230475	Up to or equal to 2%	4 x 4 feet or greater	Monitor panel gaps	No	{B6F59573-E982-4DF2-BF58-3D84FB012A8C}
20230476	Up to or equal to 2%	4 x 4 feet or greater	Old DWS runs length of landing and ramp	No	{F328F660-4036-43EF-9736-8B65A247CA8B}
20230477	Up to or equal to 2%	4 x 4 feet or greater	Curb lip. Sidewalk ramp gaps.	No	{5CB18229-1335-487A-8080-B0EB5B5C1D30}
20230478	Up to or equal to 2%	4 x 4 feet or greater	Crack in flare. Monitor panel gaps. Curb lip.	No	{CD414974-6B85-4FE9-8712-F2534F775D66}
20230479	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%.	No	{58EABD8E-4324-40BD-A791-B52014FF8EF2}
20230480	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 3%. Monitor panel gaps.	No	{F486A11D-C8DB-4458-8581-B7EF1DA4DB32}
20230481	Up to or equal to 2%	4 x 4 feet or greater	1.5 inch gap between landing and ramp panels.	No	{0DA9F57A-CA99-4D76-90C0-0BB7D361C013}
20230482	More than 2%	4 x 4 feet or greater	West approach ramp cross slope 2.3%. Monitor vegetation in gap.	No	{40239663-67F7-44FC-840C-E85753D20433}
20230483	More than 2%	4 x 4 feet or greater	PAR approach ramps cross slope 2.7%. Landing running slope 4%. Monitor vegetation in panel gap.	No	{D8FABB08-CE4B-4106-AD5F-5A07E909BF8D}
20230484	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{A412601E-21E1-4DDF-9D3E-E37E79FD22C7}
20230485	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{F0F5619E-4694-4869-BF62-9106992A0C79}
20230486	Up to or equal to 2%	4 x 4 feet or greater	Dirt at transition to road.	No	{F163E508-F705-4492-B8B1-A70AE5EE4DC3}
20230487	More than 2%	4 x 4 feet or greater	Tree root in panel gap. Cross slope 3%.	No	{8EB4F358-C601-416E-BC32-1C9CAF8BB62B}
20230488	Up to or equal to 2%	4 x 4 feet or greater	ADA parking access ramp	No	{7FD2ED44-9240-40FA-AB9B-84072C58A5EA}
20230489	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%.	No	{CA88C4A1-FD6D-4C62-9F27-B72D756105D9}
20230490	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.3%. Vegetation in panel gap.	No	{D3B00D38-480B-42BA-B16E-99EA0C3150B2}
20230491	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.5%. 1.5 inch landing to ramp gap.	No	{5C58EE59-602A-4BA3-9E21-B542C2A100B2}
20230492	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%	No	{AC29F763-4B83-495F-BAB7-465E52CDC0FC}
20230493	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{CEE8A792-0813-4CE4-86CF-5581A83F830B}
20230494	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%.	No	{2DC791F0-29FD-451C-92A6-0A9FE1B47020}
20230495	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 4.5%. PAR cross slope 3.2%.	No	{8B3F9761-2683-4E37-91D4-B0ACB9847E73}
20230496	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{E0B5FA6A-231B-4E83-B004-34398D4BABD1}
20230497	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.5%. Monitor new panel corner upheaval at ramp.	No	{6AA5790E-AD9D-4FD0-8BF9-31DF474469A7}
20230498	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 4%. PAR cross slope 2.5%.	No	{D949B303-CF93-4DC6-8CDE-FCA033228F58}
20230499	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{379F54DD-5F26-4EE5-94DE-887A5C3AD4BD}
20230500	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 4%.	No	{784D4E3E-4998-4BC8-9C16-4AA467E538D3}
20230501	More than 2%	4 x 4 feet or greater	Cross slope 5%. PAR running slope 8%.	No	{E4E898B4-AD8C-452B-BC3F-E3B83AEBEA32}
20230502	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 6%.	No	{B11BFD0D-2091-4031-B802-2C76218306DD}
20230503	More than 2%	4 x 4 feet or greater	Cross slope 3%. PAR running slope 4%. PAR cross slope 6%.	No	{49F101D3-5C23-4A30-B348-ACA3BB2B5F32}
20230504	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{2E1E050A-B76F-47A1-B280-6C16F0903EE1}
20230505	More than 2%	4 x 4 feet or greater	Running slope 3%. PAR cross slope 4%.	No	{69056D1C-8BEF-468F-968B-D1F5E46A96DF}
20230506	More than 2%	4 x 4 feet or greater	Cross slope 2.7%. PAR cross slope 2.7%.	No	{F644905D-5788-4163-A82D-D77C13E42243}
20230507	More than 2%	Less than 4 x 4 feet	Landing panel gap. Cross slope 3.4%. PAR running slope 4.7%	No	{0F2AFD1E-8FA0-478B-B151-743F2FE1D317}
20230508	More than 2%	4 x 4 feet or greater	Cross slope 3.3%. PAR cross slope 3.4%. PAR running slope 5%	No	{5E0CFB70-35A2-43EF-BF69-05C7D0AC63D9}
20230509	Up to or equal to 2%	Less than 4 x 4 feet	Curb lip. Monitor panel gaps.	No	{919AC368-6ABB-4472-AF46-877059D168E6}
20230510	More than 2%	4 x 4 feet or greater	Curb transition less than 36 inches. DWS upheaval. Cross slope 4%.	No	{F05AB48E-88FA-4677-AFCC-427DBBB3E450}
20230511	More than 2%	Less than 4 x 4 feet	Cross slope 3.4%. PAR running slope at 6%. PAR running slope 6.5%.	No	{4923E869-9832-45FD-9BCF-8DB9F313AA87}
20230512	More than 2%	4 x 4 feet or greater	Running slope 9.5%. Cross slope 2.6%. PAR running slope 5.4%.	No	{2B93FF32-4ACA-44AF-B737-AF2054119C3F}
20230513	Up to or equal to 2%	4 x 4 feet or greater	Cross slope 2.7%.PAR running slope 4%.	No	{21996A02-C597-451A-A0F7-9DA197F179B1}
20230514	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{8AFAC14B-1AA2-4F6D-95A1-CE874EB9A9EB}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230515	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 4%.PAR cross slope 5%.	No	{4772456B-B3B9-4D4A-992B-EBCC06773E82}
20230516	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 3%	No	{1B461794-B743-442F-B310-73C06DC01E28}
20230517	Up to or equal to 2%	4 x 4 feet or greater	Curb lip.	No	{F5EEAE5D-B7AA-4863-896A-689C23F9347A}
20230518	Up to or equal to 2%	4 x 4 feet or greater	Running slope 8.4%.	No	{DB980A72-447F-4AEE-81B6-F79CBD001C06}
20230519	More than 2%	4 x 4 feet or greater	Running slope 11%. Cross slope 3%. Landing has wavy concrete.	No	{24C57873-6E40-46D7-9988-F459D7D6E4F5}
20230520	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 3%. PAR cross slope 2%.	No	{EB743DEB-B819-4613-BFDC-879A0053A325}
20230521	Up to or equal to 2%	4 x 4 feet or greater	PAR running slopes 3%.	No	{157020BE-341F-4EFA-9AF0-BD0C811C4884}
20230522	More than 2%	4 x 4 feet or greater	Cross slope 3%. PAR running slope 5%.	No	{5CDF7B0E-3BD8-44C9-8E5C-BBB2A6FE3251}
20230523	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{11529438-8A23-49E9-A533-BF316B7450BE}
20230524	More than 2%	4 x 4 feet or greater	Cross slope 3%. PAR running slope 3%.	No	{0C8E6B27-1AE6-4CFC-A5CC-C38E1EC39CE6}
20230525	<Null>	<Null>	No receiving ramp	No	{56039CBC-F8B7-4A82-BBB8-8A26EA6D8B53}
20230526	Up to or equal to 2%	4 x 4 feet or greater	Running slope 15%. Matches roadway grade. Adjacent PAR running slope 16%.	Yes	{02A46D5A-D925-4901-BB64-4B6143AF6CCD}
20230527	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A50B6C85-186B-40F9-86C6-F52E8D1656B3}
20230528	Up to or equal to 2%	4 x 4 feet or greater	DWS on both sides of median refuge	Yes	{39EBB552-7020-48D5-9E27-3562825659D7}
20230529	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2%	Yes	{285E25E7-BD48-4E24-A417-3ACC02E81FA9}
20230530	Up to or equal to 2%	4 x 4 feet or greater	Landing running slope 2.7%.	No	{83959017-CC60-4DAF-9B3C-825D1E282CC2}
20230531	Up to or equal to 2%	4 x 4 feet or greater	DWS on both sides of median refuge	Yes	{49B8451F-AC27-4091-BC6E-C81D906E483F}
20230532	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B8AFD8CD-E190-4533-8A43-F52917F93D93}
20230533	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{9ACF56D5-5847-48D3-9E0F-9D38B0E47830}
20230534	Up to or equal to 2%	4 x 4 feet or greater	DWS on both sides of median refuge. Cross slope 1.3%.	Yes	{DEC4321C-07BB-40CC-B152-976B54F35CFB}
20230535	Up to or equal to 2%	4 x 4 feet or greater	DWS within landing	Yes	{517CA7AB-A7C1-4B71-9316-ABB98F121B05}
20230536	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{41BBABFB-8208-4954-87F4-E3ACF469972A}
20230537	Up to or equal to 2%	4 x 4 feet or greater	DWS on both sides of median refuge. Blended transition cross slope 1.3%.	Yes	{4C29DB5D-617E-483B-97FD-E8B60C2A8692}
20230538	More than 2%	4 x 4 feet or greater	Cross slope 3% matches roadway grade.	Yes	{E0315A7B-A322-46F2-A3E0-33FDB0B9CADC}
20230539	<Null>	<Null>	35 inches between concrete upheaval	No	{58861C44-FF4A-48C3-BD6E-AFA320DA0B35}
20230540	<Null>	<Null>	35 inches between concrete upheaval	No	{5EF8C0C9-3283-4CE9-8952-B5CF1E51E5B0}
20230541	Up to or equal to 2%	4 x 4 feet or greater	35 inches between concrete upheaval of posts in PAR	No	{597F1915-CACC-43B2-A683-A3B3E6753CF2}
20230543	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{885F34DC-4196-4165-8A54-94F3AC31E23C}
20230544	Up to or equal to 2%	4 x 4 feet or greater	Running slope 8.7%. Minor curb lip.	No	{20C04628-6BF8-4131-891B-79A2C07E09C1}
20230545	<Null>	<Null>	No DWS in median refuge	No	{217F15D3-9AA1-47D1-A73D-4AA2C8082E36}
20230546	Up to or equal to 2%	4 x 4 feet or greater	Landing running slope to ramp 2.7%.	No	{2542D925-F43D-4C02-91D6-430E0AB8E8DF}
20230547	<Null>	<Null>	No DWS at railroad crossing	No	{5E6B922F-9F10-43B2-A1B4-67E49ABF13C2}
20230548	<Null>	<Null>	No DWS at railroad crossing	No	{A71ADDB8-6362-43F7-8063-452D303A04C4}
20230549	<Null>	<Null>	No DWS at railroad crossing	No	{66D9CC1A-B5E2-4D06-AEE2-B434C2DF7E52}
20230550	<Null>	<Null>	No DWS at railroad crossing	No	{7268E4DE-7F0C-499E-BC66-B06CE847391B}
20230552	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{F85BD032-4388-4A3C-93F1-3F9AA9BA668D}
20230553	More than 2%	4 x 4 feet or greater	<Null>	Yes	{4B8C5DA4-C0E1-4301-9260-86F723CE616B}
20230562	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{FC5D04CB-59C6-4BA8-AA2B-D9F7BE86AE1B}
20230563	Up to or equal to 2%	4 x 4 feet or greater	Ramp surface deterioration. Gap to surrounding panels.	No	{0499C30A-D0FA-4B6C-8D03-CF87653698F3}
20230564	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{0969FEE5-6858-4178-97F3-737DEB3B3710}
20230565	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{8F0398BC-09F5-420B-8F6D-F275051A402F}
20230566	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{CB01283E-1EC6-44A9-84D1-0E1CEBCD522F}
20230567	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{98C44219-A47D-4737-8973-183CEE452739}
20230576	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{F244DDD7-15D5-4136-A5C9-13BA0E31F3F5}
20230577	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{FA979D92-57F6-4A4E-BB67-C5A52B7CAD0B}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230578	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E6CFF0EA-B88C-4FC6-A914-252E4BF1EF76}
20230579	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B458C6DB-9D30-4F85-9F5C-1B53ACAD7B41}
20230580	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{CCF2DBE4-20F8-482B-A082-35BCC0851A2F}
20230581	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{46339C72-94FC-4780-B8E6-58B146C5AD00}
20230582	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{99EA0E14-DB80-42F0-9AB7-B734196912AE}
20230583	More than 2%	4 x 4 feet or greater	<Null>	Yes	{910D2130-278A-4557-952A-A7D1A8BC14B9}
20230584	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{F37866B9-6E62-4D23-AB6E-35B156E69B39}
20230585	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{582A9C4C-B39C-400E-8E15-2D31A347EA47}
20230586	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{194C0923-962D-4E1D-A9BD-842323A90436}
20230587	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{39EB9541-0179-406D-9088-05137C2685AA}
20230588	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{7A4CAC28-F632-4489-A695-9B63ED03067E}
20230589	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DA7F93D8-EBDE-4DB7-BBFC-3CC5D2F509C5}
20230590	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{41CC4E49-21B7-43D3-89C2-67090617C7B2}
20230591	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{71866F93-CF72-42C3-AC19-F86A7F5D58E7}
20230592	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E4AF4753-F2FD-45C6-B7AD-DCC9E433B20B}
20230593	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B5707F47-CC52-42E7-AF0C-A28B4FC094C4}
20230594	More than 2%	4 x 4 feet or greater	Cross slope 2.3%. Matches roadway grade.	Yes	{1FC76373-AE99-4F18-87E7-DB4744F85DB9}
20230595	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{61C14781-924F-4699-9DFA-3592846B46EF}
20230596	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Matches roadway grade. Monitor sidewalk panel upheaval.	Yes	{B2CBAC71-2960-4371-B902-FE75748A137F}
20230597	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 5%. PAR cross slope 4%.	No	{671F00BF-BAAD-49A3-9355-C5234B820860}
20230598	Up to or equal to 2%	4 x 4 feet or greater	Remove ramp. Does not have PAR to cross to.	No	{E1223D45-2275-4801-8ABE-24F542FDBFBA}
20230600	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C6E7A6D0-9F63-45B4-AC2A-34C0F4219556}
20230601	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{32B164C9-EA8A-4B93-B6D2-573E88145C06}
20230602	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EB8754E2-9C36-4D57-ABDD-10596F6408E2}
20230603	Up to or equal to 2%	4 x 4 feet or greater	Panel gap. DWS upheaval. Curb lip.	No	{EFAEFEBF-3B8B-452C-84AB-B65C2D1A922B}
20230604	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 4%.	Yes	{A66CAF38-8791-4F4A-8953-F0CBCB3899E0}
20230605	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 6%. PAR cross slope 2%.	Yes	{BECC7DF3-3445-4A3B-BBB2-D5D2ED18E848}
20230610	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{F8A4CAC5-B5AC-4420-9ADA-CA48F2CC1708}
20230611	Up to or equal to 2%	4 x 4 feet or greater	Landing panel upheaval	No	{B9C1932B-37F8-40F6-9047-51312366278E}
20230612	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%.	No	{02A0C162-430D-47B6-AFEA-F9FE3315410D}
20230613	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.3%.	No	{375E76A6-A5EE-42B3-95CF-A774317DCE18}
20230614	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.6%.	No	{ED37B838-9882-47B6-B6D0-80499E2D5F0F}
20230615	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.3%.	No	{E9839EE4-D4DC-4E09-8BD7-01026B3BB360}
20230616	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 5.5%. PAR cross slope 3%. Overgrown vegetation.	No	{702F77E9-14C3-437D-8C1C-FEBEFC79EE5B}
20230617	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 5%.	Yes	{5F43A167-C3E1-48FB-870F-EF959425ABF6}
20230618	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 4%. PAR cross slope 3%.	No	{B7152159-4CD8-4930-850F-555DE18F7257}
20230619	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 6%. PAR cross slope 3%.	No	{B9E7CD46-59F2-4220-8E81-E4F268957B26}
20230620	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{CD68DA56-4613-49D7-B291-5C29F455B180}
20230621	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 5%. Minor curb lip.	Yes	{2FE23106-5644-4167-936B-A36769956C68}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230622	More than 2%	4 x 4 feet or greater	Cross slope 4%.vMatches roadway grade. PAR running slope 4%	Yes	{41E69875-5702-4D24-A265-2855BA5E41EC}
20230623	More than 2%	Less than 4 x 4 feet	Cross slope 4%. Matches roadway grade. PAR running slope 11% approaching ramp slope.	Yes	{2E625420-F1E9-429E-8E7E-01A139403422}
20230624	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	Yes	{7161F1C1-89FC-4ECA-96B8-DC32F176C105}
20230625	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.8%.	No	{2CF80C81-8C92-4C02-ACCA-BE8640A6D7F1}
20230626	More than 2%	4 x 4 feet or greater	Cross slope 3.4%. Matches roadway grade. PAR running slope 3.4%.	Yes	{FC096989-A140-4AF0-A06B-4F6F536DABC6}
20230627	More than 2%	4 x 4 feet or greater	Cross slope 4.5%. Matches roadway grade. PAR running slope 4.2%.	Yes	{FDE6A48D-AEC9-4DCF-81EE-879DC56BF7CD}
20230628	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 5%.	Yes	{911094AD-CD2C-453E-B4DB-A3A1E1956F6A}
20230629	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 4%. PAR cross slope 3%.	No	{BDB43607-D0D8-40E6-BE66-A043BC21D488}
20230630	More than 2%	4 x 4 feet or greater	Cross slope 2.3%. Matches roadway grade.	Yes	{9B2A8152-C0BC-4E74-9FEC-41ACCDFAD96C}
20230631	More than 2%	4 x 4 feet or greater	Cross slope 2.4%. Matches roadway grade. AR running slope 4%. PAR cross slope 2.4%.	Yes	{5FA73982-E84F-4F6C-A34A-70322C7BC526}
20230632	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{7D4FDFBA-7A60-4D14-AB33-1919EAF78287}
20230633	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A7AD89D5-C18F-4872-BB8C-04E17CA2E843}
20230634	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{0FC0AA3A-6726-4F56-90E9-81D8673EC274}
20230635	More than 2%	4 x 4 feet or greater	Cross slope 2.3%. Matches roadway grade.PAR running slope 3%. PAR cross slope 4%.	Yes	{CB5777C7-54F1-4386-B980-1866B1B221D8}
20230636	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{F93867A6-4FBA-4B05-BC47-9A264515829C}
20230637	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{32E0A9DB-823C-4400-80C6-D53AE7B5E104}
20230638	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{568B2681-F53D-4F51-BC49-73D807CCDB4B}
20230639	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E73E9C65-33E5-49A4-8ACC-3737A879EC9A}
20230640	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D9450F19-E255-4A1C-8578-AEAF469259E5}
20230641	More than 2%	4 x 4 feet or greater	Cross slope 2.5%. Matches roadway grade.	Yes	{80B74F76-CEAD-4BEF-ACEA-6BE5DCCE6C9B}
20230642	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Matches roadway grade. PAR running slope 4%. PAR cross slope 4%	No	{FC97FC59-5A90-4039-820C-DE45F04E99FD}
20230643	More than 2%	4 x 4 feet or greater	Cross slope 2.4%. Matches roadway slope. PAR running slope 2.4%.	Yes	{01A352B4-351C-48F2-B5CE-FEDEC5B5545F}
20230644	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6876FBE5-2F39-4872-9A54-0FEBBCB34A73B}
20230645	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{CA68170E-49A5-4013-AF20-CF8403F8B6E5}
20230646	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 5.8%.	Yes	{14BBF925-5D78-424C-B4F4-CC12BE8E3DE0}
20230647	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 7%.	Yes	{AC5B100C-7EF1-4607-9307-FF55872E1B33}
20230648	More than 2%	4 x 4 feet or greater	Cross slope 10%. Matches roadway grade. PAR running slope 13%.	Yes	{35289821-8502-4A8B-AC5A-CE2BD8D67EE3}
20230649	More than 2%	4 x 4 feet or greater	Cross slope 8%. Matches roadway grade. PAR running slope 7.5%.	Yes	{BA1D9690-E499-436F-9DE8-A1EE0C2377EA}
20230650	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DA6D800D-CE49-41B1-882B-60612969947A}
20230651	More than 2%	<Null>	Running slope 8.8%. Cross slope 9%. Matches roadway grade. PAR running slope 9%.	No	{F1EF4A01-B34E-4FEB-BF95-603A16ABA0EA}
20230652	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{1566850D-DE9F-4291-9190-0852C67A19DB}
20230653	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%	No	{65D9CDC5-3DA1-472E-AFD1-72BC88A80C8E}
20230654	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 3%.	Yes	{B21F7880-30C3-4AD7-8218-CB7BD3C6823E}
20230655	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{BD3FE06B-249D-4627-A54E-C7543F1E37AD}
20230656	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 11%. PAR cross slope 5%	No	{41E1EEEF-021A-4DBE-A8AC-21F23403008E}
20230657	More than 2%	4 x 4 feet or greater	Cross slope 4.5%. Matches roadway grade. PAR running slope 7%.	Yes	{BD048BB0-F420-4AB2-9D12-5F5A5825D3E1}
20230658	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 6%.	Yes	{3BC95F31-ADF3-417D-A264-6EC248B77660}
20230659	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 5%. PAR cross slope 3%	No	{8C0220C8-5506-4126-8761-F22C85D7264C}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230660	More than 2%	4 x 4 feet or greater	Cross slope 7%. Matches roadway grade. PAR running slope 8%.	Yes	{82898B05-7A22-402C-B409-0768D228105D}
20230661	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{CA9D83E5-CC19-4202-A864-B88FC96797DB}
20230662	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.7%	No	{F0EE62C6-2139-4004-8E05-E58D1ED87C90}
20230663	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 5%.	Yes	{2B374A4A-9E7D-438B-8C2D-41B3A436AEED}
20230664	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Matches roadway grade. PAR running slope 4%.	Yes	{5EF95602-C8DA-4599-A0F3-4B1A22D1586B}
20230665	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 3%.	Yes	{6DF9ADA3-2C4B-4ACD-B327-CCAD88458744}
20230667	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 10%. PAR cross slope 4%.	Yes	{5FCD9A98-67CD-4A3F-A705-E0D6BEEE2DBB}
20230668	More than 2%	4 x 4 feet or greater	Cross slope 7.5%. Matches roadway grade. PAR running slope 7.8	Yes	{F37FA2FE-61E9-4FE9-B611-6F5BE9584BBE}
20230670	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{23C7DD09-D8AD-4727-8B52-6D4C87944BFA}
20230671	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.5%.	No	{40402143-D25B-4A3E-9E9C-AEDFA0DF5F17}
20230672	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{627A63A0-3E01-4F5F-BEE0-955D93AE9D55}
20230673	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 4%.	Yes	{40F2823F-302D-4626-A671-BB0521F7ADFE}
20230674	More than 2%	Less than 4 x 4 feet	Cross slope 9.8%. Matches roadway grade. Landing less than 36 inch clear space. PAR cross slope 5%. Post flashes blocking landing.	No	{1C091A70-D332-42D6-B836-1FE9BC43AA96}
20230675	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{4863592A-0AB0-42DA-892F-EC6DFA824746}
20230676	More than 2%	4 x 4 feet or greater	Cross slope 4.6%. Matches roadway grade. PAR running slope 6.6%. PAR Cross slope 3%	No	{09C56CB1-AC94-4600-AA22-B191F2D3CB0B}
20230677	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 8%. Flare panel, upheaval	No	{E8C88571-99C5-4998-ABFB-03D7E9991762}
20230678	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 3%. Matches roadway grade. PAR running slope 3%.	No	{A4CC030C-3DB8-4A2C-854E-FA54A78D0E23}
20230679	More than 2%	4 x 4 feet or greater	Cross slope 7%. Matches roadway grade. PAR running slope 6.5%. PAR cross slope 3%.	No	{C8C0745C-5690-460B-AE75-853B1863C7AB}
20230680	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 8.3%.	Yes	{CF073ED6-FBDC-422F-B2FC-E6FD35DF1756}
20230681	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 8%.	Yes	{8D4DD528-2515-4595-89D3-D709D42CA5EC}
20230682	More than 2%	4 x 4 feet or greater	Cross slope 7.3%. Matches roadway grade. PAR running slope 9%.	Yes	{F43A7C2B-7EB0-4CE1-8A8E-3F8046C09369}
20230683	More than 2%	4 x 4 feet or greater	Cross slope 8.6%. Matches roadway grade. PAR running slope 11%.	Yes	{83012AC5-A371-4680-B713-3D12ED2B345B}
20230684	More than 2%	4 x 4 feet or greater	Cross slope 9.3% Matches roadway grade. PAR running slope 11.3%.	Yes	{BFBA33C9-9958-4903-80F4-756BAED5161B}
20230685	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 5%.	Yes	{C1B2C275-3FC6-4480-A357-12A50A8DE91E}
20230686	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 5%. Minor curb lip.	No	{471134F9-2169-4517-9806-87EA7AE578B5}
20230687	More than 2%	4 x 4 feet or greater	Cross slope 9.6%. Matches roadway grade. PAR running slope 10%.	Yes	{6EF68F94-5680-4447-8E70-2056A11D5415}
20230688	More than 2%	4 x 4 feet or greater	Cross slope 8.7%. Matches roadway grade. PAR running slope 9.7%.	Yes	{E8DB100B-C6D4-493B-AE23-3EA1E5B237F3}
20230689	More than 2%	4 x 4 feet or greater	Cross slope 7.8%. Matches roadway grade. PAR running slope 10%.	Yes	{DF5D3238-590D-4762-A430-6944900E0549}
20230690	More than 2%	4 x 4 feet or greater	Cross slope 11%. Matches roadway grade. PAR running slope 10%.	Yes	{2669C127-D66D-4D5A-92CD-1A0271C71CB2}
20230691	More than 2%	4 x 4 feet or greater	Cross slope 12.7%. Matches roadway grade. PAR running slope 14%.	Yes	{B79E9455-ACF0-4192-8C1F-2AC6B04A0E4E}
20230692	More than 2%	4 x 4 feet or greater	Cross slope 8.7%. Matches roadway grade. PAR running slope 9.7%.	Yes	{0081A45C-4A36-401C-A834-03F5712423F8}
20230693	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 4.3%.	Yes	{1FDFCDE4-4F0D-461A-B783-CBFF41BF52E6}
20230694	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.5%	No	{CC6EE9BF-D036-48C0-8A3C-69EB78856DF6}
20230695	More than 2%	4 x 4 feet or greater	Cross slope 9.4%. Matches roadway grade. PAR running slope 9.3%.	Yes	{C20BD3EA-27FE-4189-9699-1936D6BE08F2}
20230696	More than 2%	4 x 4 feet or greater	Cross slope 3%. Landing slopes within 4%	No	{71E8A8A0-7C31-4AF9-B477-C03D5601599D}
20230697	Up to or equal to 2%	4 x 4 feet or greater	Monitor landing to ramp panel upheaval.	Yes	{604255DF-F1E4-414C-8C49-0AF892D6CD0E}
20230698	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 6%. PAR cross slope 6%.	No	{C6912B96-E359-4A59-8B96-090367F04116}
20230699	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D0413CDE-1E8E-4867-8C3B-C28D4F2B84CE}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230700	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 3.4%.	Yes	{877E0B37-24AD-41A0-ABE3-E32B490C8EF6}
20230701	More than 2%	4 x 4 feet or greater	Running slope 13%. Cross slope 6.4%. Matches roadway grade. PAR running slope 5.8%.	No	{B960F74F-70A9-4B41-9E90-5A99CBD94D68}
20230702	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 5.8%. Matches roadway grade. PAR running slope of 5.5%. Overgrown vegetation.	No	{FC9A5EAE-B01A-4C48-9312-1E88EA04527E}
20230703	More than 2%	Less than 4 x 4 feet	Cross slope 2.8%. PAR cross slope 2.7%. Crack forming at corner.	No	{3E041324-896A-4168-A798-BB9BE1704F2C}
20230704	Up to or equal to 2%	Less than 4 x 4 feet	Landing slopes within 2.7%.	No	{5AB5E257-1B6C-482B-8802-CB91209CE9FC}
20230705	More than 2%	4 x 4 feet or greater	Cross slope 11.5%. PAR running slope 13%.	No	{2AB91B89-C2C7-45B3-9D6E-A961FEC1C479}
20230706	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 6%. PAR running slope 8%. Overgrown vegetation.	No	{61A2817F-B50C-4953-8024-869DF0BD9140}
20230707	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 4%	No	{82DB86B8-7954-44EE-90BC-722FF21E3197}
20230708	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade.PAR cross slope 3%. Crack forming in landing	No	{91E0A6F0-6F48-4FD0-9C06-ECF7F505B058}
20230709	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 2.6%.	No	{CEA9FB89-D939-4E8A-9276-E5F53FD5DC46}
20230710	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%.	No	{5B023F3B-4168-4075-82AB-4A3DC26A07BA}
20230711	More than 2%	4 x 4 feet or greater	Cross slope 2.75%. PAR Cross slope 2.25%.	No	{8480E34A-58BF-47E3-AC48-835F3C08FA25}
20230712	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Matches roadway grade. PAR running slope 4.5%.	Yes	{43A264F6-DA04-4D8C-8DBD-60D2D34D3255}
20230713	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3.5%	No	{EF21D86F-8416-4DF9-8FE2-0373C6290B38}
20230714	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.4%	No	{4D69540F-20E5-495B-A4E4-501FCB9669A7}
20230715	Up to or equal to 2%	4 x 4 feet or greater	Landing running slope 2.25%.	No	{A3019737-5893-480B-9A47-52FC85AE9DC1}
20230716	Up to or equal to 2%	4 x 4 feet or greater	Landing running slope 2.25%.	No	{874BB676-FD50-4D8F-A0F8-82FE500D4424}
20230717	More than 2%	4 x 4 feet or greater	Cross slope 2.4%. PAR cross slope 2.4%.	No	{B0D1F3E5-1B9C-4CFA-A819-75F60E674928}
20230718	Up to or equal to 2%	4 x 4 feet or greater	Cross slope 4.8%. Matches roadway grade. PAR running slope 4.4%.	Yes	{8CDC1D41-2796-4AAA-B519-4DA6556B5D67}
20230719	Up to or equal to 2%	4 x 4 feet or greater	Cross slope 5.5%. Matches roadway grade. PAR running slope 4.35%.PAR cross slope 3.1%.	No	{48AE19-98BA-40F5-9266-8D52F12FCB0D}
20230720	More than 2%	4 x 4 feet or greater	Grate in front of ramp. Cross slope 3%. Matches roadway grade. PAR running slope 3.6%. PAR cross slope 4%.	No	{E078215F-B708-4021-848E-607E0BD85735}
20230721	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade.PAR running slope 4%.	Yes	{378002D7-CE30-4D9F-AF5E-269B25305F3B}
20230722	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{BB0BE03C-8DF6-4F22-8428-339BB7AF928C}
20230723	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{21A876CC-7951-4BC9-95A5-81BB62DF8CFC}
20230724	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{7BA5FB5B-909F-4203-98B5-3BBF5D3B250A}
20230725	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.8%	No	{C0228133-174E-4305-A738-C07627B31728}
20230726	More than 2%	4 x 4 feet or greater	Cross slope 3.7%. Matches roadway grade. PAR running slope 5%.	Yes	{C5991263-11B2-44EE-90AF-895026173A8A}
20230727	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10.5%. PAR cross slope 2.8%.	No	{1E510F0D-3E77-4C36-A0DF-081A348F36F6}
20230728	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.8%	No	{E9E333D0-A74A-404A-9736-90A038FBDC80}
20230729	More than 2%	4 x 4 feet or greater	Cross slope 3.6%. Matches roadway grade.PAR running slope 3.4%. PAR cross slope 3.2%.	No	{B6D4D242-4AE4-454C-96C2-2345DCAA9284}
20230730	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 4.5%. PAR cross slope 2.5%.	No	{041AF9A4-BF33-403B-8133-83A1E3705789}
20230731	More than 2%	4 x 4 feet or greater	Running slope 11%. Cross slope 3.3%. Matches roadway grade. PAR running slope 3.3%.	No	{6C7BA379-8600-44D6-A615-6BC744115174}
20230732	More than 2%	4 x 4 feet or greater	Cross slope 2.5%. PAR running slope 3%. PAR cross slope 2.7%.	No	{A1047261-06CC-438D-A719-10D18401BF64}
20230733	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{3C83564F-6BD8-4A92-92FF-87E79FBD0170}
20230734	More than 2%	4 x 4 feet or greater	Cross slope 7%. Matches roadway grade. PAR running slope 9%.	Yes	{8DE1920B-54B8-4F44-9BA6-4AF4E12BBFFA}
20230735	More than 2%	4 x 4 feet or greater	Running slope 11%. Cross slope 4%. PAR running slope 3.8%.	No	{A3961C80-58F4-4CB1-9EE5-948C0C693A3D}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230736	More than 2%	4 x 4 feet or greater	Cross slope 3%. Landing slopes within 2.5%. Deterioration between DWS and curb transition.	No	{DB57D63D-A2F0-496D-81AA-C370129E5285}
20230737	More than 2%	Less than 4 x 4 feet	Running slope 11%. Cross slope 3%. Matches roadway grade.	No	{0AAF7D10-30F4-4497-99AA-3F7C1B4ECFAE}
20230738	Up to or equal to 2%	4 x 4 feet or greater	Utility access in front of ramp	No	{B6407BAE-2AB9-4774-AB20-9AF94A763D9D}
20230739	More than 2%	4 x 4 feet or greater	Cross slope 11.8%. Matches roadway grade. PAR running slope 12.4%	No	{686E4459-39EB-4457-B15F-62CB1106F2E9}
20230740	More than 2%	Less than 4 x 4 feet	Cross slope 15%. Matches roadway grade. PAR running slope 17%. PAR cross slope 5%.	No	{17E22EF4-24A2-4366-891F-28C71BB2DEF2}
20230741	More than 2%	Less than 4 x 4 feet	Running slope 10%. Cross slope 15%. Matches roadway grade. PAR running slope 17%. PAR cross slope 5%.	No	{1C811EA1-E5EA-41DE-B622-9A9BFD148DC7}
20230742	More than 2%	Less than 4 x 4 feet	Cross slope 12%. Matches roadway grade. PAR running slope 15%. PAR cross slope 4%	No	{2F1296D6-2297-4918-80AE-CBF583C2C2EE}
20230743	More than 2%	4 x 4 feet or greater	Cross slope 6.4%. Matches roadway grade. PAR running slope 7.4%. Crack forming in ramp.	No	{5C37A217-CBD6-4C8B-AFAE-66F6BA7D5698}
20230744	More than 2%	4 x 4 feet or greater	Running slope 11%. Cross slope 9%. Matches roadway grade. PAR running slope 11%.	No	{BD820FEF-07F4-4E38-BC79-CCB2E1627A89}
20230745	Up to or equal to 2%	4 x 4 feet or greater	Monitor 1 inch gap between front of DWS and curb transition.	No	{FDF21900-646A-4E71-99B3-ACF9A7E2F30A}
20230746	More than 2%	4 x 4 feet or greater	Cross slope 4.3%. Landing slopes 5.5%.	No	{A98BA5B5-0DBB-4878-96CD-C31FE281FEF7}
20230747	More than 2%	Less than 4 x 4 feet	Cross slope 4.5%. Matches roadway grade. PAR running slope 4.8%. PAR cross slope 8.3%.	No	{0703D965-C98A-4B0E-A7E5-0E2045DA0609}
20230748	Up to or equal to 2%	4 x 4 feet or greater	Monitor half inch gap forming between landing and curb panels	Yes	{3BB5C5BD-7490-42FA-88EE-2E7252D6E80D}
20230749	Up to or equal to 2%	4 x 4 feet or greater	Monitor half inch gap between landing and curb panels..	Yes	{D965F050-1F22-46DF-B99D-56B87E1FC839}
20230750	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.3%. Monitor gaps between landing panel and curb. Monitor half inch gap between front of DWS and curb transition.	No	{1CEAD705-9FB4-432E-944B-76D32596FC22}
20230751	More than 2%	4 x 4 feet or greater	Realign to match new receiving ramp between driveways. Cross slope 12%. Matches roadway grade. PAR running slope 11.8%. Crack forming within the ramp.	No	{BE8A4296-9A3D-4886-A537-63AAAC7770EE}
20230752	<Null>	<Null>	No receiving ramp. Align between driveways	No	{AE318551-D581-4902-9168-FF9CD607D429}
20230753	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{41DD4BD5-2F45-43B1-B831-7C1CBA5F62EF}
20230754	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 3%.	Yes	{D01E3E4A-D7BE-4EDA-8AC9-C387837BB59E}
20230755	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 6%. PAR cross slope 3.4%.	No	{E2192B54-B8C6-4C6C-B8C4-14202E5C6F2F}
20230756	Up to or equal to 2%	4 x 4 feet or greater	Crack in curb ramp flare.	No	{96E1096A-5A68-49F5-A033-278CC2624F36}
20230757	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{33AF7C27-D1A5-4D17-BBC8-F1CB12A78C73}
20230758	More than 2%	4 x 4 feet or greater	Cross slope 4.5%. Matches roadway grade. PAR running slope 5%. Monitor half inch gap between landing and curb ramp panels.	Yes	{EA0974AC-E877-437C-B00D-FC99D2991B47}
20230761	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{977B1EEC-18AD-4988-84E3-91BD1A01DA0E}
20230762	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A98EC0D1-24D4-4966-A374-9F00E8876B39}
20230763	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A4AB7CA9-31EE-46B9-AC1E-C06B10CD5E15}
20230764	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9999A169-663E-4B0B-B775-1BD596D74AAD}
20230765	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{2A304A08-6954-4302-B53F-B5868FD24D5E}
20230766	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{529F5AA7-23C8-4BC4-91F1-4AC9F71D7932}
20230767	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AD8A5C5B-141F-46BD-ADB9-AAD266364D8A}
20230768	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{5D771211-01F0-42B1-BB9B-063AA352D126}
20230769	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D7C2009C-88AC-4DD3-A090-D21E64A3D229}
20230770	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{88AB24DC-507C-4676-A453-FA651CC9BCF1}
20230777	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E190D522-AD3D-4BE8-A0A8-6A4779F910A6}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230778	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{0300F2F9-C8F5-4DC7-A37E-6010837EA15B}
20230779	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{68F5E570-37C3-47BA-8722-F4249B84B58A}
20230780	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{92D085A3-A7EF-4999-BC1B-BC9F4F9E78F1}
20230760	More than 2%	4 x 4 feet or greater	Cross slope 6.8%. Matches roadway grade	Yes	{4719F711-1711-4CC8-AE18-CEC2022D553C}
20230759	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6C49F7C4-C824-43AF-B28D-FEDC828582A3}
20230969	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{31D10B7B-7675-4298-99DE-A9C8D1FE960B}
20230968	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{8AD6B637-1358-45C5-A057-9989C3989592}
20231354	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{546CF9ED-B36C-48E4-B2FB-2781D68E2AA5}
20231368	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{828829EB-4A5F-43D6-ADE3-E8174B6D0FDB}
20231367	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{408EAF4D-3544-416F-B0EC-946CD675F93D}
20231373	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade.	Yes	{725CA1E3-BE09-412A-A9AC-98FD323003C1}
20231372	Up to or equal to 2%	4 x 4 feet or greater	Monitor cement between DWS and curb transition.	Yes	{D086948D-F704-43D7-A085-C857CB0EAB31}
20231380	Up to or equal to 2%	4 x 4 feet or greater	Monitor cement between and in front of DWS at curb transition.	Yes	{0B1EFD52-5434-48B6-A936-1D40D1B89404}
20230669	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{86469D5C-D110-4F43-B0C4-47A73CEAB016}
20231381	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D7834749-9ACE-4E3A-B9AE-3635C81B8FF8}
20230793	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AA32E256-88AD-415E-B760-3AF8A0BEF1A0}
20230794	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{29B33BED-A5A7-4FEF-8D84-B923F86F4B54}
20230795	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6DD93462-7CD7-499E-879C-03386C827D0D}
20230796	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{2D492C5B-88A1-42C3-8022-1D6B8AA33982}
20230797	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{3C729393-0F49-4F41-9FCF-365CA817B2BA}
20230798	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{565FD03A-0705-4E48-9585-7108BEA790D5}
20230799	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A6DBDEAF-0820-4482-B359-F03DE1528D17}
20230800	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{C3D8C45A-4151-4A20-ACA9-3FCAE66A49CA}
20230801	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A96AD501-1BF2-4338-BC6C-304041F4F399}
20230802	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{CC8D88C1-35C6-416A-AA45-C5922E450D22}
20230803	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade.	Yes	{4C55A3FF-BC3A-4AE5-9ECC-034F0C529BB5}
20230804	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DB4345C2-E617-49A1-A494-449303118E2E}
20230805	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B4CC3DB1-2826-4EF6-960D-B50F4A1F378C}
20230806	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{1BE990E5-0012-4A16-AB67-0C976698EA58}
20230807	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AAA7096A-DD26-4643-B02F-4346C7D582C7}
20230808	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{EA4F1557-90C1-4DEC-B15D-449F836FA82C}
20230809	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{19FD5EA4-A0BC-42E6-90EA-01696FD56FEF}
20230810	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A5118D89-432C-4D69-A22C-131710396EEA}
20230811	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{201A6580-647E-47A5-85C6-D7C6FAAF583B}
20230812	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{70EC698D-B589-40C2-8728-E24E39B0302C}
20230813	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{80E828F3-0C63-461E-B83F-6F73A220EB94}
20230814	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{1613467F-2ED0-4DE6-9851-91999965BBF2}
20230815	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{B5278D7D-B33D-4988-B82A-41004F7CD7F1}
20230816	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{F9FBB8C8-3212-4D63-A093-D261561AAAE1}
20230817	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade.	Yes	{7D56E7EF-B91D-4DF9-B403-B4A5B5DE0E5D}
20230818	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade.	Yes	{EC073904-7D02-4DBC-8F34-2921630F68E9}
20230819	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.3%	No	{CB36D81C-8DC2-4D7B-A22C-45C7B7D88923}
20230820	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.4%. Deteriorating cement between DWS and curb transition.	No	{7A841951-D97B-47FD-9B13-5F156D1F3438}
20230821	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.4%.	No	{16BB8FB1-6963-49E2-BCBD-52386CC7B57B}
20230822	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{630C9370-B915-4A6B-9D7F-9D1D05F693C4}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230823	More than 2%	Less than 4 x 4 feet	Cross slope 6%. Matches roadway grade. PAR running slope 6.3%. PAR cross slope 2.4%.	No	{A274D8B8-7961-407E-9759-AA084785F85E}
20230824	Up to or equal to 2%	4 x 4 feet or greater	Cross slope 5.5%. Matches roadway grade. PAR running slope 6.5%. PAR cross slope 2.5%.	No	{9144DAE8-925B-451A-A125-659ECEFO4A4B}
20230825	More than 2%	4 x 4 feet or greater	Cross slope 3.3%. Matches roadway grade. PAR running slope 3.4%.	Yes	{0245DD31-3CF3-42E7-A29B-8B234F042ED8}
20230826	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D25F0019-3A77-4A01-B04D-BF0AA8A07BE2}
20230827	Up to or equal to 2%	Less than 4 x 4 feet	Landing slopes within 2.6%	No	{EEE92BFF-94FC-469C-8C92-92902A85B7B4}
20230828	More than 2%	Less than 4 x 4 feet	Cross slope 4%. PAR running slope 4%. PAR cross slope 2.6%.	No	{89F7E92C-7194-47CE-BDCA-28098AC78FDC}
20230829	More than 2%	Less than 4 x 4 feet	Cross slope 4.5%. Matches roadway grade. PAR running slope 7%. PAR cross slope 3.6%.	No	{B74BF362-7E31-4466-9D7A-F2A3B891B448}
20230830	More than 2%	4 x 4 feet or greater	Cross slope 6.7%. Matches roadway grade. PAR running slope 7.6%. Cracks in flare and PAR. Minor curb lip.	No	{BE4AF2E9-B77E-45E2-89FC-4C9ED9FFAE88}
20230831	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. PAR running slope 6.5%. DWS not aligned with approach.	No	{BDEB341F-FC8F-47C3-BD88-725B808E3C66}
20230832	More than 2%	4 x 4 feet or greater	Cross slope 2.5%. Landing slopes 3%.	No	{69F2E4B8-41E5-417A-97BE-6457D8FE3B51}
20230833	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 9%. PAR cross slope 3%.	No	{D628A6B1-D562-4A1A-BF44-F889A3668697}
20230836	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 6.5%.	Yes	{6773D650-8B49-4D86-88B3-B4E6CB79B6A1}
20230837	More than 2%	Less than 4 x 4 feet	Cross slope 6.5%. Matches roadway grade. PAR running slope 11%. PAR cross slope 4%.	No	{8DF9CAE8-5BF2-4E13-A5C8-1EA530205C1E}
20230838	More than 2%	4 x 4 feet or greater	Cross slope 6.5%. Matches roadway grade. PAR running slope 9%. PAR cross slope 4.5%.	Yes	{4C588B5E-1970-42F6-8E47-EA1FE310E5EA}
20230839	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 3%	No	{8F239634-AD17-477D-8ABD-D7A335841AF1}
20230840	Up to or equal to 2%	4 x 4 feet or greater	Running slope 12%. Landing slopes within 2.8%.	No	{153D1E57-A932-4654-9A7F-BF2D43DC4D78}
20230841	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{C3C9E7BC-C3A5-4491-840E-A3C80DCFC551}
20230842	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.7%	No	{BBE4FDB7-557A-4713-941F-4AFF6FA89D15}
20230843	More than 2%	Less than 4 x 4 feet	Cross slope 6%. Matches roadway grade. PAR running slope 8%.	No	{7BF66334-4286-41A7-813C-0EBA3197C5C4}
20230844	More than 2%	Less than 4 x 4 feet	Cross slope 2.8%. PAR running slope 3.8%. PAR cross slope 2.8%.	No	{6E3A8858-A086-41A8-BF47-9C2AEE2CE12A}
20230845	Up to or equal to 2%	4 x 4 feet or greater	Cross slope 3%. Landing slopes within 2.5	No	{8E96FC34-F129-4239-982F-7130A9567547}
20230846	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip.	No	{87E9FFFD-1623-4A82-A3C4-9FECF578AB76}
20230847	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{2D75E553-F021-4C3D-B3AE-82E46DA8734F}
20230850	<Null>	Less than 4 x 4 feet	Serves inaccessible route. Consider DWS and landing	No	{72514F27-E8A2-4FA4-BD88-2A19FE9839CE}
20230851	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.7%	No	{97183741-0D42-430B-B6CA-BFFFFEF82255}
20230666	More than 2%	4 x 4 feet or greater	Running slope 10.5%. Cross slope 4.5%. Matches roadway grade. PAR running slope 6.5%.	No	{7935367A-2C13-4579-803A-F22BD98818C6}
20230852	More than 2%	4 x 4 feet or greater	Running slope 13%. Cross slope 8%. Matches roadway grade. PAR running slope 10%.	No	{E9E50E36-EC45-45FA-9E72-8C4CBFD37771}
20230853	More than 2%	4 x 4 feet or greater	Cross slope 10%. Matches roadway grade. PAR running slope 12%.	Yes	{1E07F5C5-0524-447B-81AD-CBF40ACB9E62}
20231369	More than 2%	4 x 4 feet or greater	Cross slope 4.7%. Matches roadway grade. PAR running slope 6%. PAR cross slope 3.6%.	No	{A3BB33D6-D6FB-43DB-BB48-0E1CE4F60AFC}
20230855	More than 2%	4 x 4 feet or greater	Cross slope 12%. Matches roadway grade. PAR running slope 13%. Monitor DWS to curb height difference.	No	{FF4E536F-9283-4DF4-9579-3389B8EE0217}
20230856	More than 2%	4 x 4 feet or greater	Cross slope 11%. Matches roadway grade. PAR running slope 10%.	Yes	{0907206C-21D8-495E-87D1-4061AC5F0CD2}
20230857	More than 2%	4 x 4 feet or greater	Cross slope 4.8%. Matches roadway grade. PAR running slope 4.5%. Monitor vegetation.	Yes	{BDFFE91A-87EF-4E5B-B492-51FE01BB12B1}
20230858	More than 2%	4 x 4 feet or greater	Cross slope 3.4%. Matches roadway grade. PAR running slope 5%.	Yes	{43AE6CD0-E627-407B-8AF4-4871EA6E4AAD}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230859	More than 2%	4 x 4 feet or greater	Running slope 9.3%. Cross slope 4.8%. Matches roadway grade. PAR running slope 5.7%.	No	{BA5AD24F-40D1-49E1-9A32-18FB4C87C212}
20230860	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 6%.	Yes	{3350D6CC-3A52-4640-8168-33060ADDC702}
20230861	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 3%	No	{C2965F32-474A-44E5-89BA-806D09D94E94}
20230862	More than 2%	Less than 4 x 4 feet	Cross slope 10%. Matches roadway grade. PAR running slope 11%.	No	{0B15DEA6-A2CB-40D9-978E-F99FEAAD8435}
20230863	Up to or equal to 2%	Less than 4 x 4 feet	Landing slopes within 3%	No	{03170C4E-AB5E-4693-83C2-FC01C4FEEDD9}
20230864	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 3.5%.	Yes	{6D080799-2CC1-46B7-95C7-8F43698E74DA}
20230865	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 9%. PAR cross slope 2.7%.	No	{37E4666C-77D2-4E49-83E3-4DC0C6BC02B3}
20230866	More than 2%	4 x 4 feet or greater	Running slope 9.5%. Cross slope 5.5%. Matches roadway grade. PAR running slope 5%.	No	{8201DB36-761A-4011-88CD-B43783267216}
20230867	More than 2%	4 x 4 feet or greater	Cross slope 11.5%. Matches roadway grade. PAR running slope 12%.	Yes	{508DAED4-7949-473B-9482-57D6DC062975}
20230868	More than 2%	Less than 4 x 4 feet	Cross slope 12.5%. Matches roadway grade. PAR running slope 13%.	No	{9D82C47C-D387-4084-B857-87DEE3C903C8}
20230869	More than 2%	Less than 4 x 4 feet	Cross slope 5%. Matches roadway grade. PAR running slope 8%. PAR cross slope 2.7%. Overgrown vegetation.	No	{0DDCDE60-74B3-4003-B405-8592E07599A6}
20230870	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matched roadway grade. PAR running slope 5.3%. PAR cross slope 3%.	No	{C28BEAFB-3D2C-4924-BB47-096AA1F4F4B6}
20230871	More than 2%	4 x 4 feet or greater	Running slope 9%. Cross slope 7%. PAR running slope 12.5%. PAR cross slope 7%.	No	{C32FEC93-E062-4FA5-AE1D-29FFB3AE5E2B}
20230872	More than 2%	Less than 4 x 4 feet	Cross slope 5%. Matches roadway grade. PAR running slope 14%. PAR cross slope 3%.	No	{154A837D-C9ED-4BA0-82F8-492386D72660}
20230873	Up to or equal to 2%	Less than 4 x 4 feet	Landing slopes within 2.7%	No	{B0EBA5E4-1958-4EC4-9280-066B4BAB2D4E}
20230874	More than 2%	4 x 4 feet or greater	Cross slope 9%. Matches roadway grade. PAR running slope 9%. PAR cross slope 5%.	No	{89FC11FE-46BC-42C7-8FCE-5285C8618CBE}
20230875	More than 2%	Less than 4 x 4 feet	Cross slope 4%. Matches roadway grade. PAR running slope 7%. PAR cross slope 4%.	No	{BDDDB1B2F-2C55-4F28-B87C-DD03023FBF9A}
20230876	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 4.7%. PAR cross slope 3%.	No	{ED865108-3EA0-46AF-AE13-8999A1AB1559}
20230877	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%	No	{94C05BF2-8B27-46A3-8639-822D0F6F0073}
20230878	Up to or equal to 2%	Less than 4 x 4 feet	No Landing	No	{C1B7A735-5011-40F4-B218-F4185F31EA60}
20230879	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{ACB61994-79DD-4A59-819B-F3136A90B6EF}
20230880	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{FE5F0334-356C-4756-A773-93DCE09E3574}
20230881	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. PAR cross slope 3%.	No	{16163023-5D4C-4C72-A012-A14FA43DF481}
20230882	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{E1C6F489-D314-4AB3-BB39-1A68B5B517E0}
20230883	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{05939E7D-683D-45E7-8F1F-BD4FC57E6B28}
20230884	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{38235BDD-CC4D-498B-B6D5-24E6EE1C77AB}
20230885	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 3%	No	{389130FA-D94A-4699-9996-338708B41751}
20230886	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2%	No	{C431450C-393E-4551-9D95-440E7288AFBB}
20230887	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{0E6DA033-4C45-4C0A-B34A-59140238B688}
20230888	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. 1 inch gap and elevation change between landing and ramp.	No	{29A4F7B6-E44E-4634-8133-14F12833C456}
20230889	More than 2%	4 x 4 feet or greater	Running slope 9%. Cross slope 3.5%. PAR running slope 3%.	No	{67D6A06F-93D7-4BCA-B347-FCC45E1B2C24}
20230890	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 6%.	No	{F53786F4-F829-4F85-B490-870E40A19486}
20230891	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 6%. Matches roadway grade. PAR running slope 6.5%.	No	{DD47B68D-5943-4710-8184-69E9A72232E8}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230892	More than 2%	4 x 4 feet or greater	Cross slope 12%. PAR running slope 12.5%. 2 inch panel upheaval nearby with crack in panel.	No	{5B0BD67B-EC07-405F-A777-1A8A112DA296}
20230893	<Null>	<Null>	No receiving ramp at intersection	No	{8A2FBB5D-6D8D-4D8F-A814-B1AFF75CA6CA}
20230894	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 3%. PAR running slope 7%.	No	{75D271B6-4D23-4448-B419-9C8FAA92AD42}
20230895	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 7%. Curb lip.	No	{CDC0FB22-EC00-41FD-832E-9F6034F8080F}
20230896	More than 2%	4 x 4 feet or greater	Cross slope 5%. PAR running slope 7.5%. PAR cross slope 2.5%.	No	{0BF76512-59A8-4813-83CD-CB2C1C97F15F}
20230897	<Null>	<Null>	No receiving ramp at intersection	No	{AF0430BE-AAF6-43B4-B4B8-4B0C9B60A6A3}
20230898	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{65E35533-CF76-4736-93A3-14869CA51D1F}
20230899	<Null>	<Null>	No receiving ramp at intersection	No	{E49126B2-E424-401F-8715-38461F6896BC}
20230900	More than 2%	4 x 4 feet or greater	Cross slope 6%. PAR running slope 7%.	No	{F06B9473-B659-4BEC-9B10-1588139AC6CC}
20230901	More than 2%	Less than 4 x 4 feet	Cross slope 6%. PAR running slope 6%. PAR cross slope 2.5%.	No	{6DC7CE2E-80DD-4FE0-8D4F-BC60370A7227}
20230902	<Null>	<Null>	No receiving ramp at intersection	No	{ED8CA3D8-5512-4A50-8F56-950608D9B4EA}
20230903	More than 2%	4 x 4 feet or greater	Running slope 15%. Cross slope 8%. PAR running slope 11%.	No	{20263045-EFD7-490F-B421-EB8C27059AED}
20230904	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 6.5%.	No	{DB780B64-9E65-44C8-AE60-A70EA8F6B5DD}
20230905	More than 2%	Less than 4 x 4 feet	Running slope 11%. Cross slope 15%. PAR running slope 16.5%.	No	{B0D3F0BB-BB32-45E4-B3DB-89743D5427A3}
20230906	More than 2%	4 x 4 feet or greater	Cross slope 9%. PAR running slope 11%. PAR cross slope 6%.	No	{7E1684F0-2204-4428-B452-31A890352D5E}
20230907	More than 2%	4 x 4 feet or greater	Cross slope 6%. PAR running slope 9%. PAR cross slope 4.5%.	No	{27BBC512-C13A-447A-9459-679AD5D02325}
20230908	More than 2%	Less than 4 x 4 feet	Running slope 12%. Cross slope 13%. PAR running slope 11%. PAR cross slope 19%.	No	{E5CA2C59-0A48-4BA0-AEAA-F7861AA40695}
20230909	More than 2%	Less than 4 x 4 feet	Running slope 9%. Cross slope 9%. PAR running slope 9%. PAR cross slope 15%.	No	{67E6F518-D460-46D3-8BD6-AD2C0A6D429F}
20230910	More than 2%	Less than 4 x 4 feet	Cross slope 7%. PAR running slope 9.5%. PAR cross slope 4%.	No	{ECA4BE7C-A18E-41E5-983B-FEEE94A7968C}
20230911	More than 2%	Less than 4 x 4 feet	Cross slope 8%. PAR running slope 12%. PAR cross slope 6%.	No	{F31F826D-D774-4719-8090-3F7320A27B63}
20230912	More than 2%	4 x 4 feet or greater	Cross slope 3%. PAR running slope 9%. PAR cross slope 2.5%.	No	{699797A7-39FF-46B7-8A43-63F4C3D2CBD1}
20230913	More than 2%	Less than 4 x 4 feet	Cross slope 5.6%. PAR running slope 6.5%. PAR cross slope 7%.	No	{ECC1898B-1A60-45C6-8460-E67D7B1FA71B}
20230916	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{1FDB5F54-FC5E-482E-A4E7-6DCBC4E2948A}
20230917	More than 2%	Less than 4 x 4 feet	Cross slope 6%. PAR running slope 9%. PAR cross slope 2.5%.	No	{E71DB6D6-EC53-4D99-9B10-22BD29CE2F1A}
20230918	More than 2%	Less than 4 x 4 feet	Landing slopes within 3%	No	{53FD61BE-FB46-4749-9A14-5DE8AF350764}
20230919	Up to or equal to 2%	Less than 4 x 4 feet	Running slope 10%. Landing slopes within 3%.	No	{6E2BD83A-D878-4F5F-89F8-7A4D491835BE}
20230920	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%	No	{43477E17-8510-433C-ABA7-14BADD5F9D8A}
20230921	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 3%.	No	{03D163DA-65BF-4E84-97E8-355A5C24C15C}
20230922	Up to or equal to 2%	Less than 4 x 4 feet	Running slope 11%. PAR cross slope 2.7%	No	{EDBDF287-C07A-4A05-83E8-08E7618CA12C}
20230923	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{25BC79CF-8EAE-4655-8E1B-57426CB56646}
20230924	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 3%	No	{B91BF07D-9EFE-4C9A-810C-9A968F1FAAD0}
20230925	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 4%	No	{F02DECFF-D5B0-4779-A8A3-C40A68516251}
20230926	Up to or equal to 2%	4 x 4 feet or greater	Cross slope 3.5%. PAR running slope 4%	No	{F35AA40B-131A-4FEC-A7DF-183CEF3F3403}
20230927	More than 2%	4 x 4 feet or greater	Cross slope 4.7%. PAR running slope 7%. PAR cross slope 2.5%. More than 1 inch side ramp panel upheaval. Side ramp running slope for 12%.	No	{CD859024-76D8-4E5A-BC47-05E5DD359FB6}
20230928	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 3%	No	{6FCBA019-3126-41EF-A264-32592E435515}
20230929	More than 2%	Less than 4 x 4 feet	Cross slope 8%. PAR running slope 9.5%.	No	{2E451F48-E333-486C-B8CE-0A5DC38F6819}
20230930	More than 2%	4 x 4 feet or greater	Cross slope 6%. PAR running slope 6.7%.	No	{46860418-6A5C-43D3-95C5-33ABDF8D8D62}
20230931	More than 2%	4 x 4 feet or greater	Cross slope 7.5%. PAR running slope 8.5%.	No	{C6D7D58F-4783-45CA-A850-A5A3437E32C5}
20230932	Up to or equal to 2%	Less than 4 x 4 feet	Landing slopes within 2%	No	{590B9B99-A6C7-456F-8068-2F0131615584}
20230933	More than 2%	4 x 4 feet or greater	Running slope 9.5%. Cross slope 5%. Landing within PAR. PAR running slope 8.5%. PAR cross slope 4%.	No	{32585B23-340E-47D0-8E7C-B066E295E307}
20230934	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. PAR running slope 8.5%. PAR cross slope 4%.	No	{A14828BA-53ED-440C-8599-FF8F553A71BC}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230935	More than 2%	Less than 4 x 4 feet	Cross slope 5.8%. PAR running slope 7.4%. PAR cross slope 3%. 1 inch curb ramp panel upheaval.	No	{F7CA41C3-64EF-4DBE-915B-7BEA4BA34A45}
20230936	More than 2%	Less than 4 x 4 feet	Running slope 9.5%. Cross slope 6%. PAR running slope 8%. PAR cross slope 4%.	No	{0F579B85-CF39-4201-B9B4-EF08DC18BC0D}
20230937	Up to or equal to 2%	Less than 4 x 4 feet	Cross slope 5.5%. PAR running slope 6%. Curb lip.	No	{3EFFE9FA-2E7B-44B8-A54C-2CC6EE5DDBC3}
20230938	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.5%	No	{D5B9192F-7003-4405-A76E-A6ED508D3865}
20230939	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 3%	No	{A2BA2813-640A-4932-9998-7A23773C9689}
20230940	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 3.7%. Minor curb lip.	No	{867CB943-252E-4A6D-AA3D-AD77D9F2838D}
20230941	More than 2%	4 x 4 feet or greater	Cross slope 2.7%. Minor curb lip.	No	{1871A2DD-75E5-4E51-88C5-7A736E091A81}
20230943	<Null>	<Null>	No receiving ramp	No	{BF688118-D793-40F9-BC78-91C2F011D89F}
20230942	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip	No	{1267969A-7C17-445C-8A18-24F38757533F}
20230944	Up to or equal to 2%	4 x 4 feet or greater	DWS and ramp offset from landing alignment	No	{6C16ED29-9AF4-4CE6-90EA-9AF9C7CC9005}
20230945	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 4%. PAR cross slope 2.7%.	No	{1A9D4B1C-F6C5-4214-A0B4-3474CABF58E3}
20230946	More than 2%	Less than 4 x 4 feet	Cross slope 2.7%. PAR running slope 6.4%.	No	{6913B9D7-E0A9-446C-BD2A-A7B30709E2A9}
20230947	More than 2%	4 x 4 feet or greater	Cross slope 7%. PAR running slope 7%.	No	{D782F42D-EF78-41DB-AE54-0B1E93350ACA}
20230948	More than 2%	Less than 4 x 4 feet	Cross slope 7%. PAR running slope 11%.	No	{1A538869-8D55-4AB5-8032-84784B71E6CF}
20230949	More than 2%	Less than 4 x 4 feet	Cross slope 4%.	No	{256B5712-4CC8-4C89-BBB8-CE44742ABE07}
20230950	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{94838817-7AAA-4FDE-8FCA-5E3AA325760A}
20230951	More than 2%	Less than 4 x 4 feet	Cross slope 3%. Landing slopes within 2.5%.	No	{F4C32D9F-8156-43CB-AD32-31E83E6CE33B}
20230952	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 3.5%.	No	{6AFE765F-1FB0-4A41-A054-8E48A67485CB}
20230953	More than 2%	4 x 4 feet or greater	Cross slope 3%.	No	{A54B47AA-BCF5-472B-A14F-E170B7E9D97C}
20230954	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 3%	No	{D9CECF86-6172-4256-BCC0-2D501C44A4D6}
20230955	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{AA2D1662-7476-484F-89F0-201E069702D3}
20230956	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.7%	No	{111BC450-F935-4D16-8A89-3169E85C61F4}
20230957	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 3.2%.	No	{3A55CF03-4C39-4A65-B07F-EE0A8A7A3A44}
20230958	More than 2%	Less than 4 x 4 feet	Running slope 9%. Cross slope 2.7%. Landing slopes within 6%.	No	{2AE51175-5DCB-4AFB-92EC-202514CBDFB0}
20230959	Up to or equal to 2%	4 x 4 feet or greater	Monitor gaps between flare and curb transition	No	{78B7145F-CD95-4CAA-8DDD-3F5E0595E666}
20230960	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{82308716-B368-4105-B816-7A36F3B3A3C9}
20230961	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{4E98DD22-7981-4648-8717-AE7F21681768}
20230962	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{926B4A98-6CB6-4B47-A626-F78B07CAA29B}
20230963	More than 2%	4 x 4 feet or greater	Cross slope 2.5%.	No	{E1474747-1419-49C7-A190-638D3366673E}
20230964	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{73208D0C-D86E-42BA-9286-AE1F75D19599}
20230965	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 4.4%	No	{C86869E3-55DB-4AA8-9A62-0C838C9B0BCE}
20230966	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. PAR two ramp panel vertical discontinuity.	No	{C7B15679-F978-4443-AD86-31300D1984E1}
20230967	Up to or equal to 2%	4 x 4 feet or greater	Half inch gap from ramp to landing	No	{626D2141-5177-4FBD-BA45-8B4AE15192DD}
20230970	Up to or equal to 2%	4 x 4 feet or greater	Monitor flare panel to PAR vertical discontinuity	No	{0FCE6BA0-3A34-481B-B407-571B12C8AC66}
20230971	Up to or equal to 2%	4 x 4 feet or greater	Monitor landing to curb and flare gaps	No	{0FDA6C6E-C3C9-48A4-AD9A-F1A56EE99DE9}
20230972	Up to or equal to 2%	4 x 4 feet or greater	Monitor landing to curb and flare gaps	No	{CC9ECE1D-5A92-4CD8-86AD-042170640CE6}
20230973	Up to or equal to 2%	4 x 4 feet or greater	Monitor Landing to curb gap	No	{8C54D047-91C9-494A-B799-ACD69D35BF46}
20230974	More than 2%	4 x 4 feet or greater	DWS painted on. Cross slope 2.7%.	No	{6DC41CD5-B78E-4904-97EB-7C0040FCA061}
20230975	Up to or equal to 2%	4 x 4 feet or greater	Landing running slope 6.5%. DWS painted on. PAR panel upheaval.	No	{404B6C72-5691-47A0-BB9F-AC04EDE67FA4}
20230976	<Null>	<Null>	<Null>	No	{B3E1244D-10C9-406E-B7FA-DB25587D73F3}
20230977	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{E9364975-64A5-4475-92E4-7D1D045E21B9}
20230978	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{FC1D2F60-5111-4A49-9F14-53D811D96C6C}
20230979	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{0C7C385E-0982-4105-B23E-6C87919302BA}
20230980	Up to or equal to 2%	Less than 4 x 4 feet	Running slope 9%. PAR cross slope 3.2%.	No	{3A06F939-EA76-42E6-ABC3-EBCE7EEFCCF2}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20230981	Up to or equal to 2%	Less than 4 x 4 feet	Landing cross slope 3%	No	{A37556D0-8162-4A85-816A-A60A408D7484}
20230982	Up to or equal to 2%	4 x 4 feet or greater	Monitor gap between landing and curb panels	No	{F10B9A05-1279-4815-B20A-D3091D64CBD8}
20230983	<Null>	<Null>	No receiving ramp at intersection	No	{B2AB8A5D-5C10-4653-AE06-EDA5688E9C8C}
20230986	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 4%.	No	{25A2D66C-5A7E-4659-BB2B-A5E1B5C5782A}
20230987	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.5%	No	{C2CF7D1B-7EC1-443C-B4E5-4038826715B1}
20230988	More than 2%	Less than 4 x 4 feet	Cross slope 6%. Matches roadway grade. PAR running slope 9%. PAR cross slope 7%.	No	{B5A7D458-D776-4A8F-8223-F19586770019}
20230990	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{5C61C930-272F-4D9C-8D3E-54A742CBE85D}
20230991	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.3%.	No	{D69A1280-A1A9-43C6-BFE6-04E64A59083C}
20230992	More than 2%	Less than 4 x 4 feet	Cross slope 5.7%. PAR running slope 9%. PAR cross slope 4%.	No	{A36AFD1C-C3D9-44E0-A774-16CD94E59948}
20230993	More than 2%	4 x 4 feet or greater	Cross slope 5%. PAR running slope 6.5%. PAR cross slope 3.5%.	No	{A1EA0F89-6178-4144-9E0A-63E0DC4B6BAD}
20230989	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 3.5%.	No	{9483C7E1-9EA1-4F8E-832F-71107DF3D046}
20230994	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{C84404ED-9169-4F6F-B06E-4E7577F5976E}
20230995	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3.5%.	No	{042FB37E-62DD-459A-A106-3A3FA925A9CC}
20230996	Up to or equal to 2%	Less than 4 x 4 feet	Landing slopes within 3.5%	No	{BC78ADBFB-E04F-40FF-82E3-E38E1584AD68}
20230997	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 3.5%. Crack forming in ramp and side panels.	No	{791529D1-B31D-491D-9BA3-146DCB74CF91}
20230998	More than 2%	Less than 4 x 4 feet	Cross slope 4%. PAR running slope 3.3%. PAR cross slope 5%.	No	{6CBE20AC-0CE0-4C17-AF5E-D8777691B154}
20230999	More than 2%	Less than 4 x 4 feet	Cross slope 3.5%. Landing slopes within 2.5%.	No	{B72552F7-1F74-4E8D-BBCF-20032AF3C28C}
20231000	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 2.7%	No	{CF0CD2B2-91A3-4855-AF85-493E68FDB0D6}
20231001	More than 2%	Less than 4 x 4 feet	Cross slope 6%. PAR running slope 8%.	No	{E821749F-81A0-4EC0-93C8-EBD94A645437}
20231002	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. PAR running slope 3%. Overgrown vegetation at curb.	No	{F3476547-72D3-49EB-8748-319E77483A21}
20231003	More than 2%	4 x 4 feet or greater	Running slope 9%. Cross slope 3%. PAR running slope 3%.	No	{9DCBA6CB-78ED-45FF-AB9E-B02039336CD4}
20231004	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3.8%.	No	{8D356E06-3744-4DBD-A566-A70BB0817BA0}
20231005	<Null>	<Null>	No receiving ramp at intersection	No	{5F2DCBB0-3D0F-490B-A585-2F1808069A95}
20231006	More than 2%	4 x 4 feet or greater	Cross slope 3%. PAR running slope 3.7%.	No	{D121F501-B161-4478-8045-0E34D84E1BE3}
20231007	More than 2%	4 x 4 feet or greater	PAR cross slope 2.6%	No	{93CE27E6-C416-4E80-A834-C8459C5E2071}
20231008	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.7%	No	{9A5A51CF-E935-4324-A6F8-A6EBE9AC2004}
20231009	<Null>	<Null>	No receiving ramp	No	{31FCB15B-1A70-4488-919D-C9C47E9B3E3E}
20231010	More than 2%	4 x 4 feet or greater	Cross slope 3%. PAR running slope 4%.	No	{4D28E178-D405-4651-99AB-415C97898D54}
20231011	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes 3.5%	No	{ED6CBB09-E66B-4242-BC90-4EDA7AD1BE3C}
20231012	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 3.3%. Landing slopes 3.3%.	No	{7DFE19B3-F9E8-4958-BEE3-6528E4A06A40}
20231013	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 3.6%.	Yes	{2135B98A-ED55-49F9-9660-8DD35EAA4616}
20231014	More than 2%	4 x 4 feet or greater	Running slope 9%. PAR running slope 3.7%. PAR cross slope 2.7%.	No	{68B134AA-8838-45CD-81A7-725EA7722BBB}
20231015	More than 2%	4 x 4 feet or greater	Cross slope 5%. PAR running slope 6%.	No	{4C806339-EA5F-4B28-812C-C829FC546610}
20231017	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.7%	No	{4B0BDDDB0-B0E3-4BFB-B5C9-B5D9CCA5BF71}
20231018	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%	No	{5CDF2394-51A6-4614-A871-63167F2B321C}
20231019	Up to or equal to 2%	4 x 4 feet or greater	Running slope 12%. Crack in curb ramp. 0.5+ inch gap between curb and landing panels	No	{E3529402-45AD-460A-9EAF-55757B22099B}
20231020	Up to or equal to 2%	4 x 4 feet or greater	Half inch gap between the curb and landing panel. Monitor flare gaps.	No	{D9A0B0F9-9637-43D7-9FD0-E74E525FA739}
20231021	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.7%. Monitor flare panel gaps.	No	{CFC56805-591F-432C-9FF0-0DAB2067D1B5}
20231022	More than 2%	4 x 4 feet or greater	Cross slope 6%. PAR running slope 6.6%. Minor curb lip.	No	{B3B3B2BE-AA8C-419E-8723-AD69B02BB21F}
20231023	More than 2%	4 x 4 feet or greater	Running slope 9.5%. Cross slope 6%. PAR running slope 7%. PAR cross slope 5%.	No	{2F42FA96-D086-4E30-AE9C-C401399B6743}
20231024	More than 2%	4 x 4 feet or greater	Cross slope 7.5%. PAR running slope 7.5%. PAR cross slope 2.7%. Monitor gaps.	No	{BF4AB174-D237-478D-BBB2-F7681F28080E}
20231025	More than 2%	4 x 4 feet or greater	Cross slope 5.5%. PAR running slope 6.5%. Monitor gaps.	No	{58463F5D-A6AA-43BE-A04D-3688F42E08A6}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231026	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 3%. PAR running slope 3%.	No	{A8A2FDB9-9F1A-4463-A669-0CBF58C0748D}
20231027	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%	No	{C1A53DA1-0593-4FFB-BC70-12CEB1F1411D}
20230609	<Null>	<Null>	No DWS for shared use path to roadway	No	{6544CD26-AFC6-4A89-BC74-1F7421289DB8}
20231028	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation	No	{447FDC6D-9BF4-4639-9AB8-583A95954723}
20231029	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 4%.	No	{1EFF929F-BB70-4E15-A379-26D8F14C91EF}
20231030	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. Landing slopes within 2.5%	No	{C4F5B3AB-CEDB-4759-8B3E-EA56B2EF1EF0}
20231031	More than 2%	4 x 4 feet or greater	Cross slope, 3.5%. PAR running slope 5%.	No	{A25065A6-3F41-42C0-B3D4-C7B14046DCFE}
20231032	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{2B6E2518-87FE-43BD-B77A-36FEA5E236E2}
20231033	More than 2%	4 x 4 feet or greater	Cross slope 2.7%. PAR running slope 2.7%. PAR cross slope 4%.	No	{071EB7A5-A352-4BB4-A1DE-B2190615398A}
20231034	<Null>	<Null>	No receiving ramp	No	{A605BA60-B49C-4F21-935C-13C31EFCC88E}
20231035	More than 2%	Less than 4 x 4 feet	Cross slope 6.5%. PAR running slope 10%. Minor curb lip.	No	{452E6D8F-038C-4CD8-A4DA-18E3DE21A75F}
20231036	More than 2%	Less than 4 x 4 feet	Cross slope 2.7%.	No	{B7644BB2-54A0-49AC-9675-E420BF5C1B91}
20231037	Up to or equal to 2%	4 x 4 feet or greater	PAR Running slope 3%.	No	{B333D870-8BA3-4274-AA78-6B6DD417B9AF}
20231038	More than 2%	4 x 4 feet or greater	Cross slope 6%. PAR running slope 8%. PAR cross slope 3%. Crack formed in Landing.	No	{5BF5C589-76C0-483F-B612-DE38470A215F}
20231039	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 5.8%. Crack formed in Landing.	No	{54646460-D7CD-4D82-836D-67E6F90F9FBA}
20231040	Up to or equal to 2%	4 x 4 feet or greater	Crack in ramp and transition. Monitor panel gaps.	No	{8F47B99A-F100-4DE5-86BD-3DA4ADE6F372}
20231041	More than 2%	Less than 4 x 4 feet	Cross slope 5.4%. PAR running slope 8%.	No	{00AE7755-16A7-4B8F-9B3B-D4D3E6790D94}
20231042	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. PAR running slope 4%. PAR cross slope 2.7%.	No	{7586206A-37F3-4BF6-94E5-44C8B5B56CF7}
20231043	More than 2%	Less than 4 x 4 feet	Cross slope 6%. PAR running slope 9%.	No	{8C908DDF-2F9F-4F66-9D91-FC40B7712F91}
20231044	More than 2%	4 x 4 feet or greater	Cross slope 4.6%. PAR running slope 5%. Monitor ramp to Landing gap.	No	{8A74D279-DA60-470A-A474-A94B7361FED2}
20231045	More than 2%	Less than 4 x 4 feet	Cross slope 3.7%. PAR running slope 3.2%.	No	{38122F1D-8470-4EB5-8F5A-4B43FB51359D}
20231046	More than 2%	Less than 4 x 4 feet	Cross slope 7.3%. PAR running slope 6.4%. PAR cross slope 3.4%	No	{ADB7662A-0DE1-4C8D-B882-F8C547E4920F}
20231047	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 2.7%.	No	{14336723-44DB-4305-8C9D-CAD176860C5B}
20231048	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{DBDD2BC9-B33F-4026-8946-7F3E0D114188}
20231049	More than 2%	Less than 4 x 4 feet	Running slope 8.7%. Cross slope 3%. PAR running slope 5.5%. Monitor gaps.	No	{C463D2FE-163A-4418-8114-22362C81F32A}
20231050	More than 2%	Less than 4 x 4 feet	Crack in flare. Running slope 9%. Cross slope 3.7%. PAR running slope 2.7%. PAR cross slope 3.2%.	No	{A17B4381-A120-4602-9B25-7477393255BB}
20231051	More than 2%	Less than 4 x 4 feet	Cross slope 6.5%. PAR running slope 6.7%. PAR cross slope 2.7%.	No	{9968F766-DAE4-426C-A22D-DE63576F02C8}
20231052	More than 2%	Less than 4 x 4 feet	Cross slope 7%. PAR running slope 8%. PAR cross slope 2.7%.	No	{9B5FDC3E-E094-4C34-B0D1-F57ED88C9C8B}
20231053	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation in a gap	Yes	{16C5EF06-7E03-44A9-B503-5F9FEFC8428B}
20231054	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 5%.	Yes	{80D1F685-D9BB-4BE0-90F3-CB618D4EB04B}
20231055	More than 2%	Less than 4 x 4 feet	Cross slope 3%. PAR running slope 6%	No	{2F1488CA-5C10-4587-97C3-A7D2AD697CC6}
20231056	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%.	No	{FBBE18DA-FBF5-48E4-9256-6DBC5E297649}
20231057	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E53C830E-C33E-4DDA-B7D3-E9AEC3D1EAF7}
20231058	More than 2%	Less than 4 x 4 feet	Running slope 13%. Cross slope 3.5%. Matches roadway grade. PAR running slope 5.5%. PAR cross slope 4.3%.	No	{28A2D586-AC3A-4911-9A11-659941792356}
20231059	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 6%.	Yes	{81519645-9899-46B5-AF72-F61204DEDBBB}
20231060	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Matches roadway grade. PAR running slope 4.5%.	Yes	{4B6E243D-6A0F-4879-A85C-9BB9270C5743}
20231061	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 4%.	Yes	{00C1D1FE-B31F-43E1-8F72-13CE59FF62B5}
20231062	More than 2%	4 x 4 feet or greater	PAR running slope 3.4%.	Yes	{B0A04B5D-901E-4B38-84F1-3740A7ACDDED}
20231063	More than 2%	Less than 4 x 4 feet	Cross slope 4%. Matches roadway grade. PAR running slope 6%. PAR cross slope 2.7%.	No	{94A9420E-27C9-4468-8D52-D4C64E939D7F}
20231064	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 5%.	Yes	{D6695D92-5688-4B95-809F-84436790F809}
20231065	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3.7%	No	{DF603294-BEF3-48A3-A425-E83D6E111808}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231066	More than 2%	Less than 4 x 4 feet	Cross slope 6%. Matches roadway grade. PAR running slope 8%. Monitor vertical discontinuity between landing and curb panels.	No	{E5FC78EC-A3C7-4B07-90A7-CDB0E7B7365B}
20231067	More than 2%	4 x 4 feet or greater	Cross slope 4.3%. Matches roadway grade. PAR running slope 5%.	Yes	{1C25D080-EC4A-463F-B7C6-CB2010E7A300}
20231068	More than 2%	4 x 4 feet or greater	Cross slope 5.5%. Matches roadway grade. PAR running slope 6%.	Yes	{4CD0117F-0679-4CB0-B8D2-8AA812A336E1}
20231069	More than 2%	4 x 4 feet or greater	Cross slope 7.7%. Matches roadway grade. PAR running slope 8%.	Yes	{E95B471E-FE39-4E27-B3C8-F87079763203}
20231070	More than 2%	4 x 4 feet or greater	Cross slope 7.4%. Matches roadway grade. PAR running slope 6%. Monitor landing to PAR vertical discontinuity.	No	{2EE360C3-0568-472C-99C1-7934CC155A79}
20231071	More than 2%	4 x 4 feet or greater	Cross slope 12%. Matches roadway grade. PAR running slope 13%.	Yes	{EBE78692-C894-4D64-B5E2-A6CC3B96A6FA}
20231072	More than 2%	4 x 4 feet or greater	Cross slope 13.5%. Matches roadway grade. PAR running slope 16.5%. PAR cross slope 10%.	No	{4F3BFC69-3D6B-40A1-BBE1-9C83849E8A4C}
20231073	More than 2%	4 x 4 feet or greater	Cross slope 17%. Matches roadway grade. PAR running slope 19%.	No	{62C47351-2901-4AC7-8CF2-26E7C1E0F699}
20231074	More than 2%	4 x 4 feet or greater	Cross slope 18%. Matches roadway grade. PAR running slope 13%.	No	{1BE9A976-3DD7-4838-ACB4-201FF8B5AB84}
20231075	More than 2%	4 x 4 feet or greater	Cross slope 12%. Matches roadway grade. PAR running slope 13%.	Yes	{8CEA4D88-BAC7-474C-9CC7-479F0AE8A5A4}
20231076	More than 2%	Less than 4 x 4 feet	Cross slope 16%. Matches roadway grade. PAR running slope 18%.	No	{C02DD714-C45C-4974-9440-221C985149ED}
20231077	More than 2%	4 x 4 feet or greater	Cross slope 13%. Matches roadway grade. PAR running slope 14%. PAR cross slope 3%.	No	{58E10240-B5AB-46A7-9E59-40E7A7C59220}
20231078	More than 2%	4 x 4 feet or greater	Cross slope 13%. Matches roadway grade. PAR running slope 14%. PAR cross slope 3.4%.	No	{F0A3362B-ED7D-4E1A-9F4C-DF3734294892}
20231079	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E6014E08-9B65-42A1-B7E1-2E6832112181}
20231080	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.7%.	No	{7B2687BB-C2BF-4B61-8DC2-A6D9BC0CBCFF}
20231081	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{75BBB47D-2084-43B3-88A9-85F164146747}
20231082	More than 2%	4 x 4 feet or greater	Cross slope 2.3%. PAR running slope 6%. PAR cross slope 6.2%.	No	{CF1B92F9-329F-462D-8CC1-E5FCB3F15948}
20231083	More than 2%	Less than 4 x 4 feet	Cross slope 2.3%. PAR running slope 2.7%.	No	{84A486D4-9F92-4803-83FA-090FF4B9BC39}
20231084	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 4.5%. PAR cross slope 2.7%.	No	{D9EFF069-71C3-4C86-B5AB-ED82E8AF79EC}
20231085	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip. PAR running slope 2.7%.	No	{BDCBDA31-98E0-41CA-BF34-59D6F9F904C9}
20231086	Up to or equal to 2%	Less than 4 x 4 feet	Larger DWS stamped over less than 36 inch curb transition	No	{09337C8D-8381-470C-B982-B2565B2A108F}
20231087	More than 2%	Less than 4 x 4 feet	Cross slope 3.8%. PAR running slope 4.8%. PAR cross slope 3%.	No	{3809FF68-856F-4D2A-8802-B6791A5D0276}
20231088	More than 2%	Less than 4 x 4 feet	Cross slope 3.8%. PAR running slope 3.4%.	No	{6692C4E4-097D-461B-A748-2FAC6E847CD2}
20231089	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{894FB0C2-4B0F-4511-A38D-2D2FA16A96A6}
20231090	More than 2%	4 x 4 feet or greater	Cross slope 3.9%. PAR running slope 6%. PAR cross slope 3%	No	{F52C5D64-4348-47C4-8D4F-3C56CD4816BA}
20231091	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 5%.	No	{9781BD7A-CB2D-400F-8366-B5EE545009F9}
20231092	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. PAR cross slope 2.3%.	No	{AFFC2B31-C74F-4E0C-9F8F-8B3C9B0F7E57}
20231093	Up to or equal to 2%	4 x 4 feet or greater	Landing within PAR. Monitor landing to curb gap.	No	{C780ACC1-EF24-41D1-9F0D-40ADED4D8A7C}
20231094	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 7%. PAR cross slope 3.8%.	No	{94AA2E01-90E2-46CD-8CCF-5D128AD2726D}
20231095	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 4.7%. PAR cross slope 3%.	No	{2C64C222-8BD7-4477-AEEC-0BE7C3B1E24C}
20231096	More than 2%	4 x 4 feet or greater	Cross slope 2.2%.	No	{60344871-AAE4-49CA-9819-03B02ABB9FD5}
20231097	More than 2%	4 x 4 feet or greater	Cross slope 5.7%. Matches roadway grade. PAR running slope . 8%. PAR cross up 2.7%. Crack forming in Landing area.	Yes	{4772356C-8A9B-49C6-92CD-FD085B40579E}
20231098	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 5.5%. PAR cross slope 3%.	Yes	{2ACE83AD-2BB9-4C16-BB50-8024EA4D937A}
20231099	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 3.8%.	Yes	{DA2AF52F-3ECE-4E17-B636-ADFDE2650786}
20231100	More than 2%	4 x 4 feet or greater	Cross slope 7%. Matches roadway grade. PAR running slope 10%. PAR cross slope 7%.	No	{1F2C2B54-2926-485C-931A-25C98FCFDE14}
20231101	More than 2%	4 x 4 feet or greater	Cross slope 6%. PAR running slope 10%	No	{05E0675A-0ABE-45F7-ADFC-FD4F0638969D}
20231102	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 5%. PAR cross slope 3%. Crack forming in ramp.	No	{D0DA35FD-B639-4D94-BB1C-4CD0B53B5132}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231103	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{12FBEC3B-6C93-43C8-B991-5893B54A925B}
20231104	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DE9D128A-7338-4536-9D7D-342728A97088}
20231105	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3.5%	No	{9506E5C0-73D0-456D-B02D-CBCC635C7D32}
20231106	More than 2%	4 x 4 feet or greater	Cross slope 4.5%. Matches roadway grade. PAR running slope 6%. PAR cross slope 3%.	No	{1A024E67-B29D-4893-8C4F-554E072F2212}
20231107	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{D4263508-0F09-42C5-9B17-EB4FF612119D}
20231108	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 2.7%.	Yes	{17E6C70F-8618-4BA5-BA33-D9586A6EEA56}
20231109	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9B7EEA34-27FD-4C82-A4A2-AC2C071A76A2}
20231110	More than 2%	4 x 4 feet or greater	Cross slope 2.5%. Matches roadway grade. PAR cross slope 2.3%.	No	{CE79BDBA-E951-42D8-B300-C6E24BE24474}
20231111	More than 2%	Less than 4 x 4 feet	PAR cross clope 4%	No	{15B52E2D-076A-4AE1-8E3B-BC4CA8D3E8ED}
20231112	More than 2%	4 x 4 feet or greater	Cross slope 4.8%. PAR running slope 6%. PAR cross slope 4.7%.	No	{DD3AF21F-F60E-4EDD-AE88-B0B048145C7F}
20231113	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 4%.	No	{B3F91F79-8F77-4951-AA30-2DF7748701C8}
20231114	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade.	Yes	{9817C6FE-D15E-4D5B-B889-DD485FD538E2}
20231115	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{872ED9DD-DC9B-4F71-9974-A2593A9FC24E}
20231116	More than 2%	4 x 4 feet or greater	Cross slope 2.6%. Matches roadway grade. PAR running slope 3.9%.	No	{58260CA2-BAE7-4769-8470-031797360EC8}
20231117	More than 2%	4 x 4 feet or greater	Cross slope 4%. PAR running slope 7%. PAR cross slope 5%.	No	{0303FD58-F435-47B4-AD65-760E9946EC12}
20231118	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{51CE2B9D-19DF-482B-8A58-1723B31750D7}
20231119	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{0703F206-8E01-4D46-BCB9-BDBC9049A7C1}
20230607	<Null>	<Null>	Is this City jurisdiction? No DWS at railroad crossing.	No	{ECC0ACCD-6632-42DA-B842-1BACBDB174F9}
20230599	<Null>	<Null>	Is this City jurisdiction. No DWS at railroad crossing.	No	{652AE596-9AD3-48BF-8866-F5B24978475A}
20231120	<Null>	<Null>	No DWS transition to roadway	No	{8FD566D1-053C-4147-A164-C16F72D9DC70}
20231121	<Null>	<Null>	PAR right of way across street unclear	No	{03C3F6C8-5C93-4958-B48B-4DB0AFD86C81}
20231122	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. Steep side flares.	No	{388BBB63-65DF-4261-9EF3-DC0070E63338}
20231123	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation and debris	No	{8F52C97E-4DF1-45C7-A0B9-82B3B389245D}
20231124	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{E606A02B-B705-48FD-8433-D1EA502FC1F5}
20231125	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{76E3BB79-19FE-4E1F-9A38-0F83DFD8012B}
20231126	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{9A9EEF16-8DCF-474F-A5C1-AC41294E08A0}
20230439	<Null>	<Null>	End of PAR	No	{F13A7065-583B-4C86-B21F-326588F9D1FB}
20230398	<Null>	<Null>	PAR fades into overgrown vegetation.	No	{81B23B80-F4C1-46D5-9342-28988997A545}
20230456	<Null>	<Null>	<Null>	No	{1D03EEF3-C2B5-485A-8507-E74A0510944F}
20231127	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A4D43A41-57E7-47F6-B984-D709E74D07E7}
20231128	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation and debris	No	{05421608-FD3B-42B0-A349-4382ECF0BA08}
20231129	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{684FA94B-E0AB-455B-8390-21506CDA3F16}
20231130	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{71C0DEF4-4293-470A-AADA-48195CC7D547}
20231131	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{1597F6E1-0693-45E3-8BA1-CC586EC3FF04}
20231132	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{031A7949-643F-44A4-ACF4-6E3AF4B505BD}
20231133	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{8DC864C4-3AD9-4F3D-9E83-5CDD8476EF0C}
20231134	Up to or equal to 2%	4 x 4 feet or greater	Debris	Yes	{42CBC043-1190-424B-8DE4-7193BB4EA420}
20231135	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6C382848-F8CA-4CDA-A959-0449B94600E2}
20231136	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{79AC0A37-0AFB-4A58-8E6F-987D4DD653C7}
20231137	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6ABBE925-0C14-462E-A29A-5BBABB88C908}
20230442	<Null>	<Null>	Provide blended transition to shoulder	No	{A1CED544-EC6A-49ED-AB27-410393120830}
20230282	<Null>	<Null>	Provide DWS	No	{1B157611-B750-467D-A81B-926BB3DC8C70}
20231138	<Null>	<Null>	<Null>	No	{BB79FE18-8D9D-4D3B-8625-452F8245181D}
20231139	<Null>	<Null>	<Null>	No	{E7AB99CB-5CC0-48F6-92C5-B0F56200EF26}
20230854	<Null>	<Null>	<Null>	No	{C36DC294-58DF-42A0-BDAA-8D300A81F58F}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231016	<Null>	<Null>	<Null>	No	{11E8A145-3AA4-4714-8CED-600202E0BC5A}
20231140	<Null>	<Null>	No DWS where shared use path intersects roadway	No	{3D8C1F35-082D-44F0-83D2-A84A5AF3D73E}
20231144	<Null>	<Null>	Bridge curb lip to paved goat path and no DWS to shoulder	No	{FB91DBA3-C239-4A0F-9B64-634076D00067}
20231141	<Null>	<Null>	No DWS at shared use pass crossing	No	{061FC8DD-774F-4410-BAAF-11D0E2BA5183}
20231142	<Null>	<Null>	No DWS at shared use path crossing	No	{771F2727-1D6C-4325-84C5-D160B3F1E2C6}
20231143	<Null>	<Null>	Bridge curb lip to paved path with no DWS to shoulder	No	{784CE3C6-4F02-4CD3-B853-A8780BF0D4D7}
20231146	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 6%. PAR Cross slope 4.3%.	No	{18F46F0F-BD93-43B8-89F5-AE9916160364}
20231145	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 6.6%.	No	{5A2A6F55-1CEE-43EC-8239-0035FBF19D21}
20231152	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 6.5%.	No	{A399E703-8E97-41CC-95A3-5F3C812F0FD2}
20231151	More than 2%	Less than 4 x 4 feet	Cross slope 6%. Matches roadway grade. PAR running slope 9%.	Yes	{94F32A77-B308-4954-A5B7-9C11811EF0B6}
20231150	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{5AF4F374-4524-41B3-952D-766DE031B4BF}
20231149	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.3%	No	{56AFD8A5-405E-40BF-89A1-64D0F59662F7}
20231148	More than 2%	4 x 4 feet or greater	Cross slope 3.7%. Matches roadway grade.	No	{8E962E63-85A1-45F0-87C3-7A445B4B94B4}
20231147	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{7606E03B-3F7F-4901-87B1-9176AB351457}
20231153	More than 2%	4 x 4 feet or greater	Cross slope 3.3%. Matches roadway grade. PAR running slope 4.2%.	No	{783430C3-D045-4645-B8FF-09C3E783368C}
20231154	More than 2%	Less than 4 x 4 feet	Cross slope 5.5%. Matches roadway grade. PIR running slope 5%. PAR cross slope 2.7%.	No	{F3601CDE-6531-46AC-A80E-59357CF914B2}
20231155	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 6%.	No	{C6F24FE5-70DC-4E7C-A16D-E9372BA94117}
20231156	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 3.4%. PAR cross slope 2.4%.	No	{2E903B6F-1C7D-4C0E-AD69-E5BAD9755BED}
20231157	More than 2%	4 x 4 feet or greater	Cross slope 2.8%. Matches roadway grade. PAR running slope 4.2%.	No	{FF68A7A0-0008-49BE-A08A-615CCC8F42AA}
20231158	More than 2%	Less than 4 x 4 feet	Bush covers entire landing area. Cross slope 6%. Steeper than roadway grade.	No	{9DC18BA4-1FF3-4E1E-8427-3DA1150F1911}
20231159	More than 2%	Less than 4 x 4 feet	Overgrown, vegetation, and debris in landing. Cross slope 6%. Steeper than roadway grade	No	{8B36942C-E8D7-4E29-91C6-16F79D23E8ED}
20231160	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{FDA78611-65F2-4AFF-B5BB-8CCDD4C0496A}
20231161	<Null>	<Null>	DWS missing at shared use trail crossing	No	{1F66F588-30E2-486F-BE7E-01F39576E35A}
20231162	Up to or equal to 2%	4 x 4 feet or greater	Cracks in ramp. Shared used path.	No	{9ACA32ED-B26C-4FB3-AED7-DC6B9ACBCCA9}
20231163	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 4%	No	{3C526078-819F-4DAC-B310-98F25AE80D4D}
20231164	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{2173B630-BEB9-4CEF-BB39-E8848EDD0554}
20231165	Up to or equal to 2%	Less than 4 x 4 feet	Ramp transition not aligned with ramp slope	No	{B600B652-A87D-47BA-8A90-C15F26480BCE}
20231166	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. Sidewalk upheaval between PAR and back of landing	No	{83742FCE-4C70-4F5A-A03E-7423DACF8808}
20231167	Up to or equal to 2%	4 x 4 feet or greater	Monitor panel gaps	No	{1E0BAD82-515D-4D9F-A8A7-69217D0A9334}
20231168	More than 2%	4 x 4 feet or greater	Cross slope 2.3%. PAR cross slope 3%.	No	{32BC3D53-D21C-48A6-8738-2443F1127406}
20231169	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.3%.	No	{2ABA9FEC-6845-442B-8B81-0C5523108E9F}
20231170	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip at ramp to curb transition	No	{45D3E359-F2E8-4B83-9972-D7A0C768564E}
20231171	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 2.8%. Matches roadway grade.	Yes	{2A8C72B7-0306-47BE-98EE-CE7541E3B81F}
20231172	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 8%.	Yes	{83FD24EC-7A72-43AB-B03A-6AA4EF7AEF59}
20231173	More than 2%	4 x 4 feet or greater	Cross slope 5%. Steeper than roadway grade. PAR cross slope, 8.4%.	No	{B1974A31-F120-440E-B3D3-100D9C6EA4E7}
20231174	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 3.8%. PAR cross slope 3.5%.	No	{95EEE839-C7D0-451D-B313-535B29E79EA8}
20231175	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{5C2C298D-5C18-4CCF-B78A-186DD9065EE7}
20231176	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{F220BDC2-2D7B-497D-8A10-7EECC15810EB}
20231177	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.2%.	No	{3781EF7B-BB39-491A-B50E-992916E7A2EF}
20231178	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 2.6%	No	{495A263A-8B63-4C20-B6AF-8ED6D42FBB9B}
20231179	More than 2%	4 x 4 feet or greater	Cross slope 2.9%. Matches roadway grade. PAR running slope 5.8%.	No	{B099FA5A-CB54-435B-B1A5-2BEB7F5B3C72}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231180	More than 2%	4 x 4 feet or greater	Cross slope 3.3%. Matches roadway grade. PAR running slope 4%. Minor curb lip.	No	{26392460-D34A-41D0-8E3D-35C5B5627A78}
20231181	More than 2%	Less than 4 x 4 feet	Insufficient Landing. Cross slope 3%. Matches roadway grade.	No	{E4DD7488-C583-4805-B0E3-03CAF9E96484}
20231182	Up to or equal to 2%	Less than 4 x 4 feet	Insufficient landing	No	{C28F4C06-96BB-4D90-98DD-C1AB781DA0F6}
20231183	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{AB63FA1E-120D-4DD6-A0D5-C84103181134}
20231184	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{6A63EB91-66E8-4D51-BDD2-A08F6E9853A6}
20231185	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 4.8%.	No	{9339E75D-35CB-456A-91F4-F434202FDD6D}
20231186	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.3%	No	{AA080AEF-71D6-4993-9853-39F544872A8D}
20231187	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. Cracks in landing.	No	{AF5ECD33-A1A3-4E15-A6EB-ACBE127E8359}
20231188	Up to or equal to 2%	Less than 4 x 4 feet	Running slope 10%. Vertical discontinuities between landing and ramp.	No	{438140D5-BE17-440D-A230-FF9981A49A82}
20231189	Up to or equal to 2%	Less than 4 x 4 feet	Running slope 9%. PAR cross slope 3.4%.	No	{0153EA7B-2B50-471F-8B3E-4FCDA34A7B91}
20231190	More than 2%	Less than 4 x 4 feet	Running slope 9%. Cross slope 4%. Steeper than roadway grade. PAR running slope 5%. PAR cross slope 3%.	No	{1D43B342-403C-4B8C-A357-6B86A03B2578}
20231191	More than 2%	Less than 4 x 4 feet	Cross slope 6%. More than roadway grade. PAR running soap 7%. Monitor gap between panels.	No	{936D0D1C-7FFB-406E-AF25-B22851A07934}
20231192	Up to or equal to 2%	Less than 4 x 4 feet	Minor curb lip	No	{3A6A7A18-C80A-4035-9C23-5504EEC81611}
20231193	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 4%.	No	{552D9518-2725-4D22-AB65-4CBDD55CBE1C}
20231194	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. Minor curb lip.	No	{DD13817A-92A8-497E-ACBB-4077FEF39B35}
20231195	More than 2%	Less than 4 x 4 feet	Cross slope 3%. Matches roadway grade. PAR running slope 4%.	No	{23909685-B70C-4BF6-BEA5-AB5E8CB4685B}
20231196	More than 2%	Less than 4 x 4 feet	Cross slope 2.7%. Matches roadway great. PAR running slope 4%.	No	{51A97BB6-AC6E-4C61-AA50-8BB7C02A9D5D}
20231197	More than 2%	Less than 4 x 4 feet	Curb transition less than 36 inches. Cross slope 4%. Compatible with roadway grade. PA are running slope 7%. PAR cross slope 4%.	No	{DBF27A48-DA49-4971-9B5D-AE484EAD4938}
20231198	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 6%	No	{79819E97-3C51-4F84-A256-BBF8A7A6D94D}
20231199	More than 2%	Less than 4 x 4 feet	Cross slope 2.7%. Matches roadway grade.	No	{064F3953-D4C3-4611-B202-592D136C23DE}
20231200	More than 2%	Less than 4 x 4 feet	Cross slope 3.5%. Steeper than roadway grade. PAR running slope 11%. PAR cross slope 5%	No	{A20F14E8-AB27-4F67-9162-668CEE5B0A6E}
20231201	More than 2%	Less than 4 x 4 feet	Cross slope 10%. Matches roadway grade. PAR running slope 14%. PAR cross slope 3%.	No	{DA617DB0-4976-441B-88A0-DB6BFA882948}
20231202	More than 2%	Less than 4 x 4 feet	Running slope 10%. Cross slope 9%. Steeper than roadway grade. PAR running slope 12%. PAR Cross slope 3%	No	{3E7AEF94-8B71-485D-AC1D-358C9E0AB3D1}
20231203	More than 2%	Less than 4 x 4 feet	Running slope 12%. Cross slope 12%. Steeper than roadway grade. PAR running slope 13%.	No	{D2D28478-C720-4616-A96F-B161B35DDC59}
20231204	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 3%	No	{EFB63813-74C3-49A3-AFFF-663000B02072}
20231205	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 6%.	No	{FEF459D8-D90A-4F5A-ACC1-C5CE8B05CAA1}
20231206	More than 2%	Less than 4 x 4 feet	Cross slope 7%. Steeper than roadway grade. PAR running slope 11%. PAR cross slope 5%.	No	{9547F417-5DA7-4E9A-8276-788CAF61BD51}
20231207	More than 2%	Less than 4 x 4 feet	Cross slope 9%. Matches roadway grade. PAR running slope 11%.	No	{A10C8A9D-D5AF-4070-802D-B3D30F2FC763}
20231208	More than 2%	4 x 4 feet or greater	Running slope 11%. Cross slope 5%. Matches roadway grade. PAR running slope 5%.	No	{84D0FB1F-BD7A-42BA-A9EC-55A9712E24F5}
20231209	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. Minor curb lip.	No	{5AE429A1-E819-4D8B-BEDD-67103CA58E14}
20231210	Up to or equal to 2%	Less than 4 x 4 feet	Cracks in flares. Monitor gaps. Overgrown vegetation.	No	{42F7F940-93E4-44BC-89CA-FC73D4DE4ECE}
20231211	More than 2%	Less than 4 x 4 feet	Cracks in flares. Cross slope 2.6%. Monitor gaps.	No	{8B5AA187-2DBB-4C42-B555-80461DB4EC05}
20231212	More than 2%	Less than 4 x 4 feet	Cross slope 3%. Matches roadway grade. PAR running slope 3.7%. Monitor gaps.	No	{56DB0C70-695F-4B2F-B41F-56CA8D40E108}
20231213	More than 2%	Less than 4 x 4 feet	Cross slope 10%. Steeper than roadway grade. PAR running slope 12%.	No	{83540AF2-9C4D-444C-8673-D16C1568EC09}
20231214	Up to or equal to 2%	Less than 4 x 4 feet	Minor curb lip.	No	{439BF57C-E53F-448A-B9E2-7D26D3A35472}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231215	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. Crack forming in landing. Monitor gaps.	No	{E4FA87C9-6751-4D9F-B2EE-99D317AE95AD}
20231216	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 4%.	No	{32EA6514-E124-444D-A4A1-737B07762BCB}
20231217	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 2.7%.	No	{DA1B429B-EB62-4795-A347-D3487F18308E}
20231218	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{C335C3F2-B077-479C-9CAE-37799C79F1DA}
20231219	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{164C1E4B-2752-436E-A4D1-9F54807F99F1}
20231220	Up to or equal to 2%	Less than 4 x 4 feet	Drain grate interferes at curb transition	No	{D6A627D4-C32F-4B2F-97F1-E9AB08412C20}
20231221	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 3.7%	No	{535D8E29-B0EB-4F41-B266-BBCDDD0ED32E}
20231222	Up to or equal to 2%	4 x 4 feet or greater	Running slope 13%. Monitor gaps.	No	{B5098FB9-BE31-46AB-A15B-1B283737E513}
20231223	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{3B370BC3-C8E1-4A19-883E-2109A3A812C5}
20231224	More than 2%	Less than 4 x 4 feet	Running slope 9%. Cross slope 4%. Matches roadway grade. PAR running slope 5%.	No	{02536C73-B7FC-464E-AA76-12F7394E69D5}
20231225	More than 2%	Less than 4 x 4 feet	Cross slope 3%. PAR running slope 4%.	No	{9F21D027-FABF-49C0-A825-914BF68B285B}
20231226	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{E781AAA9-FD4F-4B9F-A200-0E183D59C91A}
20231227	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{5C300805-7645-40B8-B593-38CE2EA1BEB0}
20231228	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{9C07BB40-CDB3-45D7-8663-17C2B3BAA2C2}
20231229	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes within 2.2%.	No	{20F5F4C4-8E1C-4CD0-9B52-200E102A1ABA}
20231230	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{ECD4E48-6A22-413B-A157-2772CABC1535}
20231231	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. PAR running slope 3.6%.	No	{AA6F14F3-72E2-43F1-A2DE-3435CB5729A8}
20231232	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes 2.7%.	No	{8B46861D-12FB-4179-BB5B-894BF2D16F28}
20231233	Up to or equal to 2%	4 x 4 feet or greater	Monitor vertical discontinuity between landing and ramp	No	{16F12AE8-3FF8-4CB9-8DAD-EFD4B0B323DC}
20231234	More than 2%	Less than 4 x 4 feet	Cross slope 4.5%. Steeper than roadway grade. PAR running slope 6.5%.	No	{B50740FD-AA98-4E27-AD28-6B69DCB19C82}
20231235	More than 2%	Less than 4 x 4 feet	Cross slope 5%. Matches roadway grade. PAR running slope 5%. PAR cross slope 4%.	No	{BEA6C615-3ABE-4A0C-BBF3-E497906BFC1B}
20231236	Up to or equal to 2%	Less than 4 x 4 feet	Crack between ramp and flare	No	{7885D441-BDEE-4247-9B66-5337861D110F}
20231237	More than 2%	4 x 4 feet or greater	Cross slope 9%. Matches roadway grade. Crack through ramp.	No	{E9071F72-8877-4D75-881B-4CE985EF3E64}
20231238	More than 2%	Less than 4 x 4 feet	Cross slope 12%. Steeper than roadway grade. PAR running slope 16%. PAR cross slope 4%. Moss growing over DWS.	No	{B52191D5-8281-4118-B58E-B04427C8D048}
20231239	More than 2%	Less than 4 x 4 feet	Cross slope 15%. Steeper than roadway grade. PAR running slope 19%. PAR cross slope 3%.	No	{639D65EC-FD86-46E2-8F5D-97AFD006EB4F}
20231240	More than 2%	Less than 4 x 4 feet	Cross slope 12%. Steeper than 10% roadway grade. PAR running slope 10%. PAR cross slope 4%.	No	{A89EE4C8-F0DD-4715-99F2-FC8DED15A43A}
20231241	More than 2%	Less than 4 x 4 feet	Cross slope 19%. Steeper than 16% roadway grade. PAR running slope 21%. PAR cross slope 7.8%.	No	{ADC7E231-04E5-4BE2-B13E-3CD3355ACC7A}
20231242	More than 2%	Less than 4 x 4 feet	Cross slope 7%. Matches roadway grade. PAR running slope 8.5%. PAR cross slope 3%.	No	{D5703B7D-B41B-4E36-9A7A-ADAAC81C3D50}
20231243	More than 2%	Less than 4 x 4 feet	Cross slope 13%. Steeper than 12% roadway grade. PAR running slope 18%.	No	{43EC42AC-94E1-48EF-B1F7-55AC7076C044}
20231244	More than 2%	4 x 4 feet or greater	Cross slope 14%. Matches roadway grade. PAR running slope 15%.	No	{27602B43-A298-4704-8BED-684EDEC5B887}
20231245	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade.	No	{6AA3ED2C-99C5-4CE6-AC1C-D8E9B5C3CC8F}
20231246	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade.	No	{E0D1AA34-7F86-48C8-8A61-5ACC3361A76C}
20231247	More than 2%	4 x 4 feet or greater	Cross slope 7%. Matches roadway grade. Crack forming in ramp.	Yes	{A93559DA-7A02-4488-B8DC-261AB5E0E6A8}
20231248	More than 2%	Less than 4 x 4 feet	Cross slope 12%. Matches roadway grade. PAR running slope 15%. Minor curb lip.	No	{6A149A29-7151-4656-AE6C-4366807C5003}
20231249	More than 2%	Less than 4 x 4 feet	Cross slope 9%. Steeper than 7% roadway grade. PAR running slope 11%. PAR cross slope 4.7%.	No	{DED404C0-8D6B-4BCC-853A-F5C3D897C389}
20231250	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{1272CA80-FC55-42F5-BFC3-694B2C4DADD9}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231251	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{16322F6E-7802-4FE9-935F-F11EB4A3F941}
20231252	Up to or equal to 2%	Less than 4 x 4 feet	Minor curb lip. PAR running slope 4%.	No	{64F2ABD3-EC3F-4FB0-ADD7-76047FED90FC}
20231253	Up to or equal to 2%	Less than 4 x 4 feet	Landing slopes 5%	No	{58521DD0-D0CF-4FBF-8D0C-B8DA4E79ECEA}
20231254	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{FD49FF15-C019-4A58-BCB1-7ED4BE30BE5D}
20231255	More than 2%	Less than 4 x 4 feet	Cross slope 3%. Steeper than roadway grade. Curb lip.	No	{B66AF735-71EA-403F-B356-8B85B72B3FBC}
20231256	More than 2%	Less than 4 x 4 feet	Cross slope 7%. Matches roadway grade. PAR running slope 13%. PAR Cross slope 7%. Curb lip.	No	{1D7A12AC-763A-4453-ADCB-DF6EE8C61118}
20231257	More than 2%	Less than 4 x 4 feet	Cross slope 10%. Matches roadway grade. PAR running slope 12%. PAR cross slope 9%.	No	{364690E6-8CB5-441D-B1B2-BCCF840EFD24}
20231258	More than 2%	4 x 4 feet or greater	Cross slope 9%. Matches roadway grade. PAR running slope 14%.	Yes	{30B3D0B1-C130-43D4-AA46-C071ADFA14F9}
20231259	More than 2%	4 x 4 feet or greater	Cross slope 8%. Steeper than 6% roadway grade. PAR running slope 13%. PAR cross slope 9%.	No	{C882853B-D9A9-4DAC-A90D-9FCDFC76B114}
20231260	More than 2%	Less than 4 x 4 feet	Cross slope 6%. Steeper than 4% roadway grade. PAR running slope 6%.	No	{1020DBF8-DF6D-479D-909B-BF840BED5ACF}
20231261	More than 2%	4 x 4 feet or greater	Running slope 11%. Cross slope 3%. Matches roadway grade. Vertical discontinuity between ramp and landing.	No	{4141293A-86A7-4192-9C3A-64FA51655AD2}
20231262	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 8%.	No	{6C3B4712-0F30-4987-992D-91AB6987F028}
20231263	More than 2%	4 x 4 feet or greater	Minor curb lip. PAR running slope 2.5%.	No	{26087756-03E1-4A33-92E4-37B9ABCFB0DF}
20231264	More than 2%	Less than 4 x 4 feet	Cross slope 3%. Matches roadway grade. PAR running slope 4%.	No	{9E15E0D5-D2C6-4694-AEEA-C093DC49805C}
20230792	<Null>	<Null>	No receiving ramp for diagonally oriented ramp at intersection	No	{CEF381FF-0056-4119-A164-D2586BCC3FD4}
20231265	More than 2%	Less than 4 x 4 feet	Cross slope 7%. Steeper than 5.8% roadway grade. PAR running slope 11%.	No	{BBE2982E-984D-4E1F-A403-F6C04F5F2283}
20231266	More than 2%	Less than 4 x 4 feet	Cross slope 3%. Steeper than 1% roadway grade. PAR running slope 4.5%.	No	{527CEA86-01A1-45CC-87E0-C3E6A2541D14}
20231267	More than 2%	Less than 4 x 4 feet	Cross slope 5.7%. Matches roadway grade. PAR running slope 10%.	No	{C9EEC96B-EFB3-4913-9CA9-449DE12F4C93}
20231268	More than 2%	4 x 4 feet or greater	Cross slope 5.5%. Matches roadway grade. PAR running slope 7.5%. PAR cross slope 4%.	No	{2C444DF3-079B-498E-9A90-2F5F828E1A27}
20231269	More than 2%	4 x 4 feet or greater	Cross slope 3%. Transition upheaval at roadway interface	No	{A55CE96A-2B8F-43CB-98CB-77323AB96EBA}
20231270	More than 2%	Less than 4 x 4 feet	Cross slope 3%. PAR running slope 5%.	No	{4FBDD1F2-9278-4658-A4B9-A0FA60A8A3F0}
20231271	More than 2%	Less than 4 x 4 feet	Cross slope 4.7%. Matches roadway grade. PAR running slope 7%. PAR cross slope 4%.	No	{215C23D0-9091-441F-A2BE-D3521B04C17C}
20231272	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 4%.	No	{891A6D0F-7391-4BDF-9E0E-19AF85BAF8D1}
20230791	<Null>	<Null>	No receiving ramp at intersection for diagonal ramp	No	{539704F4-26F8-4F77-A454-844703EF75F7}
20231273	More than 2%	Less than 4 x 4 feet	Cross slope 5%. Steeper than roadway grade. PAR running slope 6%. PAR cross slope 7%.	No	{57DA74E6-8023-4D02-ADEF-5155748A781F}
20230789	<Null>	<Null>	No receiving ramp at intersection with diagonally oriented ramp	No	{D905ABE5-F296-42B1-BA87-D2DA5CBDD563}
20231274	Up to or equal to 2%	Less than 4 x 4 feet	<Null>	No	{4AA75F8A-A5C9-4A0A-8E9D-DF6F1B46D5FE}
20231275	Up to or equal to 2%	Less than 4 x 4 feet	Minor curb lip	No	{F4A5499A-9EDA-4A4A-A35D-E2B2D81579F6}
20231276	Up to or equal to 2%	4 x 4 feet or greater	Landing to ramp vertical discontinuity. Curb lip.	No	{4971449F-5B85-42FD-A702-1129509AA7AA}
20231277	Up to or equal to 2%	4 x 4 feet or greater	DWS deterioration	Yes	{38692B09-6291-4C3A-8DA0-D029F0279AFD}
20231278	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 2.3%	No	{833FAAE9-96C5-4A18-B968-12C922D439DC}
20231279	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 2.3%	No	{3D5A30B4-3231-41F3-A2CC-19EF7C29BC6B}
20231280	More than 2%	Less than 4 x 4 feet	Running slope 9%. Cross slope 6%. Steeper than 3% roadway grade. PAR running slope 6.5%	No	{EFC0BC3D-5100-4655-AA4C-693F0EF8C03B}
20230788	<Null>	<Null>	No receiving ramp at intersection across from diagonally oriented ramp	No	{845F0744-2A60-4B07-824A-0E961A668DE5}
20231281	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{49217152-5C07-4780-94E6-051AFFA85576}
20231282	Up to or equal to 2%	Less than 4 x 4 feet	Monitor gap and vertical discontinuity forming	No	{391CB310-D91E-44E8-BD8D-BD90F0DC6ABF}
20231283	Up to or equal to 2%	Less than 4 x 4 feet	PAR cross slope 4%	No	{04E1153F-3CD5-4007-963B-62A24EA0CBE2}
20231284	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip	No	{EE14E641-6EBE-46D8-AD83-7A105C83EE30}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231285	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{328BF5CB-0C15-4A47-A2F0-87E03EC5B390}
20231286	Up to or equal to 2%	Less than 4 x 4 feet	Monitor upheaval at top corner of ramp and gaps.	No	{D32B4132-0D8D-435C-A39A-00ED4855FAC3}
20231287	Up to or equal to 2%	Less than 4 x 4 feet	PAR running slope 3%.	No	{C32C657B-5260-49FD-BE4F-3CBE7BC60C3D}
20231288	Up to or equal to 2%	4 x 4 feet or greater	Running slope 12%. PAR cross slope 3%.	No	{181477C7-E13F-414C-8ACB-F2EEF2D02749}
20231289	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{D4F8C35B-D1B0-47E9-BF24-B1D482AD6077}
20231290	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip	No	{DABC5369-0A3C-4EBF-8A8E-05DE7CEE6C84}
20231291	More than 2%	Less than 4 x 4 feet	Running slope 11%. Cross slope 2.7%. PAR running slope 2.7%.	No	{E7CEF7FA-7DD3-4C8C-AB4E-F3152F70E9A9}
20231292	Up to or equal to 2%	Less than 4 x 4 feet	Minor curb lip	No	{65BA90E6-9E25-4167-BAAD-8C1E5E2FB855}
20231293	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. Curb lip.	No	{53C0AE8C-9A7D-44B3-A037-7D4DB5738101}
20231294	Up to or equal to 2%	4 x 4 feet or greater	Monitor landing to ramp gap and flare vertical discontinuities	No	{F9FFB031-0494-4918-A0DC-6D74685575CB}
20231295	Up to or equal to 2%	Less than 4 x 4 feet	Monitor flare vertical discontinuity	No	{D1081F9B-B22D-46F9-ADCD-82E5636B2DAF}
20231296	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip	No	{575CA631-07FC-402F-9A4D-933A1E1813B8}
20231297	Up to or equal to 2%	Less than 4 x 4 feet	Minor curb lip.	No	{234D0D41-C3C2-4A77-8543-C8A1C3A8CF95}
20231298	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{6F834BE0-24A7-40B8-9A9B-360DE0BFA50F}
20231299	Up to or equal to 2%	4 x 4 feet or greater	<Null>	No	{1B77E882-B62C-42FC-807D-29F7554305A0}
20231300	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%. Minor curb lip.	No	{5B9316EA-98FF-4416-B40D-5555D64F8F8A}
20231301	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip. Monitor landing to ramp gap.	No	{BCD6203E-B8A0-478B-8038-4A737196EFCC}
20231302	Up to or equal to 2%	4 x 4 feet or greater	Running slope 11%. Curb lips. Monitor landing to ramp gaps.	No	{A414C3F4-A02D-40C5-A48C-55F4A20914A4}
20231303	Up to or equal to 2%	4 x 4 feet or greater	Running slope 10%.	No	{219798E3-BEF1-4F19-83BF-B14AA80B24EB}
20231304	Up to or equal to 2%	Less than 4 x 4 feet	Mud debris	No	{FFCF6498-8E8D-45D8-923B-D7B7ED13B02C}
20231305	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. PAR running slope 4%.	Yes	{C680F892-F176-450F-AB37-D5229D2468C3}
20231306	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.7%.	No	{D1A20CDD-C01E-4131-9870-8B6C930D9C09}
20231307	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. Minor DWS lip.	No	{AA464EA8-7916-4767-8B0F-A28DEB33C96A}
20231308	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{05788737-8251-4ACE-B7E3-CDB2BDFD3367}
20231309	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{DD5CE767-A795-4BBA-9709-87F07BA53718}
20231310	Up to or equal to 2%	4 x 4 feet or greater	Monitor DWS lip	Yes	{E1D18FC7-DABF-4AF7-86E1-CD9ECF8F4448}
20231311	Up to or equal to 2%	4 x 4 feet or greater	Running slope 9%. Overgrown vegetation.	No	{CBEB17B1-B1D9-4D14-92EB-AC0FD68C6FC1}
20231312	Up to or equal to 2%	4 x 4 feet or greater	Landing slopes 2.3%. Monitor gaps.	No	{20F95B02-3005-43AD-B348-378940888FDA}
20231313	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.7%. Monitor gaps.	No	{43446C01-0C99-4115-A90C-274EF2C702C4}
20231314	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 3%. Monitor gaps.	No	{7C2AD2DB-E9D2-4ABB-8B7F-60E842A88315}
20231315	More than 2%	4 x 4 feet or greater	Cross slope 3%. Landing slopes 3.5%.	No	{F40CF6B0-617A-45A0-8D7E-84358A1D6B6A}
20231316	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 2.7%	Yes	{1160EA11-FDB2-4E0A-B4B0-4DDF51609F80}
20231317	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{0CFE32F1-6AD6-4915-871B-75F6ABFE154A}
20231325	More than 2%	4 x 4 feet or greater	Cross slope 4.8%. Matches roadway grade. PA are running soap 5.8%. PAR cross slope 3%	No	{0E003DF4-2E4F-432D-8C30-371014A23A19}
20231318	More than 2%	4 x 4 feet or greater	Cross slope 7%. Matches roadway grade. PAR running slope 7%. PAR cross slope 2.5%.	No	{C9BDAD0C-23FA-4518-8604-EBC54F74F1F0}
20231319	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 2.7%.	Yes	{8F0C1F4A-5F28-4C0B-92D0-074AECE0AD0E}
20231320	More than 2%	4 x 4 feet or greater	Cross slope 6%. Steeper than 4.8% roadway grade. PAR running slope 8%. PAR cross slope, 8%.	No	{8227C04A-2539-4817-B061-FE8533E48CC8}
20231321	More than 2%	4 x 4 feet or greater	Cross slope 8%. Matches roadway grade. PAR running slope 9%. PAR cross slope 3%.	No	{913C64FE-556D-4443-9E1C-E8CA036EB664}
20231322	More than 2%	4 x 4 feet or greater	Cross slope 10%. Steeper than 7% roadway grade. PAR running slope 12%. PAR cross slope 3%.	No	{3E6293C0-B998-41C2-A89E-BD4C0718E7A0}
20231323	More than 2%	4 x 4 feet or greater	Cross slope at 8%. Steeper than 4% roadway grade. P. and I are running smoke 12%. PAR cross slope 3.5	No	{F49BCA0E-0F14-446C-8482-A0B0754E08C0}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231324	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Matches roadway grade. PAR running slope 3%.	Yes	{FCD89316-759E-419F-BCFD-0F45BC246815}
20231326	More than 2%	4 x 4 feet or greater	Monitor vertical discontinuity. Cross slope 4.2%. Matches roadway grade. PAR cross slope 5.7%.	No	{59696063-C230-4949-B8CA-87B1EE638EAA}
20231327	More than 2%	4 x 4 feet or greater	Cross slope 5.7%. Matches roadway grade. PAR running slope 5%.	Yes	{A8604F55-90E2-49EA-AF75-B65BA3280286}
20231328	More than 2%	4 x 4 feet or greater	Cross slope 8%. Steeper than 6.8% roadway grade. PAR running slope 9.8%. PAR cross slope 3%.	No	{6064EEE5-C577-4E46-8B52-8A22511F77DD}
20231329	More than 2%	4 x 4 feet or greater	Cross slope 7.5%. Steeper than 4% roadway grade. PAR running slope 9.3%. PAR cross slope 7.6%.	No	{46D90E02-860B-4E64-8011-F42AA77C156C}
20231330	More than 2%	4 x 4 feet or greater	Cross slope 4%. Steeper than 2% roadway grade. PAR running slope 4%. PAR cross slope 6.5%.	No	{6DA4B8BD-DE41-4195-AA7D-F01AF8246BF6}
20231331	More than 2%	4 x 4 feet or greater	Cross slope 6%. Matches roadway grade. PAR running slope 7.6% PAR cross slope 2.4%.	No	{C273CA54-D68F-4897-961A-E8CA285F1686}
20231332	More than 2%	4 x 4 feet or greater	Minor curb, lip,. Cross slope. Matches roadway grade. PAR running slope 6%.	No	{A140F1F3-1A01-4977-89E4-D875407EA45B}
20231333	More than 2%	4 x 4 feet or greater	Cross slope 5.5%. Matches roadway grade. PAR running slope 5.8%.	Yes	{7EC5F11C-DE2D-49F8-9618-B4617ED7C20C}
20231334	More than 2%	4 x 4 feet or greater	Cross slope 6.3%. Steeper than 4.8% roadway grade. PAR running slope 10%.	No	{9BD6B216-29C7-4611-A85D-EA354186F027}
20231335	More than 2%	4 x 4 feet or greater	Cross slope 5.8%. Steeper than 4% roadway grade. Landing slopes 7%.	No	{DFB54753-00E9-4631-940C-1406BD903D69}
20231336	More than 2%	4 x 4 feet or greater	Cross slope 5%. Steeper than 3% roadway grade. Landing slopes 4%.	No	{050A3990-5B22-4078-9F74-095A6EDE2166}
20231337	Up to or equal to 2%	4 x 4 feet or greater	DWS damage.	No	{DEB004AF-2B93-4A9A-871A-01FF1F75E8B5}
20231338	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{22BFA7EF-0B64-4D34-879B-3DA667CD449A}
20231339	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Steeper than 2% roadway grade. PAR running slope 3%. Monitor gap.	No	{2E73BCD6-55A0-464D-93EC-846B7627A8C9}
20231340	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 8%.	Yes	{F4301A72-8AAE-4515-845D-911C33C1E5F0}
20231341	More than 2%	4 x 4 feet or greater	Cross slope 6%. Steeper than 4% roadway grade. PAR running slope 10%.	No	{949773B6-43BE-475E-B7A8-3564FAC7E4B9}
20231342	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 4%.	Yes	{A16A0F4B-356F-41CA-A5B6-DC8775D39849}
20231343	Up to or equal to 2%	4 x 4 feet or greater	PAR running slope 2.7%.	Yes	{9B7B9067-41DC-46B4-A5F5-6E0FE5634080}
20231344	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{50AC5BC8-33F6-45F1-BA1F-422EFBAF6FB3}
20231345	More than 2%	4 x 4 feet or greater	Monitor gaps. Cross slope 7%. Steeper than 4.4% roadway grade. PAR running slope 9%. PAR cross slope 3%.	No	{E1A33584-CD3D-4489-83F3-6BE4242EAC68}
20231346	Up to or equal to 2%	4 x 4 feet or greater	Minor Curb lip	No	{03DF7AAF-C3AD-4D36-BAE0-31ADC38253F5}
20231347	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{A8CAC020-D97B-4836-A72F-86CF922D0E9F}
20231348	Up to or equal to 2%	4 x 4 feet or greater	Overgrown vegetation.	No	{BE5E85DE-41E6-4CE5-9C7D-1B3D00365B7C}
20231349	Up to or equal to 2%	4 x 4 feet or greater	Running slope 11%.	No	{F13F5CCF-A6F4-473D-AFFB-B31CA42A9366}
20231350	More than 2%	4 x 4 feet or greater	Running slope 10%. Cross slope 3%. Matches roadway great. Overgrown vegetation. PAR running slope 3%.	No	{CAE8C173-79EC-4844-B19A-0785E60E48AD}
20231351	More than 2%	4 x 4 feet or greater	Monitor curb to DWS lip. Cross slope 6%. Matches roadway grade. PAR running slope 5.5%.	No	{E632C66D-7488-461C-8005-2C933B12376A}
20231352	More than 2%	4 x 4 feet or greater	Cross slope 4%. Matches roadway grade. PAR running slope 6%. PAR cross slope 3%.	No	{25193CFD-6EC5-49C4-8652-F3E20F2DDFBA}
20231353	Up to or equal to 2%	4 x 4 feet or greater	Monitor curb lip. PAR cross slope 2.2%.	No	{DF51DB94-7A6C-49FA-BAE9-1D47E7EA00D4}
20231355	More than 2%	4 x 4 feet or greater	Cross slope 3.5%. Matches roadway grade. PAR running slope 4.6%. PAR cross slope 2.3%. Monitor DWS to curb lips.	No	{49E7B1E3-C7F6-4644-89EE-1F47AC421B84}
20231356	Up to or equal to 2%	4 x 4 feet or greater	Monitor vegetation. PAR running slope 4%. PAR cross slope 2.7%.	No	{187394FD-F0EE-4908-AEEB-7889415B4710}
20231358	Up to or equal to 2%	4 x 4 feet or greater	Monitor DWS to curb transition	Yes	{B385B51F-664D-414D-A627-7C9A2E4AD397}
20231357	More than 2%	4 x 4 feet or greater	Cross slope 3%. Matches roadway grade. Landing slopes 4.7%.	No	{EBF128AA-4552-48C1-AC4D-E4AA9B9C92EB}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	Cross_Slope	Landing	Notes	TSI_ADA_Compliant *	GlobalID *
20231359	Up to or equal to 2%	4 x 4 feet or greater	Crack forming in ramp. Running slope 9%. PAR cross slope 3%. Matches roadway grade.	No	{EC1C4140-CFF1-4612-A00A-D7B3CF2EB60F}
20231360	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 6%. PAR cross slope 3%.	No	{48B9F418-63F6-4559-83A9-50FBA491191A}
20231361	Up to or equal to 2%	4 x 4 feet or greater	PAR cross slope 2.5%.	No	{BFFEE2F9-E1F2-403E-BEE3-E4AA263628F9}
20231362	More than 2%	4 x 4 feet or greater	Cross slope 4.5%. Matches roadway grade. PAR running slopes 5.8%	Yes	{C59836C6-E60F-477F-95B2-7ABA17A8B813}
20231363	<Null>	4 x 4 feet or greater	Cross slope 6%. Steeper than 4.6% roadway grade. PAR running slope 5.8%	No	{3DFFCD01-7931-475A-AD02-773C83913A31}
20231364	More than 2%	4 x 4 feet or greater	Cross slopes 9.5%. Steeper than 6.5% roadway grade. PAR running slopes 14%	No	{AEC31F7A-2119-408E-B6FB-8E13799AF766}
20231365	More than 2%	4 x 4 feet or greater	Cross slope 6%. Steeper than 4.3% roadway grade. PAR running slopes 7.5%	No	{4B09FA63-3706-4F8B-9D22-261994163805}
20231366	More than 2%	4 x 4 feet or greater	Cross slope 5%. Matches roadway grade. PAR running slope 5.5%. Monitor gap.	Yes	{56C44EF4-1BA3-47D9-9470-5E52B95D6E9C}
20230784	<Null>	<Null>	No receiving ramp at intersection	No	{D120D879-B800-4F20-8693-D0A80856D48B}
20230783	More than 2%	4 x 4 feet or greater	Cross slope 2.5%. Matches roadway grade. PAR running slope 3.7%.	No	{FB6419F7-74B7-40D8-977E-23CB93B62A36}
20230782	Up to or equal to 2%	4 x 4 feet or greater	Poor ramp, no DWS transition to road	No	{46CADCA5-762A-4768-B096-71EDCAE6070B}
20230408	Up to or equal to 2%	4 x 4 feet or greater	No DWS at end of PAR.	No	{DFBBD695-767E-400D-AED9-F115C8F6DBB9}
20230790	<Null>	<Null>	Appears to be public right of way	No	{31FDC30E-362C-4980-A0C7-1E82587CBC34}
20230409	<Null>	<Null>	Appears to be public right of way	No	{A6CCECFE-596C-48B8-B4A5-0F9E2471E331}
20230275	Up to or equal to 2%	4 x 4 feet or greater	Minor curb lip. Blended transition recommended at shoulder	No	{8D55FA49-F49F-4BE8-83D4-B80CF8F91BBF}
20230281	Up to or equal to 2%	Less than 4 x 4 feet	No Landing. Major curb lip. Blended transition recommended at shoulder	No	{CAD2BF08-D9AD-4A9A-835B-83D6CBF47C65}
20230135	Up to or equal to 2%	4 x 4 feet or greater	<Null>	Yes	{6F3241C3-C998-4F4B-8CC5-DAEAC4BD76F8}

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230382	Plan Set for ramp removal	Ramp 59	59	<Null>
20230381	Plan Set for MEF ramp	Ramp 58	58	Missing
20230380	Plan Set for MEF ramp	Ramp 57	57	Missing
20230379	Plan Set for ramp removal	Ramp 56	56	<Null>
20230303	Plan Set for fully ADA-compliant ramp	Ramp 55	55	<Null>
20230302	Plan Set for fully ADA-compliant ramp	Ramp 54	54	<Null>
20230301	Plan Set for MEF ramp	Ramp 53	53	Missing
20230364	<Null>	Ramp 52	52	MEF as of March 2023 KPG Report
20230365	No proposed work on this ramp	Ramp 51	51	Missing
20230366	<Null>	Ramp 50	50	MEF as of March 2023 KPG Report
20230367	<Null>	Ramp 49	49	MEF as of March 2023 KPG Report
20230363	Plan Set for MEF ramp	Ramp 48	48	MEF as of March 2023 KPG Report
20230324	Plan Set for MEF ramp	Ramp 47	47	MEF as of March 2023 KPG Report
20230325	Plan Set for MEF ramp	Ramp 46	46	MEF as of March 2023 KPG Report
20230362	Plan Set for MEF ramp	Ramp 45	45	MEF as of March 2023 KPG Report
20230285	Plan Set for ramp removal	Ramp 44	44	<Null>
20230284	Plan Set for fully ADA-compliant ramp	Ramp 43	43	<Null>
20230318	<Null>	Ramp 42	42	MEF as of September 2019 Perteet Report
20230319	<Null>	Ramp 41	41	MEF as of September 2019 Perteet Report
20230320	Plan Set for ramp removal	Ramp 40	40	<Null>
20230321	Plan Set for MEF ramp	Ramp 39	39	Missing
20230322	<Null>	Ramp 38	38	MEF as of September 2019 Perteet Report
20230323	<Null>	Ramp 37	37	MEF as of September 2019 Perteet Report
20230422	<Null>	Ramp 36	36	MEF as of September 2014 Perteet Report
20230423	<Null>	Ramp 35	35	MEF as of September 2014 Perteet Report
20230424	<Null>	Ramp 34	34	MEF as of September 2014 Perteet Report
20230425	<Null>	Ramp 33	33	MEF as of September 2014 Perteet Report
20230136	Plan Set for fully ADA-compliant ramp	Ramp 32	32	<Null>
20230134	Plan Set for fully ADA-compliant ramp	Ramp 31	31	<Null>
20230133	Plan Set for fully ADA-compliant ramp	Ramp 30	30	<Null>
20230132	Plan Set for fully ADA-compliant ramp	Ramp 29	29	<Null>
20230138	Plan Set for fully ADA-compliant ramp	Ramp 28	28	<Null>
20230140	Plan Set for fully ADA-compliant ramp	Ramp 27	27	<Null>
20230142	Plan Set for fully ADA-compliant ramp	Ramp 26	26	<Null>
20230144	Plan Set for fully ADA-compliant ramp	Ramp 25	25	<Null>
20230269	<Null>	Ramp 24	24	MEF as of September 2014 Perteet Report
20230360	<Null>	Ramp 23	23	MEF as of September 2014 Perteet Report
20230317	<Null>	Ramp 22	22	MEF as of September 2014 Perteet Report
20230274	<Null>	Ramp 21	21	MEF as of September 2014 Perteet Report

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230270	<Null>	Ramp 20	20	MEF as of September 2014 Perteet Report
20230271	<Null>	Ramp 19	19	MEF as of September 2014 Perteet Report
20230272	<Null>	Ramp 18	18	MEF as of September 2014 Perteet Report
20230273	<Null>	Ramp 17	17	MEF as of September 2014 Perteet Report
20230559	<Null>	Ramp 16	16	MEF as of March 2023 KPG Report
20230558	<Null>	Ramp 15	15	MEF as of March 2023 KPG Report
20230557	<Null>	Ramp 14	14	MEF as of March 2023 KPG Report
20230556	<Null>	Ramp 13	13	MEF as of March 2023 KPG Report
20230560	<Null>	Ramp 12	12	MEF as of March 2023 KPG Report
20230561	<Null>	Ramp 11	11	MEF as of March 2023 KPG Report
20230554	Plan Set for fully ADA-compliant ramp	Ramp 10	10	<Null>
20230555	Plan Set for fully ADA-compliant ramp	Ramp 9	9	<Null>
20230575	Plan Set for fully ADA-compliant ramp	Ramp 8	8	<Null>
20230574	Plan Set for fully ADA-compliant ramp	Ramp 7	7	<Null>
20230573	Plan Set for fully ADA-compliant ramp	Ramp 6	6	<Null>
20230572	Plan Set for fully ADA-compliant ramp	Ramp 5	5	<Null>
20230568	Plan Set for fully ADA-compliant ramp	Ramp 4	4	<Null>
20230569	Plan Set for fully ADA-compliant ramp	Ramp 3	3	<Null>
20230570	Plan Set for fully ADA-compliant ramp	Ramp 2	2	<Null>
20230571	Plan Set for fully ADA-compliant ramp	Ramp 1	1	<Null>
20230001	<Null>	<Null>	<Null>	<Null>
20230002	<Null>	<Null>	<Null>	<Null>
20230003	<Null>	<Null>	<Null>	<Null>
20230004	<Null>	<Null>	<Null>	<Null>
20230005	<Null>	<Null>	<Null>	<Null>
20230006	<Null>	<Null>	<Null>	<Null>
20230007	<Null>	<Null>	<Null>	<Null>
20230008	<Null>	<Null>	<Null>	<Null>
20230153	<Null>	<Null>	<Null>	<Null>
20230009	<Null>	<Null>	<Null>	<Null>
20230010	<Null>	<Null>	<Null>	<Null>
20230011	<Null>	<Null>	<Null>	<Null>
20230012	<Null>	<Null>	<Null>	<Null>
20230432	<Null>	<Null>	<Null>	<Null>
20230013	<Null>	<Null>	<Null>	<Null>
20230014	<Null>	<Null>	<Null>	<Null>
20230015	<Null>	<Null>	<Null>	<Null>
20230016	<Null>	<Null>	<Null>	<Null>
20230017	<Null>	<Null>	<Null>	<Null>
20230018	<Null>	<Null>	<Null>	<Null>
20230019	<Null>	<Null>	<Null>	<Null>
20230020	<Null>	<Null>	<Null>	<Null>
20230021	<Null>	<Null>	<Null>	<Null>
20230022	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230023	<Null>	<Null>	<Null>	<Null>
20230024	<Null>	<Null>	<Null>	<Null>
20230025	<Null>	<Null>	<Null>	<Null>
20230026	<Null>	<Null>	<Null>	<Null>
20230027	<Null>	<Null>	<Null>	<Null>
20230029	<Null>	<Null>	<Null>	<Null>
20230030	<Null>	<Null>	<Null>	<Null>
20230031	<Null>	<Null>	<Null>	<Null>
20230032	<Null>	<Null>	<Null>	<Null>
20230034	<Null>	<Null>	<Null>	<Null>
20230035	<Null>	<Null>	<Null>	<Null>
20230158	<Null>	<Null>	<Null>	<Null>
20230036	<Null>	<Null>	<Null>	<Null>
20230037	<Null>	<Null>	<Null>	<Null>
20230197	<Null>	<Null>	<Null>	<Null>
20230038	<Null>	<Null>	<Null>	<Null>
20230105	<Null>	<Null>	<Null>	<Null>
20230039	<Null>	<Null>	<Null>	<Null>
20230040	<Null>	<Null>	<Null>	<Null>
20230041	<Null>	<Null>	<Null>	<Null>
20230043	<Null>	<Null>	<Null>	<Null>
20230042	<Null>	<Null>	<Null>	<Null>
20230044	<Null>	<Null>	<Null>	<Null>
20230045	<Null>	<Null>	<Null>	<Null>
20230046	<Null>	<Null>	<Null>	<Null>
20230047	<Null>	<Null>	<Null>	<Null>
20230048	<Null>	<Null>	<Null>	<Null>
20230049	<Null>	<Null>	<Null>	<Null>
20230050	<Null>	<Null>	<Null>	<Null>
20230051	<Null>	<Null>	<Null>	<Null>
20230052	<Null>	<Null>	<Null>	<Null>
20230053	<Null>	<Null>	<Null>	<Null>
20230054	<Null>	<Null>	<Null>	<Null>
20230055	<Null>	<Null>	<Null>	<Null>
20230056	<Null>	<Null>	<Null>	<Null>
20230057	<Null>	<Null>	<Null>	<Null>
20230058	<Null>	<Null>	<Null>	<Null>
20230059	<Null>	<Null>	<Null>	<Null>
20230060	<Null>	<Null>	<Null>	<Null>
20230061	<Null>	<Null>	<Null>	<Null>
20230062	<Null>	<Null>	<Null>	<Null>
20230063	<Null>	<Null>	<Null>	<Null>
20230064	<Null>	<Null>	<Null>	<Null>
20230065	<Null>	<Null>	<Null>	<Null>
20230066	<Null>	<Null>	<Null>	<Null>
20230106	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230433	<Null>	<Null>	<Null>	<Null>
20230067	<Null>	<Null>	<Null>	<Null>
20230068	<Null>	<Null>	<Null>	<Null>
20230069	<Null>	<Null>	<Null>	<Null>
20230107	<Null>	<Null>	<Null>	<Null>
20230070	<Null>	<Null>	<Null>	<Null>
20230108	<Null>	<Null>	<Null>	<Null>
20230071	<Null>	<Null>	<Null>	<Null>
20230072	<Null>	<Null>	<Null>	<Null>
20230073	<Null>	<Null>	<Null>	<Null>
20230434	<Null>	<Null>	<Null>	<Null>
20230109	<Null>	<Null>	<Null>	<Null>
20230074	<Null>	<Null>	<Null>	<Null>
20230435	<Null>	<Null>	<Null>	<Null>
20230075	<Null>	<Null>	<Null>	<Null>
20230076	<Null>	<Null>	<Null>	<Null>
20230436	<Null>	<Null>	<Null>	<Null>
20230077	<Null>	<Null>	<Null>	<Null>
20230078	<Null>	<Null>	<Null>	<Null>
20230079	<Null>	<Null>	<Null>	<Null>
20230110	<Null>	<Null>	<Null>	<Null>
20230080	<Null>	<Null>	<Null>	<Null>
20230111	<Null>	<Null>	<Null>	<Null>
20230081	<Null>	<Null>	<Null>	<Null>
20230082	<Null>	<Null>	<Null>	<Null>
20230083	<Null>	<Null>	<Null>	<Null>
20230084	<Null>	<Null>	<Null>	<Null>
20230112	<Null>	<Null>	<Null>	<Null>
20230085	<Null>	<Null>	<Null>	<Null>
20230113	<Null>	<Null>	<Null>	<Null>
20230086	<Null>	<Null>	<Null>	<Null>
20230437	<Null>	<Null>	<Null>	<Null>
20230438	<Null>	<Null>	<Null>	<Null>
20230440	<Null>	<Null>	<Null>	<Null>
20230087	<Null>	<Null>	<Null>	<Null>
20230088	<Null>	<Null>	<Null>	<Null>
20230114	<Null>	<Null>	<Null>	<Null>
20230089	<Null>	<Null>	<Null>	<Null>
20230090	<Null>	<Null>	<Null>	<Null>
20230091	<Null>	<Null>	<Null>	<Null>
20230115	<Null>	<Null>	<Null>	<Null>
20230092	<Null>	<Null>	<Null>	<Null>
20230093	<Null>	<Null>	<Null>	<Null>
20230094	<Null>	<Null>	<Null>	<Null>
20230095	<Null>	<Null>	<Null>	<Null>
20230116	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230096	<Null>	<Null>	<Null>	<Null>
20230097	<Null>	<Null>	<Null>	<Null>
20230441	<Null>	<Null>	<Null>	<Null>
20230098	<Null>	<Null>	<Null>	<Null>
20230099	<Null>	<Null>	<Null>	<Null>
20230117	<Null>	<Null>	<Null>	<Null>
20230118	<Null>	<Null>	<Null>	<Null>
20230100	<Null>	<Null>	<Null>	<Null>
20230119	<Null>	<Null>	<Null>	<Null>
20230101	<Null>	<Null>	<Null>	<Null>
20230102	<Null>	<Null>	<Null>	<Null>
20230103	<Null>	<Null>	<Null>	<Null>
20230104	<Null>	<Null>	<Null>	<Null>
20230150	<Null>	<Null>	<Null>	<Null>
20230151	<Null>	<Null>	<Null>	<Null>
20230152	<Null>	<Null>	<Null>	<Null>
20230154	<Null>	<Null>	<Null>	<Null>
20230155	<Null>	<Null>	<Null>	<Null>
20230149	<Null>	<Null>	<Null>	<Null>
20230156	<Null>	<Null>	<Null>	<Null>
20230157	<Null>	<Null>	<Null>	<Null>
20230159	<Null>	<Null>	<Null>	<Null>
20230160	<Null>	<Null>	<Null>	<Null>
20230161	<Null>	<Null>	<Null>	<Null>
20230162	<Null>	<Null>	<Null>	<Null>
20230163	<Null>	<Null>	<Null>	<Null>
20230164	<Null>	<Null>	<Null>	<Null>
20230165	<Null>	<Null>	<Null>	<Null>
20230166	<Null>	<Null>	<Null>	<Null>
20230167	<Null>	<Null>	<Null>	<Null>
20230168	<Null>	<Null>	<Null>	<Null>
20230169	<Null>	<Null>	<Null>	<Null>
20230170	<Null>	<Null>	<Null>	<Null>
20230171	<Null>	<Null>	<Null>	<Null>
20230172	<Null>	<Null>	<Null>	<Null>
20230173	<Null>	<Null>	<Null>	<Null>
20230174	<Null>	<Null>	<Null>	<Null>
20230175	<Null>	<Null>	<Null>	<Null>
20230176	<Null>	<Null>	<Null>	<Null>
20230177	<Null>	<Null>	<Null>	<Null>
20230178	<Null>	<Null>	<Null>	<Null>
20230179	<Null>	<Null>	<Null>	<Null>
20230180	<Null>	<Null>	<Null>	<Null>
20230181	<Null>	<Null>	<Null>	<Null>
20230182	<Null>	<Null>	<Null>	<Null>
20230183	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230184	<Null>	<Null>	<Null>	<Null>
20230185	<Null>	<Null>	<Null>	<Null>
20230186	<Null>	<Null>	<Null>	<Null>
20230187	<Null>	<Null>	<Null>	<Null>
20230188	<Null>	<Null>	<Null>	<Null>
20230189	<Null>	<Null>	<Null>	<Null>
20230190	<Null>	<Null>	<Null>	<Null>
20230120	<Null>	<Null>	<Null>	<Null>
20230451	<Null>	<Null>	<Null>	<Null>
20230191	<Null>	<Null>	<Null>	<Null>
20230192	<Null>	<Null>	<Null>	<Null>
20230193	<Null>	<Null>	<Null>	<Null>
20230194	<Null>	<Null>	<Null>	<Null>
20230195	<Null>	<Null>	<Null>	<Null>
20230196	<Null>	<Null>	<Null>	<Null>
20230198	<Null>	<Null>	<Null>	<Null>
20230199	<Null>	<Null>	<Null>	<Null>
20230200	<Null>	<Null>	<Null>	<Null>
20230201	<Null>	<Null>	<Null>	<Null>
20230202	<Null>	<Null>	<Null>	<Null>
20230203	<Null>	<Null>	<Null>	<Null>
20230204	<Null>	<Null>	<Null>	<Null>
20230205	<Null>	<Null>	<Null>	<Null>
20230206	<Null>	<Null>	<Null>	<Null>
20230207	<Null>	<Null>	<Null>	<Null>
20230208	<Null>	<Null>	<Null>	<Null>
20230209	<Null>	<Null>	<Null>	<Null>
20230210	<Null>	<Null>	<Null>	<Null>
20230211	<Null>	<Null>	<Null>	<Null>
20230212	<Null>	<Null>	<Null>	<Null>
20230213	<Null>	<Null>	<Null>	<Null>
20230214	<Null>	<Null>	<Null>	<Null>
20230215	<Null>	<Null>	<Null>	<Null>
20230216	<Null>	<Null>	<Null>	<Null>
20230217	<Null>	<Null>	<Null>	<Null>
20230218	<Null>	<Null>	<Null>	<Null>
20230219	<Null>	<Null>	<Null>	<Null>
20230220	<Null>	<Null>	<Null>	<Null>
20230221	<Null>	<Null>	<Null>	<Null>
20230222	<Null>	<Null>	<Null>	<Null>
20230223	<Null>	<Null>	<Null>	<Null>
20230224	<Null>	<Null>	<Null>	<Null>
20230225	<Null>	<Null>	<Null>	<Null>
20230226	<Null>	<Null>	<Null>	<Null>
20230227	<Null>	<Null>	<Null>	<Null>
20230228	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230229	<Null>	<Null>	<Null>	<Null>
20230230	<Null>	<Null>	<Null>	<Null>
20230444	<Null>	<Null>	<Null>	<Null>
20230231	<Null>	<Null>	<Null>	<Null>
20230232	<Null>	<Null>	<Null>	<Null>
20230445	<Null>	<Null>	<Null>	<Null>
20230121	<Null>	<Null>	<Null>	<Null>
20230122	<Null>	<Null>	<Null>	<Null>
20230123	<Null>	<Null>	<Null>	<Null>
20230124	<Null>	<Null>	<Null>	<Null>
20230125	<Null>	<Null>	<Null>	<Null>
20230126	<Null>	<Null>	<Null>	<Null>
20230447	<Null>	<Null>	<Null>	<Null>
20230127	<Null>	<Null>	<Null>	<Null>
20230448	<Null>	<Null>	<Null>	<Null>
20230128	<Null>	<Null>	<Null>	<Null>
20230129	<Null>	<Null>	<Null>	<Null>
20230130	<Null>	<Null>	<Null>	<Null>
20230233	<Null>	<Null>	<Null>	<Null>
20230234	<Null>	<Null>	<Null>	<Null>
20230235	<Null>	<Null>	<Null>	<Null>
20230236	<Null>	<Null>	<Null>	<Null>
20230237	<Null>	<Null>	<Null>	<Null>
20230449	<Null>	<Null>	<Null>	<Null>
20230450	<Null>	<Null>	<Null>	<Null>
20230238	<Null>	<Null>	<Null>	<Null>
20230239	<Null>	<Null>	<Null>	<Null>
20230240	<Null>	<Null>	<Null>	<Null>
20230241	<Null>	<Null>	<Null>	<Null>
20230242	<Null>	<Null>	<Null>	<Null>
20230243	<Null>	<Null>	<Null>	<Null>
20230244	<Null>	<Null>	<Null>	<Null>
20230245	<Null>	<Null>	<Null>	<Null>
20230246	<Null>	<Null>	<Null>	<Null>
20230247	<Null>	<Null>	<Null>	<Null>
20230248	<Null>	<Null>	<Null>	<Null>
20230249	<Null>	<Null>	<Null>	<Null>
20230250	<Null>	<Null>	<Null>	<Null>
20230251	<Null>	<Null>	<Null>	<Null>
20230252	<Null>	<Null>	<Null>	<Null>
20230253	<Null>	<Null>	<Null>	<Null>
20230254	<Null>	<Null>	<Null>	<Null>
20230255	<Null>	<Null>	<Null>	<Null>
20230326	<Null>	<Null>	<Null>	<Null>
20230327	<Null>	<Null>	<Null>	<Null>
20230328	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230329	<Null>	<Null>	<Null>	<Null>
20230330	<Null>	<Null>	<Null>	<Null>
20230331	<Null>	<Null>	<Null>	<Null>
20230131	<Null>	<Null>	<Null>	<Null>
20230332	<Null>	<Null>	<Null>	<Null>
20230333	<Null>	<Null>	<Null>	<Null>
20230334	<Null>	<Null>	<Null>	<Null>
20230455	<Null>	<Null>	<Null>	<Null>
20230335	<Null>	<Null>	<Null>	<Null>
20230336	<Null>	<Null>	<Null>	<Null>
20230148	<Null>	<Null>	<Null>	<Null>
20230337	<Null>	<Null>	<Null>	<Null>
20230338	<Null>	<Null>	<Null>	<Null>
20230339	<Null>	<Null>	<Null>	<Null>
20230340	<Null>	<Null>	<Null>	<Null>
20230341	<Null>	<Null>	<Null>	<Null>
20230342	<Null>	<Null>	<Null>	<Null>
20230343	<Null>	<Null>	<Null>	<Null>
20230344	<Null>	<Null>	<Null>	<Null>
20230345	<Null>	<Null>	<Null>	<Null>
20230453	<Null>	<Null>	<Null>	<Null>
20230347	<Null>	<Null>	<Null>	<Null>
20230452	<Null>	<Null>	<Null>	<Null>
20230454	<Null>	<Null>	<Null>	<Null>
20230458	<Null>	<Null>	<Null>	<Null>
20230351	<Null>	<Null>	<Null>	<Null>
20230146	<Null>	<Null>	<Null>	<Null>
20230147	<Null>	<Null>	<Null>	<Null>
20230256	<Null>	<Null>	<Null>	<Null>
20230257	<Null>	<Null>	<Null>	<Null>
20230258	<Null>	<Null>	<Null>	<Null>
20230259	<Null>	<Null>	<Null>	<Null>
20230261	<Null>	<Null>	<Null>	<Null>
20230262	<Null>	<Null>	<Null>	<Null>
20230263	<Null>	<Null>	<Null>	<Null>
20230264	<Null>	<Null>	<Null>	<Null>
20230265	<Null>	<Null>	<Null>	<Null>
20230430	<Null>	<Null>	<Null>	<Null>
20230266	<Null>	<Null>	<Null>	<Null>
20230267	<Null>	<Null>	<Null>	<Null>
20230268	<Null>	<Null>	<Null>	<Null>
20230346	<Null>	<Null>	<Null>	<Null>
20230286	<Null>	<Null>	<Null>	<Null>
20230287	<Null>	<Null>	<Null>	<Null>
20230288	<Null>	<Null>	<Null>	<Null>
20230289	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230290	<Null>	<Null>	<Null>	<Null>
20230291	<Null>	<Null>	<Null>	<Null>
20230292	<Null>	<Null>	<Null>	<Null>
20230293	<Null>	<Null>	<Null>	<Null>
20230294	<Null>	<Null>	<Null>	<Null>
20230295	<Null>	<Null>	<Null>	<Null>
20230296	<Null>	<Null>	<Null>	<Null>
20230297	<Null>	<Null>	<Null>	<Null>
20230298	<Null>	<Null>	<Null>	<Null>
20230299	<Null>	<Null>	<Null>	<Null>
20230300	<Null>	<Null>	<Null>	<Null>
20230276	<Null>	<Null>	<Null>	<Null>
20230277	Plan Set for DWS installation	<Null>	<Null>	<Null>
20230304	<Null>	<Null>	<Null>	<Null>
20230305	<Null>	<Null>	<Null>	<Null>
20230306	<Null>	<Null>	<Null>	<Null>
20230307	<Null>	<Null>	<Null>	<Null>
20230308	<Null>	<Null>	<Null>	<Null>
20230309	<Null>	<Null>	<Null>	<Null>
20230310	<Null>	<Null>	<Null>	<Null>
20230311	<Null>	<Null>	<Null>	<Null>
20230312	<Null>	<Null>	<Null>	<Null>
20230313	<Null>	<Null>	<Null>	<Null>
20230314	<Null>	<Null>	<Null>	<Null>
20230315	<Null>	<Null>	<Null>	<Null>
20230316	<Null>	<Null>	<Null>	<Null>
20230137	<Null>	<Null>	<Null>	<Null>
20230139	<Null>	<Null>	<Null>	<Null>
20230141	<Null>	<Null>	<Null>	<Null>
20230143	<Null>	<Null>	<Null>	<Null>
20230145	<Null>	<Null>	<Null>	<Null>
20230033	<Null>	<Null>	<Null>	<Null>
20230028	<Null>	<Null>	<Null>	<Null>
20230348	<Null>	<Null>	<Null>	<Null>
20230349	<Null>	<Null>	<Null>	<Null>
20230350	<Null>	<Null>	<Null>	<Null>
20230260	<Null>	<Null>	<Null>	<Null>
20230352	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230353	<Null>	<Null>	<Null>	<Null>
20230354	<Null>	<Null>	<Null>	<Null>
20230355	<Null>	<Null>	<Null>	<Null>
20230356	<Null>	<Null>	<Null>	<Null>
20230357	<Null>	<Null>	<Null>	<Null>
20230358	<Null>	<Null>	<Null>	<Null>
20230359	<Null>	<Null>	<Null>	<Null>
20230368	<Null>	<Null>	<Null>	<Null>
20230369	<Null>	<Null>	<Null>	<Null>
20230361	<Null>	<Null>	<Null>	<Null>
20230370	<Null>	<Null>	<Null>	<Null>
20230371	<Null>	<Null>	<Null>	<Null>
20230372	<Null>	<Null>	<Null>	<Null>
20230373	<Null>	<Null>	<Null>	<Null>
20230374	<Null>	<Null>	<Null>	<Null>
20230375	<Null>	<Null>	<Null>	<Null>
20230376	<Null>	<Null>	<Null>	<Null>
20230377	<Null>	<Null>	<Null>	<Null>
20230378	<Null>	<Null>	<Null>	<Null>
20230383	<Null>	<Null>	<Null>	<Null>
20230384	<Null>	<Null>	<Null>	<Null>
20230385	<Null>	<Null>	<Null>	<Null>
20230386	<Null>	<Null>	<Null>	<Null>
20230387	<Null>	<Null>	<Null>	<Null>
20230388	<Null>	<Null>	<Null>	<Null>
20230389	<Null>	<Null>	<Null>	<Null>
20230390	<Null>	<Null>	<Null>	<Null>
20230391	<Null>	<Null>	<Null>	<Null>
20230392	<Null>	<Null>	<Null>	<Null>
20230393	<Null>	<Null>	<Null>	<Null>
20230394	<Null>	<Null>	<Null>	<Null>
20230395	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230396	<Null>	<Null>	<Null>	<Null>
20230397	<Null>	<Null>	<Null>	<Null>
20230399	<Null>	<Null>	<Null>	<Null>
20230400	<Null>	<Null>	<Null>	<Null>
20230401	<Null>	<Null>	<Null>	<Null>
20230402	<Null>	<Null>	<Null>	<Null>
20230403	<Null>	<Null>	<Null>	<Null>
20230404	<Null>	<Null>	<Null>	<Null>
20230405	<Null>	<Null>	<Null>	<Null>
20230406	<Null>	<Null>	<Null>	<Null>
20230407	<Null>	<Null>	<Null>	<Null>
20230410	<Null>	<Null>	<Null>	<Null>
20230411	<Null>	<Null>	<Null>	<Null>
20230412	<Null>	<Null>	<Null>	<Null>
20230413	<Null>	<Null>	<Null>	<Null>
20230414	<Null>	<Null>	<Null>	<Null>
20230415	<Null>	<Null>	<Null>	<Null>
20230416	<Null>	<Null>	<Null>	<Null>
20230417	<Null>	<Null>	<Null>	<Null>
20230418	<Null>	<Null>	<Null>	<Null>
20230419	<Null>	<Null>	<Null>	<Null>
20230420	<Null>	<Null>	<Null>	<Null>
20230421	<Null>	<Null>	<Null>	<Null>
20230426	<Null>	<Null>	<Null>	<Null>
20230427	<Null>	<Null>	<Null>	<Null>
20230428	<Null>	<Null>	<Null>	<Null>
20230429	<Null>	<Null>	<Null>	<Null>
20230459	<Null>	<Null>	<Null>	<Null>
20230460	<Null>	<Null>	<Null>	<Null>
20230461	<Null>	<Null>	<Null>	<Null>
20230462	<Null>	<Null>	<Null>	<Null>
20230463	<Null>	<Null>	<Null>	<Null>
20230464	<Null>	<Null>	<Null>	<Null>
20230465	<Null>	<Null>	<Null>	<Null>
20230466	<Null>	<Null>	<Null>	<Null>
20230467	<Null>	<Null>	<Null>	<Null>
20230468	<Null>	<Null>	<Null>	<Null>
20230469	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230470	<Null>	<Null>	<Null>	<Null>
20230471	<Null>	<Null>	<Null>	<Null>
20230472	<Null>	<Null>	<Null>	<Null>
20230473	<Null>	<Null>	<Null>	<Null>
20230474	<Null>	<Null>	<Null>	<Null>
20230475	<Null>	<Null>	<Null>	<Null>
20230476	<Null>	<Null>	<Null>	<Null>
20230477	<Null>	<Null>	<Null>	<Null>
20230478	<Null>	<Null>	<Null>	<Null>
20230479	<Null>	<Null>	<Null>	<Null>
20230480	<Null>	<Null>	<Null>	<Null>
20230481	<Null>	<Null>	<Null>	<Null>
20230482	<Null>	<Null>	<Null>	<Null>
20230483	<Null>	<Null>	<Null>	<Null>
20230484	<Null>	<Null>	<Null>	<Null>
20230485	<Null>	<Null>	<Null>	<Null>
20230486	<Null>	<Null>	<Null>	<Null>
20230487	<Null>	<Null>	<Null>	<Null>
20230488	<Null>	<Null>	<Null>	<Null>
20230489	<Null>	<Null>	<Null>	<Null>
20230490	<Null>	<Null>	<Null>	<Null>
20230491	<Null>	<Null>	<Null>	<Null>
20230492	<Null>	<Null>	<Null>	<Null>
20230493	<Null>	<Null>	<Null>	<Null>
20230494	<Null>	<Null>	<Null>	<Null>
20230495	<Null>	<Null>	<Null>	<Null>
20230496	<Null>	<Null>	<Null>	<Null>
20230497	<Null>	<Null>	<Null>	<Null>
20230498	<Null>	<Null>	<Null>	<Null>
20230499	<Null>	<Null>	<Null>	<Null>
20230500	<Null>	<Null>	<Null>	<Null>
20230501	<Null>	<Null>	<Null>	<Null>
20230502	<Null>	<Null>	<Null>	<Null>
20230503	<Null>	<Null>	<Null>	<Null>
20230504	<Null>	<Null>	<Null>	<Null>
20230505	<Null>	<Null>	<Null>	<Null>
20230506	<Null>	<Null>	<Null>	<Null>
20230507	<Null>	<Null>	<Null>	<Null>
20230508	<Null>	<Null>	<Null>	<Null>
20230509	<Null>	<Null>	<Null>	<Null>
20230510	<Null>	<Null>	<Null>	<Null>
20230511	<Null>	<Null>	<Null>	<Null>
20230512	<Null>	<Null>	<Null>	<Null>
20230513	<Null>	<Null>	<Null>	<Null>
20230514	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230515	<Null>	<Null>	<Null>	<Null>
20230516	<Null>	<Null>	<Null>	<Null>
20230517	<Null>	<Null>	<Null>	<Null>
20230518	<Null>	<Null>	<Null>	<Null>
20230519	<Null>	<Null>	<Null>	<Null>
20230520	<Null>	<Null>	<Null>	<Null>
20230521	<Null>	<Null>	<Null>	<Null>
20230522	<Null>	<Null>	<Null>	<Null>
20230523	<Null>	<Null>	<Null>	<Null>
20230524	<Null>	<Null>	<Null>	<Null>
20230525	<Null>	<Null>	<Null>	<Null>
20230526	<Null>	<Null>	<Null>	<Null>
20230527	<Null>	<Null>	<Null>	<Null>
20230528	<Null>	<Null>	<Null>	<Null>
20230529	<Null>	<Null>	<Null>	<Null>
20230530	<Null>	<Null>	<Null>	<Null>
20230531	<Null>	<Null>	<Null>	<Null>
20230532	<Null>	<Null>	<Null>	<Null>
20230533	<Null>	<Null>	<Null>	<Null>
20230534	<Null>	<Null>	<Null>	<Null>
20230535	<Null>	<Null>	<Null>	<Null>
20230536	<Null>	<Null>	<Null>	<Null>
20230537	<Null>	<Null>	<Null>	<Null>
20230538	<Null>	<Null>	<Null>	<Null>
20230539	<Null>	<Null>	<Null>	<Null>
20230540	<Null>	<Null>	<Null>	<Null>
20230541	<Null>	<Null>	<Null>	<Null>
20230543	<Null>	<Null>	<Null>	<Null>
20230544	<Null>	<Null>	<Null>	<Null>
20230545	<Null>	<Null>	<Null>	<Null>
20230546	<Null>	<Null>	<Null>	<Null>
20230547	<Null>	<Null>	<Null>	<Null>
20230548	<Null>	<Null>	<Null>	<Null>
20230549	<Null>	<Null>	<Null>	<Null>
20230550	<Null>	<Null>	<Null>	<Null>
20230552	<Null>	<Null>	<Null>	<Null>
20230553	<Null>	<Null>	<Null>	<Null>
20230562	<Null>	<Null>	<Null>	<Null>
20230563	<Null>	<Null>	<Null>	<Null>
20230564	<Null>	<Null>	<Null>	<Null>
20230565	<Null>	<Null>	<Null>	<Null>
20230566	<Null>	<Null>	<Null>	<Null>
20230567	<Null>	<Null>	<Null>	<Null>
20230576	<Null>	<Null>	<Null>	<Null>
20230577	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230578	<Null>	<Null>	<Null>	<Null>
20230579	<Null>	<Null>	<Null>	<Null>
20230580	<Null>	<Null>	<Null>	<Null>
20230581	<Null>	<Null>	<Null>	<Null>
20230582	<Null>	<Null>	<Null>	<Null>
20230583	<Null>	<Null>	<Null>	<Null>
20230584	<Null>	<Null>	<Null>	<Null>
20230585	<Null>	<Null>	<Null>	<Null>
20230586	<Null>	<Null>	<Null>	<Null>
20230587	<Null>	<Null>	<Null>	<Null>
20230588	<Null>	<Null>	<Null>	<Null>
20230589	<Null>	<Null>	<Null>	<Null>
20230590	<Null>	<Null>	<Null>	<Null>
20230591	<Null>	<Null>	<Null>	<Null>
20230592	<Null>	<Null>	<Null>	<Null>
20230593	<Null>	<Null>	<Null>	<Null>
20230594	<Null>	<Null>	<Null>	<Null>
20230595	<Null>	<Null>	<Null>	<Null>
20230596	<Null>	<Null>	<Null>	<Null>
20230597	<Null>	<Null>	<Null>	<Null>
20230598	<Null>	<Null>	<Null>	<Null>
20230600	<Null>	<Null>	<Null>	<Null>
20230601	<Null>	<Null>	<Null>	<Null>
20230602	<Null>	<Null>	<Null>	<Null>
20230603	<Null>	<Null>	<Null>	<Null>
20230604	<Null>	<Null>	<Null>	<Null>
20230605	<Null>	<Null>	<Null>	<Null>
20230610	<Null>	<Null>	<Null>	<Null>
20230611	<Null>	<Null>	<Null>	<Null>
20230612	<Null>	<Null>	<Null>	<Null>
20230613	<Null>	<Null>	<Null>	<Null>
20230614	<Null>	<Null>	<Null>	<Null>
20230615	<Null>	<Null>	<Null>	<Null>
20230616	<Null>	<Null>	<Null>	<Null>
20230617	<Null>	<Null>	<Null>	<Null>
20230618	<Null>	<Null>	<Null>	<Null>
20230619	<Null>	<Null>	<Null>	<Null>
20230620	<Null>	<Null>	<Null>	<Null>
20230621	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230622	<Null>	<Null>	<Null>	<Null>
20230623	<Null>	<Null>	<Null>	<Null>
20230624	<Null>	<Null>	<Null>	<Null>
20230625	<Null>	<Null>	<Null>	<Null>
20230626	<Null>	<Null>	<Null>	<Null>
20230627	<Null>	<Null>	<Null>	<Null>
20230628	<Null>	<Null>	<Null>	<Null>
20230629	<Null>	<Null>	<Null>	<Null>
20230630	<Null>	<Null>	<Null>	<Null>
20230631	<Null>	<Null>	<Null>	<Null>
20230632	<Null>	<Null>	<Null>	<Null>
20230633	<Null>	<Null>	<Null>	<Null>
20230634	<Null>	<Null>	<Null>	<Null>
20230635	<Null>	<Null>	<Null>	<Null>
20230636	<Null>	<Null>	<Null>	<Null>
20230637	<Null>	<Null>	<Null>	<Null>
20230638	<Null>	<Null>	<Null>	<Null>
20230639	<Null>	<Null>	<Null>	<Null>
20230640	<Null>	<Null>	<Null>	<Null>
20230641	<Null>	<Null>	<Null>	<Null>
20230642	<Null>	<Null>	<Null>	<Null>
20230643	<Null>	<Null>	<Null>	<Null>
20230644	<Null>	<Null>	<Null>	<Null>
20230645	<Null>	<Null>	<Null>	<Null>
20230646	<Null>	<Null>	<Null>	<Null>
20230647	<Null>	<Null>	<Null>	<Null>
20230648	<Null>	<Null>	<Null>	<Null>
20230649	<Null>	<Null>	<Null>	<Null>
20230650	<Null>	<Null>	<Null>	<Null>
20230651	<Null>	<Null>	<Null>	<Null>
20230652	<Null>	<Null>	<Null>	<Null>
20230653	<Null>	<Null>	<Null>	<Null>
20230654	<Null>	<Null>	<Null>	<Null>
20230655	<Null>	<Null>	<Null>	<Null>
20230656	<Null>	<Null>	<Null>	<Null>
20230657	<Null>	<Null>	<Null>	<Null>
20230658	<Null>	<Null>	<Null>	<Null>
20230659	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230660	<Null>	<Null>	<Null>	<Null>
20230661	<Null>	<Null>	<Null>	<Null>
20230662	<Null>	<Null>	<Null>	<Null>
20230663	<Null>	<Null>	<Null>	<Null>
20230664	<Null>	<Null>	<Null>	<Null>
20230665	<Null>	<Null>	<Null>	<Null>
20230667	<Null>	<Null>	<Null>	<Null>
20230668	<Null>	<Null>	<Null>	<Null>
20230670	<Null>	<Null>	<Null>	<Null>
20230671	<Null>	<Null>	<Null>	<Null>
20230672	<Null>	<Null>	<Null>	<Null>
20230673	<Null>	<Null>	<Null>	<Null>
20230674	<Null>	<Null>	<Null>	<Null>
20230675	<Null>	<Null>	<Null>	<Null>
20230676	<Null>	<Null>	<Null>	<Null>
20230677	<Null>	<Null>	<Null>	<Null>
20230678	<Null>	<Null>	<Null>	<Null>
20230679	<Null>	<Null>	<Null>	<Null>
20230680	<Null>	<Null>	<Null>	<Null>
20230681	<Null>	<Null>	<Null>	<Null>
20230682	<Null>	<Null>	<Null>	<Null>
20230683	<Null>	<Null>	<Null>	<Null>
20230684	<Null>	<Null>	<Null>	<Null>
20230685	<Null>	<Null>	<Null>	<Null>
20230686	<Null>	<Null>	<Null>	<Null>
20230687	<Null>	<Null>	<Null>	<Null>
20230688	<Null>	<Null>	<Null>	<Null>
20230689	<Null>	<Null>	<Null>	<Null>
20230690	<Null>	<Null>	<Null>	<Null>
20230691	<Null>	<Null>	<Null>	<Null>
20230692	<Null>	<Null>	<Null>	<Null>
20230693	<Null>	<Null>	<Null>	<Null>
20230694	<Null>	<Null>	<Null>	<Null>
20230695	<Null>	<Null>	<Null>	<Null>
20230696	<Null>	<Null>	<Null>	<Null>
20230697	<Null>	<Null>	<Null>	<Null>
20230698	<Null>	<Null>	<Null>	<Null>
20230699	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230700	<Null>	<Null>	<Null>	<Null>
20230701	<Null>	<Null>	<Null>	<Null>
20230702	<Null>	<Null>	<Null>	<Null>
20230703	<Null>	<Null>	<Null>	<Null>
20230704	<Null>	<Null>	<Null>	<Null>
20230705	<Null>	<Null>	<Null>	<Null>
20230706	<Null>	<Null>	<Null>	<Null>
20230707	<Null>	<Null>	<Null>	<Null>
20230708	<Null>	<Null>	<Null>	<Null>
20230709	<Null>	<Null>	<Null>	<Null>
20230710	<Null>	<Null>	<Null>	<Null>
20230711	<Null>	<Null>	<Null>	<Null>
20230712	<Null>	<Null>	<Null>	<Null>
20230713	<Null>	<Null>	<Null>	<Null>
20230714	<Null>	<Null>	<Null>	<Null>
20230715	<Null>	<Null>	<Null>	<Null>
20230716	<Null>	<Null>	<Null>	<Null>
20230717	<Null>	<Null>	<Null>	<Null>
20230718	<Null>	<Null>	<Null>	<Null>
20230719	<Null>	<Null>	<Null>	<Null>
20230720	<Null>	<Null>	<Null>	<Null>
20230721	<Null>	<Null>	<Null>	<Null>
20230722	<Null>	<Null>	<Null>	<Null>
20230723	<Null>	<Null>	<Null>	<Null>
20230724	<Null>	<Null>	<Null>	<Null>
20230725	<Null>	<Null>	<Null>	<Null>
20230726	<Null>	<Null>	<Null>	<Null>
20230727	<Null>	<Null>	<Null>	<Null>
20230728	<Null>	<Null>	<Null>	<Null>
20230729	<Null>	<Null>	<Null>	<Null>
20230730	<Null>	<Null>	<Null>	<Null>
20230731	<Null>	<Null>	<Null>	<Null>
20230732	<Null>	<Null>	<Null>	<Null>
20230733	<Null>	<Null>	<Null>	<Null>
20230734	<Null>	<Null>	<Null>	<Null>
20230735	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230736	<Null>	<Null>	<Null>	<Null>
20230737	<Null>	<Null>	<Null>	<Null>
20230738	<Null>	<Null>	<Null>	<Null>
20230739	<Null>	<Null>	<Null>	<Null>
20230740	<Null>	<Null>	<Null>	<Null>
20230741	<Null>	<Null>	<Null>	<Null>
20230742	<Null>	<Null>	<Null>	<Null>
20230743	<Null>	<Null>	<Null>	<Null>
20230744	<Null>	<Null>	<Null>	<Null>
20230745	<Null>	<Null>	<Null>	<Null>
20230746	<Null>	<Null>	<Null>	<Null>
20230747	<Null>	<Null>	<Null>	<Null>
20230748	<Null>	<Null>	<Null>	<Null>
20230749	<Null>	<Null>	<Null>	<Null>
20230750	<Null>	<Null>	<Null>	<Null>
20230751	<Null>	<Null>	<Null>	<Null>
20230752	<Null>	<Null>	<Null>	<Null>
20230753	<Null>	<Null>	<Null>	<Null>
20230754	<Null>	<Null>	<Null>	<Null>
20230755	<Null>	<Null>	<Null>	<Null>
20230756	<Null>	<Null>	<Null>	<Null>
20230757	<Null>	<Null>	<Null>	<Null>
20230758	<Null>	<Null>	<Null>	<Null>
20230761	<Null>	<Null>	<Null>	<Null>
20230762	<Null>	<Null>	<Null>	<Null>
20230763	<Null>	<Null>	<Null>	<Null>
20230764	<Null>	<Null>	<Null>	<Null>
20230765	<Null>	<Null>	<Null>	<Null>
20230766	<Null>	<Null>	<Null>	<Null>
20230767	<Null>	<Null>	<Null>	<Null>
20230768	<Null>	<Null>	<Null>	<Null>
20230769	<Null>	<Null>	<Null>	<Null>
20230770	<Null>	<Null>	<Null>	<Null>
20230777	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230778	<Null>	<Null>	<Null>	<Null>
20230779	<Null>	<Null>	<Null>	<Null>
20230780	<Null>	<Null>	<Null>	<Null>
20230760	<Null>	<Null>	<Null>	<Null>
20230759	<Null>	<Null>	<Null>	<Null>
20230969	<Null>	<Null>	<Null>	<Null>
20230968	<Null>	<Null>	<Null>	<Null>
20231354	<Null>	<Null>	<Null>	<Null>
20231368	<Null>	<Null>	<Null>	<Null>
20231367	<Null>	<Null>	<Null>	<Null>
20231373	<Null>	<Null>	<Null>	<Null>
20231372	<Null>	<Null>	<Null>	<Null>
20231380	<Null>	<Null>	<Null>	<Null>
20230669	<Null>	<Null>	<Null>	<Null>
20231381	<Null>	<Null>	<Null>	<Null>
20230793	<Null>	<Null>	<Null>	<Null>
20230794	<Null>	<Null>	<Null>	<Null>
20230795	<Null>	<Null>	<Null>	<Null>
20230796	<Null>	<Null>	<Null>	<Null>
20230797	<Null>	<Null>	<Null>	<Null>
20230798	<Null>	<Null>	<Null>	<Null>
20230799	<Null>	<Null>	<Null>	<Null>
20230800	<Null>	<Null>	<Null>	<Null>
20230801	<Null>	<Null>	<Null>	<Null>
20230802	<Null>	<Null>	<Null>	<Null>
20230803	<Null>	<Null>	<Null>	<Null>
20230804	<Null>	<Null>	<Null>	<Null>
20230805	<Null>	<Null>	<Null>	<Null>
20230806	<Null>	<Null>	<Null>	<Null>
20230807	<Null>	<Null>	<Null>	<Null>
20230808	<Null>	<Null>	<Null>	<Null>
20230809	<Null>	<Null>	<Null>	<Null>
20230810	<Null>	<Null>	<Null>	<Null>
20230811	<Null>	<Null>	<Null>	<Null>
20230812	<Null>	<Null>	<Null>	<Null>
20230813	<Null>	<Null>	<Null>	<Null>
20230814	<Null>	<Null>	<Null>	<Null>
20230815	<Null>	<Null>	<Null>	<Null>
20230816	<Null>	<Null>	<Null>	<Null>
20230817	<Null>	<Null>	<Null>	<Null>
20230818	<Null>	<Null>	<Null>	<Null>
20230819	<Null>	<Null>	<Null>	<Null>
20230820	<Null>	<Null>	<Null>	<Null>
20230821	<Null>	<Null>	<Null>	<Null>
20230822	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230823	<Null>	<Null>	<Null>	<Null>
20230824	<Null>	<Null>	<Null>	<Null>
20230825	<Null>	<Null>	<Null>	<Null>
20230826	<Null>	<Null>	<Null>	<Null>
20230827	<Null>	<Null>	<Null>	<Null>
20230828	<Null>	<Null>	<Null>	<Null>
20230829	<Null>	<Null>	<Null>	<Null>
20230830	<Null>	<Null>	<Null>	<Null>
20230831	<Null>	<Null>	<Null>	<Null>
20230832	<Null>	<Null>	<Null>	<Null>
20230833	<Null>	<Null>	<Null>	<Null>
20230836	<Null>	<Null>	<Null>	<Null>
20230837	<Null>	<Null>	<Null>	<Null>
20230838	<Null>	<Null>	<Null>	<Null>
20230839	<Null>	<Null>	<Null>	<Null>
20230840	<Null>	<Null>	<Null>	<Null>
20230841	<Null>	<Null>	<Null>	<Null>
20230842	<Null>	<Null>	<Null>	<Null>
20230843	<Null>	<Null>	<Null>	<Null>
20230844	<Null>	<Null>	<Null>	<Null>
20230845	<Null>	<Null>	<Null>	<Null>
20230846	<Null>	<Null>	<Null>	<Null>
20230847	<Null>	<Null>	<Null>	<Null>
20230850	<Null>	<Null>	<Null>	<Null>
20230851	<Null>	<Null>	<Null>	<Null>
20230666	<Null>	<Null>	<Null>	<Null>
20230852	<Null>	<Null>	<Null>	<Null>
20230853	<Null>	<Null>	<Null>	<Null>
20231369	<Null>	<Null>	<Null>	<Null>
20230855	<Null>	<Null>	<Null>	<Null>
20230856	<Null>	<Null>	<Null>	<Null>
20230857	<Null>	<Null>	<Null>	<Null>
20230858	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230859	<Null>	<Null>	<Null>	<Null>
20230860	<Null>	<Null>	<Null>	<Null>
20230861	<Null>	<Null>	<Null>	<Null>
20230862	<Null>	<Null>	<Null>	<Null>
20230863	<Null>	<Null>	<Null>	<Null>
20230864	<Null>	<Null>	<Null>	<Null>
20230865	<Null>	<Null>	<Null>	<Null>
20230866	<Null>	<Null>	<Null>	<Null>
20230867	<Null>	<Null>	<Null>	<Null>
20230868	<Null>	<Null>	<Null>	<Null>
20230869	<Null>	<Null>	<Null>	<Null>
20230870	<Null>	<Null>	<Null>	<Null>
20230871	<Null>	<Null>	<Null>	<Null>
20230872	<Null>	<Null>	<Null>	<Null>
20230873	<Null>	<Null>	<Null>	<Null>
20230874	<Null>	<Null>	<Null>	<Null>
20230875	<Null>	<Null>	<Null>	<Null>
20230876	<Null>	<Null>	<Null>	<Null>
20230877	<Null>	<Null>	<Null>	<Null>
20230878	<Null>	<Null>	<Null>	<Null>
20230879	<Null>	<Null>	<Null>	<Null>
20230880	<Null>	<Null>	<Null>	<Null>
20230881	<Null>	<Null>	<Null>	<Null>
20230882	<Null>	<Null>	<Null>	<Null>
20230883	<Null>	<Null>	<Null>	<Null>
20230884	<Null>	<Null>	<Null>	<Null>
20230885	<Null>	<Null>	<Null>	<Null>
20230886	<Null>	<Null>	<Null>	<Null>
20230887	<Null>	<Null>	<Null>	<Null>
20230888	<Null>	<Null>	<Null>	<Null>
20230889	<Null>	<Null>	<Null>	<Null>
20230890	<Null>	<Null>	<Null>	<Null>
20230891	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230892	<Null>	<Null>	<Null>	<Null>
20230893	<Null>	<Null>	<Null>	<Null>
20230894	<Null>	<Null>	<Null>	<Null>
20230895	<Null>	<Null>	<Null>	<Null>
20230896	<Null>	<Null>	<Null>	<Null>
20230897	<Null>	<Null>	<Null>	<Null>
20230898	<Null>	<Null>	<Null>	<Null>
20230899	<Null>	<Null>	<Null>	<Null>
20230900	<Null>	<Null>	<Null>	<Null>
20230901	<Null>	<Null>	<Null>	<Null>
20230902	<Null>	<Null>	<Null>	<Null>
20230903	<Null>	<Null>	<Null>	<Null>
20230904	<Null>	<Null>	<Null>	<Null>
20230905	<Null>	<Null>	<Null>	<Null>
20230906	<Null>	<Null>	<Null>	<Null>
20230907	<Null>	<Null>	<Null>	<Null>
20230908	<Null>	<Null>	<Null>	<Null>
20230909	<Null>	<Null>	<Null>	<Null>
20230910	<Null>	<Null>	<Null>	<Null>
20230911	<Null>	<Null>	<Null>	<Null>
20230912	<Null>	<Null>	<Null>	<Null>
20230913	<Null>	<Null>	<Null>	<Null>
20230916	<Null>	<Null>	<Null>	<Null>
20230917	<Null>	<Null>	<Null>	<Null>
20230918	<Null>	<Null>	<Null>	<Null>
20230919	<Null>	<Null>	<Null>	<Null>
20230920	<Null>	<Null>	<Null>	<Null>
20230921	<Null>	<Null>	<Null>	<Null>
20230922	<Null>	<Null>	<Null>	<Null>
20230923	<Null>	<Null>	<Null>	<Null>
20230924	<Null>	<Null>	<Null>	<Null>
20230925	<Null>	<Null>	<Null>	<Null>
20230926	<Null>	<Null>	<Null>	<Null>
20230927	<Null>	<Null>	<Null>	<Null>
20230928	<Null>	<Null>	<Null>	<Null>
20230929	<Null>	<Null>	<Null>	<Null>
20230930	<Null>	<Null>	<Null>	<Null>
20230931	<Null>	<Null>	<Null>	<Null>
20230932	<Null>	<Null>	<Null>	<Null>
20230933	<Null>	<Null>	<Null>	<Null>
20230934	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230935	<Null>	<Null>	<Null>	<Null>
20230936	<Null>	<Null>	<Null>	<Null>
20230937	<Null>	<Null>	<Null>	<Null>
20230938	<Null>	<Null>	<Null>	<Null>
20230939	<Null>	<Null>	<Null>	<Null>
20230940	<Null>	<Null>	<Null>	<Null>
20230941	<Null>	<Null>	<Null>	<Null>
20230943	<Null>	<Null>	<Null>	<Null>
20230942	<Null>	<Null>	<Null>	<Null>
20230944	<Null>	<Null>	<Null>	<Null>
20230945	<Null>	<Null>	<Null>	<Null>
20230946	<Null>	<Null>	<Null>	<Null>
20230947	<Null>	<Null>	<Null>	<Null>
20230948	<Null>	<Null>	<Null>	<Null>
20230949	<Null>	<Null>	<Null>	<Null>
20230950	<Null>	<Null>	<Null>	<Null>
20230951	<Null>	<Null>	<Null>	<Null>
20230952	<Null>	<Null>	<Null>	<Null>
20230953	<Null>	<Null>	<Null>	<Null>
20230954	<Null>	<Null>	<Null>	<Null>
20230955	<Null>	<Null>	<Null>	<Null>
20230956	<Null>	<Null>	<Null>	<Null>
20230957	<Null>	<Null>	<Null>	<Null>
20230958	<Null>	<Null>	<Null>	<Null>
20230959	<Null>	<Null>	<Null>	<Null>
20230960	<Null>	<Null>	<Null>	<Null>
20230961	<Null>	<Null>	<Null>	<Null>
20230962	<Null>	<Null>	<Null>	<Null>
20230963	<Null>	<Null>	<Null>	<Null>
20230964	<Null>	<Null>	<Null>	<Null>
20230965	<Null>	<Null>	<Null>	<Null>
20230966	<Null>	<Null>	<Null>	<Null>
20230967	<Null>	<Null>	<Null>	<Null>
20230970	<Null>	<Null>	<Null>	<Null>
20230971	<Null>	<Null>	<Null>	<Null>
20230972	<Null>	<Null>	<Null>	<Null>
20230973	<Null>	<Null>	<Null>	<Null>
20230974	<Null>	<Null>	<Null>	<Null>
20230975	<Null>	<Null>	<Null>	<Null>
20230976	<Null>	<Null>	<Null>	<Null>
20230977	<Null>	<Null>	<Null>	<Null>
20230978	<Null>	<Null>	<Null>	<Null>
20230979	<Null>	<Null>	<Null>	<Null>
20230980	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20230981	<Null>	<Null>	<Null>	<Null>
20230982	<Null>	<Null>	<Null>	<Null>
20230983	<Null>	<Null>	<Null>	<Null>
20230986	<Null>	<Null>	<Null>	<Null>
20230987	<Null>	<Null>	<Null>	<Null>
20230988	<Null>	<Null>	<Null>	<Null>
20230990	<Null>	<Null>	<Null>	<Null>
20230991	<Null>	<Null>	<Null>	<Null>
20230992	<Null>	<Null>	<Null>	<Null>
20230993	<Null>	<Null>	<Null>	<Null>
20230989	<Null>	<Null>	<Null>	<Null>
20230994	<Null>	<Null>	<Null>	<Null>
20230995	<Null>	<Null>	<Null>	<Null>
20230996	<Null>	<Null>	<Null>	<Null>
20230997	<Null>	<Null>	<Null>	<Null>
20230998	<Null>	<Null>	<Null>	<Null>
20230999	<Null>	<Null>	<Null>	<Null>
20231000	<Null>	<Null>	<Null>	<Null>
20231001	<Null>	<Null>	<Null>	<Null>
20231002	<Null>	<Null>	<Null>	<Null>
20231003	<Null>	<Null>	<Null>	<Null>
20231004	<Null>	<Null>	<Null>	<Null>
20231005	<Null>	<Null>	<Null>	<Null>
20231006	<Null>	<Null>	<Null>	<Null>
20231007	<Null>	<Null>	<Null>	<Null>
20231008	<Null>	<Null>	<Null>	<Null>
20231009	<Null>	<Null>	<Null>	<Null>
20231010	<Null>	<Null>	<Null>	<Null>
20231011	<Null>	<Null>	<Null>	<Null>
20231012	<Null>	<Null>	<Null>	<Null>
20231013	<Null>	<Null>	<Null>	<Null>
20231014	<Null>	<Null>	<Null>	<Null>
20231015	<Null>	<Null>	<Null>	<Null>
20231017	<Null>	<Null>	<Null>	<Null>
20231018	<Null>	<Null>	<Null>	<Null>
20231019	<Null>	<Null>	<Null>	<Null>
20231020	<Null>	<Null>	<Null>	<Null>
20231021	<Null>	<Null>	<Null>	<Null>
20231022	<Null>	<Null>	<Null>	<Null>
20231023	<Null>	<Null>	<Null>	<Null>
20231024	<Null>	<Null>	<Null>	<Null>
20231025	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231026	<Null>	<Null>	<Null>	<Null>
20231027	<Null>	<Null>	<Null>	<Null>
20230609	<Null>	<Null>	<Null>	<Null>
20231028	<Null>	<Null>	<Null>	<Null>
20231029	<Null>	<Null>	<Null>	<Null>
20231030	<Null>	<Null>	<Null>	<Null>
20231031	<Null>	<Null>	<Null>	<Null>
20231032	<Null>	<Null>	<Null>	<Null>
20231033	<Null>	<Null>	<Null>	<Null>
20231034	<Null>	<Null>	<Null>	<Null>
20231035	<Null>	<Null>	<Null>	<Null>
20231036	<Null>	<Null>	<Null>	<Null>
20231037	<Null>	<Null>	<Null>	<Null>
20231038	<Null>	<Null>	<Null>	<Null>
20231039	<Null>	<Null>	<Null>	<Null>
20231040	<Null>	<Null>	<Null>	<Null>
20231041	<Null>	<Null>	<Null>	<Null>
20231042	<Null>	<Null>	<Null>	<Null>
20231043	<Null>	<Null>	<Null>	<Null>
20231044	<Null>	<Null>	<Null>	<Null>
20231045	<Null>	<Null>	<Null>	<Null>
20231046	<Null>	<Null>	<Null>	<Null>
20231047	<Null>	<Null>	<Null>	<Null>
20231048	<Null>	<Null>	<Null>	<Null>
20231049	<Null>	<Null>	<Null>	<Null>
20231050	<Null>	<Null>	<Null>	<Null>
20231051	<Null>	<Null>	<Null>	<Null>
20231052	<Null>	<Null>	<Null>	<Null>
20231053	<Null>	<Null>	<Null>	<Null>
20231054	<Null>	<Null>	<Null>	<Null>
20231055	<Null>	<Null>	<Null>	<Null>
20231056	<Null>	<Null>	<Null>	<Null>
20231057	<Null>	<Null>	<Null>	<Null>
20231058	<Null>	<Null>	<Null>	<Null>
20231059	<Null>	<Null>	<Null>	<Null>
20231060	<Null>	<Null>	<Null>	<Null>
20231061	<Null>	<Null>	<Null>	<Null>
20231062	<Null>	<Null>	<Null>	<Null>
20231063	<Null>	<Null>	<Null>	<Null>
20231064	<Null>	<Null>	<Null>	<Null>
20231065	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231066	<Null>	<Null>	<Null>	<Null>
20231067	<Null>	<Null>	<Null>	<Null>
20231068	<Null>	<Null>	<Null>	<Null>
20231069	<Null>	<Null>	<Null>	<Null>
20231070	<Null>	<Null>	<Null>	<Null>
20231071	<Null>	<Null>	<Null>	<Null>
20231072	<Null>	<Null>	<Null>	<Null>
20231073	<Null>	<Null>	<Null>	<Null>
20231074	<Null>	<Null>	<Null>	<Null>
20231075	<Null>	<Null>	<Null>	<Null>
20231076	<Null>	<Null>	<Null>	<Null>
20231077	<Null>	<Null>	<Null>	<Null>
20231078	<Null>	<Null>	<Null>	<Null>
20231079	<Null>	<Null>	<Null>	<Null>
20231080	<Null>	<Null>	<Null>	<Null>
20231081	<Null>	<Null>	<Null>	<Null>
20231082	<Null>	<Null>	<Null>	<Null>
20231083	<Null>	<Null>	<Null>	<Null>
20231084	<Null>	<Null>	<Null>	<Null>
20231085	<Null>	<Null>	<Null>	<Null>
20231086	<Null>	<Null>	<Null>	<Null>
20231087	<Null>	<Null>	<Null>	<Null>
20231088	<Null>	<Null>	<Null>	<Null>
20231089	<Null>	<Null>	<Null>	<Null>
20231090	<Null>	<Null>	<Null>	<Null>
20231091	<Null>	<Null>	<Null>	<Null>
20231092	<Null>	<Null>	<Null>	<Null>
20231093	<Null>	<Null>	<Null>	<Null>
20231094	<Null>	<Null>	<Null>	<Null>
20231095	<Null>	<Null>	<Null>	<Null>
20231096	<Null>	<Null>	<Null>	<Null>
20231097	<Null>	<Null>	<Null>	<Null>
20231098	<Null>	<Null>	<Null>	<Null>
20231099	<Null>	<Null>	<Null>	<Null>
20231100	<Null>	<Null>	<Null>	<Null>
20231101	<Null>	<Null>	<Null>	<Null>
20231102	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231103	<Null>	<Null>	<Null>	<Null>
20231104	<Null>	<Null>	<Null>	<Null>
20231105	<Null>	<Null>	<Null>	<Null>
20231106	<Null>	<Null>	<Null>	<Null>
20231107	<Null>	<Null>	<Null>	<Null>
20231108	<Null>	<Null>	<Null>	<Null>
20231109	<Null>	<Null>	<Null>	<Null>
20231110	<Null>	<Null>	<Null>	<Null>
20231111	<Null>	<Null>	<Null>	<Null>
20231112	<Null>	<Null>	<Null>	<Null>
20231113	<Null>	<Null>	<Null>	<Null>
20231114	<Null>	<Null>	<Null>	<Null>
20231115	<Null>	<Null>	<Null>	<Null>
20231116	<Null>	<Null>	<Null>	<Null>
20231117	<Null>	<Null>	<Null>	<Null>
20231118	<Null>	<Null>	<Null>	<Null>
20231119	<Null>	<Null>	<Null>	<Null>
20230607	<Null>	<Null>	<Null>	<Null>
20230599	<Null>	<Null>	<Null>	<Null>
20231120	<Null>	<Null>	<Null>	<Null>
20231121	<Null>	<Null>	<Null>	<Null>
20231122	<Null>	<Null>	<Null>	<Null>
20231123	<Null>	<Null>	<Null>	<Null>
20231124	<Null>	<Null>	<Null>	<Null>
20231125	<Null>	<Null>	<Null>	<Null>
20231126	<Null>	<Null>	<Null>	<Null>
20230439	<Null>	<Null>	<Null>	<Null>
20230398	<Null>	<Null>	<Null>	<Null>
20230456	<Null>	<Null>	<Null>	<Null>
20231127	<Null>	<Null>	<Null>	<Null>
20231128	<Null>	<Null>	<Null>	<Null>
20231129	<Null>	<Null>	<Null>	<Null>
20231130	<Null>	<Null>	<Null>	<Null>
20231131	<Null>	<Null>	<Null>	<Null>
20231132	<Null>	<Null>	<Null>	<Null>
20231133	<Null>	<Null>	<Null>	<Null>
20231134	<Null>	<Null>	<Null>	<Null>
20231135	<Null>	<Null>	<Null>	<Null>
20231136	<Null>	<Null>	<Null>	<Null>
20231137	<Null>	<Null>	<Null>	<Null>
20230442	<Null>	<Null>	<Null>	<Null>
20230282	<Null>	<Null>	<Null>	<Null>
20231138	<Null>	<Null>	<Null>	<Null>
20231139	<Null>	<Null>	<Null>	<Null>
20230854	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231016	<Null>	<Null>	<Null>	<Null>
20231140	<Null>	<Null>	<Null>	<Null>
20231144	<Null>	<Null>	<Null>	<Null>
20231141	<Null>	<Null>	<Null>	<Null>
20231142	<Null>	<Null>	<Null>	<Null>
20231143	<Null>	<Null>	<Null>	<Null>
20231146	<Null>	<Null>	<Null>	<Null>
20231145	<Null>	<Null>	<Null>	<Null>
20231152	<Null>	<Null>	<Null>	<Null>
20231151	<Null>	<Null>	<Null>	<Null>
20231150	<Null>	<Null>	<Null>	<Null>
20231149	<Null>	<Null>	<Null>	<Null>
20231148	<Null>	<Null>	<Null>	<Null>
20231147	<Null>	<Null>	<Null>	<Null>
20231153	<Null>	<Null>	<Null>	<Null>
20231154	<Null>	<Null>	<Null>	<Null>
20231155	<Null>	<Null>	<Null>	<Null>
20231156	<Null>	<Null>	<Null>	<Null>
20231157	<Null>	<Null>	<Null>	<Null>
20231158	<Null>	<Null>	<Null>	<Null>
20231159	<Null>	<Null>	<Null>	<Null>
20231160	<Null>	<Null>	<Null>	<Null>
20231161	<Null>	<Null>	<Null>	<Null>
20231162	<Null>	<Null>	<Null>	<Null>
20231163	<Null>	<Null>	<Null>	<Null>
20231164	<Null>	<Null>	<Null>	<Null>
20231165	<Null>	<Null>	<Null>	<Null>
20231166	<Null>	<Null>	<Null>	<Null>
20231167	<Null>	<Null>	<Null>	<Null>
20231168	<Null>	<Null>	<Null>	<Null>
20231169	<Null>	<Null>	<Null>	<Null>
20231170	<Null>	<Null>	<Null>	<Null>
20231171	<Null>	<Null>	<Null>	<Null>
20231172	<Null>	<Null>	<Null>	<Null>
20231173	<Null>	<Null>	<Null>	<Null>
20231174	<Null>	<Null>	<Null>	<Null>
20231175	<Null>	<Null>	<Null>	<Null>
20231176	<Null>	<Null>	<Null>	<Null>
20231177	<Null>	<Null>	<Null>	<Null>
20231178	<Null>	<Null>	<Null>	<Null>
20231179	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231180	<Null>	<Null>	<Null>	<Null>
20231181	<Null>	<Null>	<Null>	<Null>
20231182	<Null>	<Null>	<Null>	<Null>
20231183	<Null>	<Null>	<Null>	<Null>
20231184	<Null>	<Null>	<Null>	<Null>
20231185	<Null>	<Null>	<Null>	<Null>
20231186	<Null>	<Null>	<Null>	<Null>
20231187	<Null>	<Null>	<Null>	<Null>
20231188	<Null>	<Null>	<Null>	<Null>
20231189	<Null>	<Null>	<Null>	<Null>
20231190	<Null>	<Null>	<Null>	<Null>
20231191	<Null>	<Null>	<Null>	<Null>
20231192	<Null>	<Null>	<Null>	<Null>
20231193	<Null>	<Null>	<Null>	<Null>
20231194	<Null>	<Null>	<Null>	<Null>
20231195	<Null>	<Null>	<Null>	<Null>
20231196	<Null>	<Null>	<Null>	<Null>
20231197	<Null>	<Null>	<Null>	<Null>
20231198	<Null>	<Null>	<Null>	<Null>
20231199	<Null>	<Null>	<Null>	<Null>
20231200	<Null>	<Null>	<Null>	<Null>
20231201	<Null>	<Null>	<Null>	<Null>
20231202	<Null>	<Null>	<Null>	<Null>
20231203	<Null>	<Null>	<Null>	<Null>
20231204	<Null>	<Null>	<Null>	<Null>
20231205	<Null>	<Null>	<Null>	<Null>
20231206	<Null>	<Null>	<Null>	<Null>
20231207	<Null>	<Null>	<Null>	<Null>
20231208	<Null>	<Null>	<Null>	<Null>
20231209	<Null>	<Null>	<Null>	<Null>
20231210	<Null>	<Null>	<Null>	<Null>
20231211	<Null>	<Null>	<Null>	<Null>
20231212	<Null>	<Null>	<Null>	<Null>
20231213	<Null>	<Null>	<Null>	<Null>
20231214	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231215	<Null>	<Null>	<Null>	<Null>
20231216	<Null>	<Null>	<Null>	<Null>
20231217	<Null>	<Null>	<Null>	<Null>
20231218	<Null>	<Null>	<Null>	<Null>
20231219	<Null>	<Null>	<Null>	<Null>
20231220	<Null>	<Null>	<Null>	<Null>
20231221	<Null>	<Null>	<Null>	<Null>
20231222	<Null>	<Null>	<Null>	<Null>
20231223	<Null>	<Null>	<Null>	<Null>
20231224	<Null>	<Null>	<Null>	<Null>
20231225	<Null>	<Null>	<Null>	<Null>
20231226	<Null>	<Null>	<Null>	<Null>
20231227	<Null>	<Null>	<Null>	<Null>
20231228	<Null>	<Null>	<Null>	<Null>
20231229	<Null>	<Null>	<Null>	<Null>
20231230	<Null>	<Null>	<Null>	<Null>
20231231	<Null>	<Null>	<Null>	<Null>
20231232	<Null>	<Null>	<Null>	<Null>
20231233	<Null>	<Null>	<Null>	<Null>
20231234	<Null>	<Null>	<Null>	<Null>
20231235	<Null>	<Null>	<Null>	<Null>
20231236	<Null>	<Null>	<Null>	<Null>
20231237	<Null>	<Null>	<Null>	<Null>
20231238	<Null>	<Null>	<Null>	<Null>
20231239	<Null>	<Null>	<Null>	<Null>
20231240	<Null>	<Null>	<Null>	<Null>
20231241	<Null>	<Null>	<Null>	<Null>
20231242	<Null>	<Null>	<Null>	<Null>
20231243	<Null>	<Null>	<Null>	<Null>
20231244	<Null>	<Null>	<Null>	<Null>
20231245	<Null>	<Null>	<Null>	<Null>
20231246	<Null>	<Null>	<Null>	<Null>
20231247	<Null>	<Null>	<Null>	<Null>
20231248	<Null>	<Null>	<Null>	<Null>
20231249	<Null>	<Null>	<Null>	<Null>
20231250	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231251	<Null>	<Null>	<Null>	<Null>
20231252	<Null>	<Null>	<Null>	<Null>
20231253	<Null>	<Null>	<Null>	<Null>
20231254	<Null>	<Null>	<Null>	<Null>
20231255	<Null>	<Null>	<Null>	<Null>
20231256	<Null>	<Null>	<Null>	<Null>
20231257	<Null>	<Null>	<Null>	<Null>
20231258	<Null>	<Null>	<Null>	<Null>
20231259	<Null>	<Null>	<Null>	<Null>
20231260	<Null>	<Null>	<Null>	<Null>
20231261	<Null>	<Null>	<Null>	<Null>
20231262	<Null>	<Null>	<Null>	<Null>
20231263	<Null>	<Null>	<Null>	<Null>
20231264	<Null>	<Null>	<Null>	<Null>
20230792	<Null>	<Null>	<Null>	<Null>
20231265	<Null>	<Null>	<Null>	<Null>
20231266	<Null>	<Null>	<Null>	<Null>
20231267	<Null>	<Null>	<Null>	<Null>
20231268	<Null>	<Null>	<Null>	<Null>
20231269	<Null>	<Null>	<Null>	<Null>
20231270	<Null>	<Null>	<Null>	<Null>
20231271	<Null>	<Null>	<Null>	<Null>
20231272	<Null>	<Null>	<Null>	<Null>
20230791	<Null>	<Null>	<Null>	<Null>
20231273	<Null>	<Null>	<Null>	<Null>
20230789	<Null>	<Null>	<Null>	<Null>
20231274	<Null>	<Null>	<Null>	<Null>
20231275	<Null>	<Null>	<Null>	<Null>
20231276	<Null>	<Null>	<Null>	<Null>
20231277	<Null>	<Null>	<Null>	<Null>
20231278	<Null>	<Null>	<Null>	<Null>
20231279	<Null>	<Null>	<Null>	<Null>
20231280	<Null>	<Null>	<Null>	<Null>
20230788	<Null>	<Null>	<Null>	<Null>
20231281	<Null>	<Null>	<Null>	<Null>
20231282	<Null>	<Null>	<Null>	<Null>
20231283	<Null>	<Null>	<Null>	<Null>
20231284	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231285	<Null>	<Null>	<Null>	<Null>
20231286	<Null>	<Null>	<Null>	<Null>
20231287	<Null>	<Null>	<Null>	<Null>
20231288	<Null>	<Null>	<Null>	<Null>
20231289	<Null>	<Null>	<Null>	<Null>
20231290	<Null>	<Null>	<Null>	<Null>
20231291	<Null>	<Null>	<Null>	<Null>
20231292	<Null>	<Null>	<Null>	<Null>
20231293	<Null>	<Null>	<Null>	<Null>
20231294	<Null>	<Null>	<Null>	<Null>
20231295	<Null>	<Null>	<Null>	<Null>
20231296	<Null>	<Null>	<Null>	<Null>
20231297	<Null>	<Null>	<Null>	<Null>
20231298	<Null>	<Null>	<Null>	<Null>
20231299	<Null>	<Null>	<Null>	<Null>
20231300	<Null>	<Null>	<Null>	<Null>
20231301	<Null>	<Null>	<Null>	<Null>
20231302	<Null>	<Null>	<Null>	<Null>
20231303	<Null>	<Null>	<Null>	<Null>
20231304	<Null>	<Null>	<Null>	<Null>
20231305	<Null>	<Null>	<Null>	<Null>
20231306	<Null>	<Null>	<Null>	<Null>
20231307	<Null>	<Null>	<Null>	<Null>
20231308	<Null>	<Null>	<Null>	<Null>
20231309	<Null>	<Null>	<Null>	<Null>
20231310	<Null>	<Null>	<Null>	<Null>
20231311	<Null>	<Null>	<Null>	<Null>
20231312	<Null>	<Null>	<Null>	<Null>
20231313	<Null>	<Null>	<Null>	<Null>
20231314	<Null>	<Null>	<Null>	<Null>
20231315	<Null>	<Null>	<Null>	<Null>
20231316	<Null>	<Null>	<Null>	<Null>
20231317	<Null>	<Null>	<Null>	<Null>
20231325	<Null>	<Null>	<Null>	<Null>
20231318	<Null>	<Null>	<Null>	<Null>
20231319	<Null>	<Null>	<Null>	<Null>
20231320	<Null>	<Null>	<Null>	<Null>
20231321	<Null>	<Null>	<Null>	<Null>
20231322	<Null>	<Null>	<Null>	<Null>
20231323	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231324	<Null>	<Null>	<Null>	<Null>
20231326	<Null>	<Null>	<Null>	<Null>
20231327	<Null>	<Null>	<Null>	<Null>
20231328	<Null>	<Null>	<Null>	<Null>
20231329	<Null>	<Null>	<Null>	<Null>
20231330	<Null>	<Null>	<Null>	<Null>
20231331	<Null>	<Null>	<Null>	<Null>
20231332	<Null>	<Null>	<Null>	<Null>
20231333	<Null>	<Null>	<Null>	<Null>
20231334	<Null>	<Null>	<Null>	<Null>
20231335	<Null>	<Null>	<Null>	<Null>
20231336	<Null>	<Null>	<Null>	<Null>
20231337	<Null>	<Null>	<Null>	<Null>
20231338	<Null>	<Null>	<Null>	<Null>
20231339	<Null>	<Null>	<Null>	<Null>
20231340	<Null>	<Null>	<Null>	<Null>
20231341	<Null>	<Null>	<Null>	<Null>
20231342	<Null>	<Null>	<Null>	<Null>
20231343	<Null>	<Null>	<Null>	<Null>
20231344	<Null>	<Null>	<Null>	<Null>
20231345	<Null>	<Null>	<Null>	<Null>
20231346	<Null>	<Null>	<Null>	<Null>
20231347	<Null>	<Null>	<Null>	<Null>
20231348	<Null>	<Null>	<Null>	<Null>
20231349	<Null>	<Null>	<Null>	<Null>
20231350	<Null>	<Null>	<Null>	<Null>
20231351	<Null>	<Null>	<Null>	<Null>
20231352	<Null>	<Null>	<Null>	<Null>
20231353	<Null>	<Null>	<Null>	<Null>
20231355	<Null>	<Null>	<Null>	<Null>
20231356	<Null>	<Null>	<Null>	<Null>
20231358	<Null>	<Null>	<Null>	<Null>
20231357	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory

TSI_Curb_Ramp_ID	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number	MEF_Documentation
20231359	<Null>	<Null>	<Null>	<Null>
20231360	<Null>	<Null>	<Null>	<Null>
20231361	<Null>	<Null>	<Null>	<Null>
20231362	<Null>	<Null>	<Null>	<Null>
20231363	<Null>	<Null>	<Null>	<Null>
20231364	<Null>	<Null>	<Null>	<Null>
20231365	<Null>	<Null>	<Null>	<Null>
20231366	<Null>	<Null>	<Null>	<Null>
20230784	<Null>	<Null>	<Null>	<Null>
20230783	<Null>	<Null>	<Null>	<Null>
20230782	<Null>	<Null>	<Null>	<Null>
20230408	<Null>	<Null>	<Null>	<Null>
20230790	<Null>	<Null>	<Null>	<Null>
20230409	<Null>	<Null>	<Null>	<Null>
20230275	<Null>	<Null>	<Null>	<Null>
20230281	<Null>	<Null>	<Null>	<Null>
20230135	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory - 38 Other Ramps

OBJECTID *	SHAPE *	TSI_Curb_Ramp_ID	Grade	Condition *	Ramp_Width	DWS	Ramp_Type	Running_Slope	Cross_Slope	Landing
227	Point M	20230446	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
425	Point M	20230279	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
426	Point M	20230278	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
450	Point M	20230280	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
451	Point M	20230431	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
556	Point M	20230551	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
612	Point M	20230606	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
614	Point M	20230608	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
780	Point M	20230771	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
781	Point M	20230772	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
782	Point M	20230773	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
783	Point M	20230774	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
784	Point M	20230775	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
785	Point M	20230776	<Null>	Other	<Null>	<Null>	Blended Transition	<Null>	<Null>	<Null>
802	Point M	20231379	<Null>	Other	<Null>	<Null>	Blended Transition	<Null>	<Null>	<Null>
803	Point M	20231378	<Null>	Other	<Null>	<Null>	Blended Transition	<Null>	<Null>	<Null>
804	Point M	20231377	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
805	Point M	20231376	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
806	Point M	20231375	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
807	Point M	20231374	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
850	Point M	20230834	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
851	Point M	20230835	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
864	Point M	20230848	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
865	Point M	20230849	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
892	Point M	20231371	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
893	Point M	20231370	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
938	Point M	20230914	<Null>	Other	<Null>	No DWS (Non-Compliant)	<Null>	<Null>	<Null>	<Null>
939	Point M	20230915	<Null>	Other	60" or greater	<Null>	<Null>	<Null>	<Null>	<Null>
1008	Point M	20230984	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
1009	Point M	20230985	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
1154	Point M	20230542	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
1155	Point M	20230443	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
1165	Point M	20230457	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
1181	Point M	20230283	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
1353	Point M	20230787	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
1418	Point M	20230786	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
1419	Point M	20230785	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>
1423	Point M	20230781	<Null>	Other	<Null>	<Null>	<Null>	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory - 38 Other Ramps

TSI_Curb_Ramp_ID	Notes	TSI_ADA_Compliant *	GlobalID *	July2023_Snoq_Parkwy_Rehab	Alt_ID	Alt_ID_Number
20230446	No DWS and no PAR route to golf course driveway. Consider relocating crosswalk or creating PAR to golf course.	No	{02176480-25CA-4142-A507-AA5265D59F63}	<Null>	<Null>	<Null>
20230279	Included since pedestrians use corridor. Consider DWS.	<Null>	{60650117-80BD-4EBD-81EB-B4F1034DB7ED}	<Null>	<Null>	<Null>
20230278	Included since pedestrians use corridor. Consider DWS.	<Null>	{7613CCCA-0DDF-48E0-A328-D0349AB2ED57}	<Null>	<Null>	<Null>
20230280	Included since pedestrians use corridor. Consider DWS	<Null>	{F789FD0E-73A5-4C71-84B0-D841FAC65811}	<Null>	<Null>	<Null>
20230431	Included since pedestrians use corridor. Consider DWS.	<Null>	{CA097DB9-886A-46B8-A095-B2C3472421E0}	<Null>	<Null>	<Null>
20230551	Sidewalk ends in ledge. Needs PAR barricade.	No	{A78A6DEA-15C1-4AF7-B830-F0264779D5E6}	<Null>	<Null>	<Null>
20230606	No PAR barricade	No	{EB0C09A9-A47E-4281-AF60-7B2CCACB9075}	<Null>	<Null>	<Null>
20230608	No PAR barricade	No	{142EE42C-FDC3-4E76-B524-3CEC13A1B2DA}	<Null>	<Null>	<Null>
20230771	Is this a non-compliance issue?	<Null>	{B2D90ACF-1611-471C-8B74-F943BE282206}	<Null>	<Null>	<Null>
20230772	Is this a non-compliance issue?	<Null>	{CC822049-EA10-4BA0-A699-EA38BED9DA60}	<Null>	<Null>	<Null>
20230773	Is this a non-compliance issue?	<Null>	{C9D3052E-795E-48C4-AAC5-A7158905C300}	<Null>	<Null>	<Null>
20230774	Is this a non-compliance issue?	<Null>	{B6DF5113-D35E-4E72-AEF4-30BB7E57E18A}	<Null>	<Null>	<Null>
20230775	<Null>	<Null>	{7D2C9A1F-7153-4F87-9A08-DC6772210172}	<Null>	<Null>	<Null>
20230776	Is this a non-compliance issue?	<Null>	{33015A4D-0202-4025-BB10-256058F0C78D}	<Null>	<Null>	<Null>
20231379	Is this a non-compliance issue?	<Null>	{13393679-2CB8-4790-A146-9A2CB6F9739E}	<Null>	<Null>	<Null>
20231378	Is this a non-compliance issue?	<Null>	{54383F24-53C7-482D-95CB-B71C1F6F2683}	<Null>	<Null>	<Null>
20231377	Is this a non-compliance issue?	<Null>	{9B58BDAD-D828-44EE-A5C6-233593B5DF0D}	<Null>	<Null>	<Null>
20231376	Is this a non-compliance issue?	<Null>	{A09E5C56-E9A2-40D7-B229-B97C7439C760}	<Null>	<Null>	<Null>
20231375	Is this a non-compliance issue?	<Null>	{C6925A0A-5641-470A-B3F1-D92FFF48A438}	<Null>	<Null>	<Null>
20231374	Is this a non-compliance issue?	<Null>	{1732F57B-EADF-4146-B6B4-18E8A57F48DE}	<Null>	<Null>	<Null>
20230834	Golf cart crossing. Consider DWS.	<Null>	{41A81E02-970C-4C5B-839C-D4B5D900156E}	<Null>	<Null>	<Null>
20230835	Golf cart crossing. Consider DWS.	<Null>	{FF20A5D5-6DB4-469E-8F17-2598AC9EDBC2}	<Null>	<Null>	<Null>
20230848	No PAR barricade	No	{87FDB190-0BC6-4420-880E-B336123A365C}	<Null>	<Null>	<Null>
20230849	No PAR barricade	No	{0E7C8786-00A1-4338-93C6-BF8CD45ADD71}	<Null>	<Null>	<Null>
20231371	Golf cart crossing. Consider DWS	<Null>	{520C325A-4310-4B85-A03D-E2E3723940F7}	<Null>	<Null>	<Null>
20231370	Golf cart crossing. Consider DWS	<Null>	{BCFDD56F-D014-4888-8DD0-F50C2C9C7AB1}	<Null>	<Null>	<Null>
20230914	Golf cart crossing. Consider DWS	<Null>	{6F53CEA3-84B5-445A-AD01-1CCCC5A3484}	<Null>	<Null>	<Null>
20230915	Golf cart crossing. Consider DWS. Crack in PAR. Minor curb lip	<Null>	{63ECF14A-B880-4079-9094-4435D7F1E07D}	<Null>	<Null>	<Null>
20230984	Golf cart crossing. Consider DWS	<Null>	{F7B419D5-53EB-412F-AC36-AB0DA65C56B9}	<Null>	<Null>	<Null>
20230985	Golf cart crossing. Consider DWS	<Null>	{43B3C03E-5388-42BC-ADB8-4A24FA409E8A}	<Null>	<Null>	<Null>
20230542	No PAR barricade	No	{836DA46E-897D-4728-920F-FFB01C742F88}	<Null>	<Null>	<Null>
20230443	No PAR barricade	No	{637861DA-B1A2-40ED-ACE4-4D2C30141A3F}	<Null>	<Null>	<Null>
20230457	No PAR barricade.	No	{E378B01C-8C51-4C9F-91B1-8CCA8C7F2D07}	<Null>	<Null>	<Null>
20230283	No PAR barricade. Sidewalk leads to embankment and river	No	{78213713-EDE6-42CB-9ED9-D8B1FD298B81}	<Null>	<Null>	<Null>
20230787	No PAR barricade or remove panel beyond ramp landing.	No	{0E490225-8024-4728-807C-C0E7610C93DE}	<Null>	<Null>	<Null>
20230786	No PAR barricade	No	{8194D3D7-C04E-42CA-BD82-816A29C731EF}	<Null>	<Null>	<Null>
20230785	No PAR barricade	No	{4EE0F1AB-C40F-473D-9369-4B06899426C7}	<Null>	<Null>	<Null>
20230781	No PAR barricade or continue PAR around cul-de-sac	No	{C0B7BF1B-CB02-4A1F-9659-914A922152D9}	<Null>	<Null>	<Null>

City of Snoqualmie
2023 ADA Curb Ramp Inventory - 38 Other Ramps

TSI_Curb_Ramp_ID	MEF_Documentation
20230446	<Null>
20230279	<Null>
20230278	<Null>
20230280	<Null>
20230431	<Null>
20230551	<Null>
20230606	<Null>
20230608	<Null>
20230771	<Null>
20230772	<Null>
20230773	<Null>
20230774	<Null>
20230775	<Null>
20230776	<Null>
20231379	<Null>
20231378	<Null>
20231377	<Null>
20231376	<Null>
20231375	<Null>
20231374	<Null>
20230834	<Null>
20230835	<Null>
20230848	<Null>
20230849	<Null>
20231371	<Null>
20231370	<Null>
20230914	<Null>
20230915	<Null>
20230984	<Null>
20230985	<Null>
20230542	<Null>
20230443	<Null>
20230457	<Null>
20230283	<Null>
20230787	<Null>
20230786	<Null>
20230785	<Null>
20230781	<Null>

APS/RRFB/HAWK GIS INVENTORY

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

OBJECTID *	Shape *	Intersection_Control_Type	TSI_Intersection_ID	TSI_APS_RRFB_HAWK_ID	TSI_APS_RRFB_HAWK_NO	Cross_Street_1	Cross_Street_2
27	Point	Signalized Intersection	1	TSI_APS_RRFB_HAWK_001_NW_Corner_SB	1	Snoqualmie Parkway	SE Jacobia St
28	Point	Signalized Intersection	1	TSI_APS_RRFB_HAWK_002_NW_Corner_EB	2	Snoqualmie Parkway	SE Jacobia St
29	Point	Signalized Intersection	1	TSI_APS_RRFB_HAWK_003_NE_Corner_WB	3	Snoqualmie Parkway	SE Jacobia St
30	Point	Signalized Intersection	1	TSI_APS_RRFB_HAWK_004_NE_Corner_SB	4	Snoqualmie Parkway	SE Jacobia St
31	Point	Signalized Intersection	1	TSI_APS_RRFB_HAWK_005_SE_Corner_NB	5	Snoqualmie Parkway	SE Jacobia St
32	Point	Signalized Intersection	1	TSI_APS_RRFB_HAWK_006_SE_Corner_WB	6	Snoqualmie Parkway	SE Jacobia St
33	Point	Signalized Intersection	1	TSI_APS_RRFB_HAWK_007_SW_Corner_EB	7	Snoqualmie Parkway	SE Jacobia St
34	Point	Signalized Intersection	1	TSI_APS_RRFB_HAWK_008_SW_Corner_NB	8	Snoqualmie Parkway	SE Jacobia St
35	Point	Signalized Intersection	2	TSI_APS_RRFB_HAWK_009_NW_Corner_SB	9	Snoqualmie Parkway	SE Swenson Dr
36	Point	Signalized Intersection	2	TSI_APS_RRFB_HAWK_010_NW_Corner_EB	10	Snoqualmie Parkway	SE Swenson Dr
37	Point	Signalized Intersection	2	TSI_APS_RRFB_HAWK_011_NE_Corner_WB	11	Snoqualmie Parkway	SE Swenson Dr
38	Point	Signalized Intersection	2	TSI_APS_RRFB_HAWK_012_NE_Corner_SB	12	Snoqualmie Parkway	SE Swenson Dr
39	Point	Signalized Intersection	2	TSI_APS_RRFB_HAWK_013_SE_Corner_NB	13	Snoqualmie Parkway	SE Swenson Dr
40	Point	Signalized Intersection	2	TSI_APS_RRFB_HAWK_014_SE_Corner_WB	14	Snoqualmie Parkway	SE Swenson Dr
41	Point	Signalized Intersection	2	TSI_APS_RRFB_HAWK_015_SW_Corner_EB	15	Snoqualmie Parkway	SE Swenson Dr
42	Point	Signalized Intersection	2	TSI_APS_RRFB_HAWK_016_SW_Corner_NB	16	Snoqualmie Parkway	SE Swenson Dr
43	Point	Signalized Intersection	3	TSI_APS_RRFB_HAWK_017_NE_Corner_WB	17	Snoqualmie Parkway	Douglas Ave SE
44	Point	Signalized Intersection	3	TSI_APS_RRFB_HAWK_018_NE_Corner_SB	18	Snoqualmie Parkway	Douglas Ave SE
45	Point	Signalized Intersection	3	TSI_APS_RRFB_HAWK_019_SE_Corner_NB	19	Snoqualmie Parkway	SE Douglas St
46	Point	Signalized Intersection	3	TSI_APS_RRFB_HAWK_020_SE_Corner_WB	20	Snoqualmie Parkway	SE Douglas St
47	Point	Signalized Intersection	3	TSI_APS_RRFB_HAWK_021_SW_Corner_EB	21	Snoqualmie Parkway	SE Douglas St
48	Point	Signalized Intersection	3	TSI_APS_RRFB_HAWK_022_SW_Corner_NB	22	Snoqualmie Parkway	SE Douglas St
49	Point	Signalized Intersection	3	TSI_APS_RRFB_HAWK_023_NW_Corner_SB	23	Snoqualmie Parkway	SE Douglas Ave
50	Point	Signalized Intersection	3	TSI_APS_RRFB_HAWK_024_NW_Corner_EB	24	Snoqualmie Parkway	SE Douglas Ave
51	Point	Signalized Intersection	4	TSI_APS_RRFB_HAWK_025_NE_Corner_WB	25	Snoqualmie Parkway	SE Center Blvd SE
52	Point	Signalized Intersection	4	TSI_APS_RRFB_HAWK_026_NE_Corner_SB	26	Snoqualmie Parkway	SE Center Blvd SE
53	Point	Signalized Intersection	4	TSI_APS_RRFB_HAWK_027_SE_Corner_NB	27	Snoqualmie Parkway	SE Center St
54	Point	Signalized Intersection	4	TSI_APS_RRFB_HAWK_028_SE_Corner_WB	28	Snoqualmie Parkway	SE Center St

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

OBJECTID *	Shape *	Intersection_Control_Type	TSI_Intersection_ID	TSI_APS_RRFB_HAWK_ID	TSI_APS_RRFB_HAWK_NO	Cross_Street_1	Cross_Street_2
55	Point	Signalized Intersection	4	TSI_APS_RRFB_HAWK_029_SW_Corner_EB	29	Snoqualmie Parkway	SE Center St
56	Point	Signalized Intersection	4	TSI_APS_RRFB_HAWK_030_SW_Corner_NB	30	Snoqualmie Parkway	SE Center St
57	Point	Signalized Intersection	4	TSI_APS_RRFB_HAWK_031_NW_Corner_SB	31	Snoqualmie Parkway	SE Center Blvd SE
58	Point	Signalized Intersection	4	TSI_APS_RRFB_HAWK_032_NW_Corner_EB	32	Snoqualmie Parkway	SE Center Blvd SE
59	Point	Signalized Intersection	5	TSI_APS_RRFB_HAWK_033_NE_Corner_WB	33	Snoqualmie Parkway	Fairway Ave SE
60	Point	Signalized Intersection	5	TSI_APS_RRFB_HAWK_034_NE_Corner_SB	34	Snoqualmie Parkway	Fairway Ave SE
61	Point	Signalized Intersection	5	TSI_APS_RRFB_HAWK_035_SE_Corner_NB	35	Snoqualmie Parkway	Fairway Ave SE
62	Point	Signalized Intersection	5	TSI_APS_RRFB_HAWK_036_NW_Corner_EB	36	Snoqualmie Parkway	Fairway Ave SE
15	Point	Signalized Intersection	6	TSI_APS_RRFB_HAWK_037_NE_Corner_WB	37	Snoqualmie Parkway	Better Way SE
16	Point	Signalized Intersection	6	TSI_APS_RRFB_HAWK_038_NE_Corner_SB	38	Snoqualmie Parkway	Better Way SE
19	Point	Signalized Intersection	6	TSI_APS_RRFB_HAWK_039_SE_Corner_NB	39	Snoqualmie Parkway	Better Way SE
20	Point	Signalized Intersection	6	TSI_APS_RRFB_HAWK_040_SE_Corner_WB	40	Snoqualmie Parkway	Better Way SE
21	Point	Signalized Intersection	6	TSI_APS_RRFB_HAWK_041_SW_Corner_EB	41	Snoqualmie Parkway	Better Way SE
22	Point	Signalized Intersection	6	TSI_APS_RRFB_HAWK_042_SW_Corner_NB	42	Snoqualmie Parkway	Better Way SE
18	Point	Signalized Intersection	6	TSI_APS_RRFB_HAWK_043_NW_Corner_SB	43	Snoqualmie Parkway	Better Way SE
17	Point	Signalized Intersection	6	TSI_APS_RRFB_HAWK_044_NW_Corner_EB	44	Snoqualmie Parkway	Better Way SE
26	Point	Signalized Intersection	7	TSI_APS_RRFB_HAWK_045_SE_Corner_WB	45	Snoqualmie Parkway	Railroad Ave
25	Point	Signalized Intersection	7	TSI_APS_RRFB_HAWK_046_SW_Corner_EB	46	Snoqualmie Parkway	Railroad Ave
24	Point	Signalized Intersection	7	TSI_APS_RRFB_HAWK_047_SW_Corner_NB	47	Snoqualmie Parkway	Railroad Ave
23	Point	Signalized Intersection	7	TSI_APS_RRFB_HAWK_048_NW_Corner_SB	48	Snoqualmie Parkway	Railroad Ave
63	Point	Signalized Intersection	8	TSI_APS_RRFB_HAWK_049_NE_Corner_WB	49	Railroad Ave	Meadowbrook Way SE
71	Point	Signalized Intersection	8	TSI_APS_RRFB_HAWK_050_NE_Corner_SB	50	Railroad Ave	Meadowbrook Way SE
70	Point	Signalized Intersection	8	TSI_APS_RRFB_HAWK_051_SE_Corner_NB	51	Railroad Ave	Meadowbrook Way SE
69	Point	Signalized Intersection	8	TSI_APS_RRFB_HAWK_052_SE_Corner_WB	52	Railroad Ave	Meadowbrook Way SE
68	Point	Signalized Intersection	8	TSI_APS_RRFB_HAWK_053_SW_Corner_EB	53	Railroad Ave	Meadowbrook Way SE
66	Point	Signalized Intersection	8	TSI_APS_RRFB_HAWK_054_SW_Corner_NB	54	Railroad Ave	Meadowbrook Way SE
65	Point	Signalized Intersection	8	TSI_APS_RRFB_HAWK_055_NW_Corner_SB	55	Railroad Ave	Meadowbrook Way SE
64	Point	Signalized Intersection	8	TSI_APS_RRFB_HAWK_056_NW_Corner_EB	56	Railroad Ave	Meadowbrook Way SE
72	Point	RRFB	9	TSI_APS_RRFB_HAWK_057_NE_Corner_WB	57	Railroad Ave	SE King St
74	Point	RRFB	9	TSI_APS_RRFB_HAWK_058_SE_Corner_WB	58	Railroad Ave	SE King St
75	Point	RRFB	9	TSI_APS_RRFB_HAWK_059_SW_Corner_EB	59	Railroad Ave	SE King St
73	Point	RRFB	9	TSI_APS_RRFB_HAWK_060_NW_Corner_EB	60	Railroad Ave	SE King St
76	Point	RRFB	10	TSI_APS_RRFB_HAWK_061_E_Corner_WB	61	Railroad Ave	Midblock between SE King St and River St
77	Point	RRFB	10	TSI_APS_RRFB_HAWK_062_W_Corner_EB	62	Railroad Ave	Midblock between SE King St and River St
78	Point	RRFB	11	TSI_APS_RRFB_HAWK_063_NE_Corner_WB	63	Railroad Ave	River St
80	Point	RRFB	11	TSI_APS_RRFB_HAWK_064_SE_Corner_WB	64	Railroad Ave	River St

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

OBJECTID *	Shape *	Intersection_Control_Type	TSI_Intersection_ID	TSI_APS_RRFB_HAWK_ID	TSI_APS_RRFB_HAWK_NO	Cross_Street_1	Cross_Street_2
81	Point	RRFB	11	TSI_APS_RRFB_HAWK_065_SW_Corner_EB	65	Railroad Ave	River St
79	Point	RRFB	11	TSI_APS_RRFB_HAWK_066_NW_Corner_EB	66	Railroad Ave	River St
82	Point	HAWK	12	TSI_APS_RRFB_HAWK_067_NW_Corner_SB	67	Snoqualmie Parkway	Fisher Ave
83	Point	HAWK	12	TSI_APS_RRFB_HAWK_068_SW_Corner_NB	68	Snoqualmie Parkway	Fisher Ave

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	APS_Crossing_Type	Field_Eval_Date	Corner	Crossing_Direction	Q1_PB_APS_Compliant	Q2_Dir_Arrow_Parallel_XWalk	Q3_PB_Height_42in_Above_PAR
TSI_APS_RRFB_HAWK_001_NW_Corner_SB	APS	2/1/2023	Northwest	SB	Yes	Yes	No
TSI_APS_RRFB_HAWK_002_NW_Corner_EB	APS	2/1/2023	Northwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_003_NE_Corner_WB	APS	2/1/2023	Northeast	WB	Yes	Yes	No
TSI_APS_RRFB_HAWK_004_NE_Corner_SB	APS	2/1/2023	Northeast	SB	Yes	Yes	No
TSI_APS_RRFB_HAWK_005_SE_Corner_NB	APS	2/1/2023	Southeast	NB	Yes	Yes	No
TSI_APS_RRFB_HAWK_006_SE_Corner_WB	APS	2/1/2023	Southeast	WB	Yes	Yes	No
TSI_APS_RRFB_HAWK_007_SW_Corner_EB	APS	2/1/2023	Southwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_008_SW_Corner_NB	APS	2/1/2023	Southwest	NB	Yes	Yes	No
TSI_APS_RRFB_HAWK_009_NW_Corner_SB	APS	2/1/2023	Northwest	SB	Yes	Yes	No
TSI_APS_RRFB_HAWK_010_NW_Corner_EB	APS	2/1/2023	Northwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_011_NE_Corner_WB	APS	2/1/2023	Northeast	WB	Yes	No	No
TSI_APS_RRFB_HAWK_012_NE_Corner_SB	APS	2/1/2023	Northeast	SB	Yes	No	No
TSI_APS_RRFB_HAWK_013_SE_Corner_NB	APS	2/1/2023	Southeast	NB	Yes	No	No
TSI_APS_RRFB_HAWK_014_SE_Corner_WB	APS	2/1/2023	Southeast	WB	Yes	Yes	No
TSI_APS_RRFB_HAWK_015_SW_Corner_EB	APS	2/1/2023	Southwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_016_SW_Corner_NB	APS	2/1/2023	Southwest	NB	Yes	Yes	No
TSI_APS_RRFB_HAWK_017_NE_Corner_WB	APS	2/1/2023	Northeast	WB	Yes	Yes	No
TSI_APS_RRFB_HAWK_018_NE_Corner_SB	APS	2/1/2023	Northeast	SB	Yes	Yes	No
TSI_APS_RRFB_HAWK_019_SE_Corner_NB	APS	2/1/2023	Southeast	NB	Yes	No	No
TSI_APS_RRFB_HAWK_020_SE_Corner_WB	APS	2/1/2023	Southeast	WB	Yes	Yes	No
TSI_APS_RRFB_HAWK_021_SW_Corner_EB	APS	2/1/2023	Southwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_022_SW_Corner_NB	APS	2/1/2023	Southwest	NB	Yes	Yes	No
TSI_APS_RRFB_HAWK_023_NW_Corner_SB	APS	2/1/2023	Northwest	SB	Yes	Yes	No
TSI_APS_RRFB_HAWK_024_NW_Corner_EB	APS	2/1/2023	Northwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_025_NE_Corner_WB	APS	2/1/2023	Northeast	WB	Yes	Yes	No
TSI_APS_RRFB_HAWK_026_NE_Corner_SB	APS	2/1/2023	Northeast	SB	Yes	Yes	No
TSI_APS_RRFB_HAWK_027_SE_Corner_NB	APS	2/1/2023	Southeast	NB	Yes	Yes	No
TSI_APS_RRFB_HAWK_028_SE_Corner_WB	APS	2/1/2023	Southeast	WB	Yes	Yes	No

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	APS_Crossing_Type	Field_Eval_Date	Corner	Crossing_Direction	Q1_PB_APS_Compliant	Q2_Dir_Arrow_Parallel_XWalk	Q3_PB_Height_42in_Above_PAR
TSI_APS_RRFB_HAWK_029_SW_Corner_EB	APS	2/1/2023	Southwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_030_SW_Corner_NB	APS	2/1/2023	Southwest	NB	Yes	Yes	No
TSI_APS_RRFB_HAWK_031_NW_Corner_SB	APS	2/1/2023	Northwest	SB	Yes	Yes	No
TSI_APS_RRFB_HAWK_032_NW_Corner_EB	APS	2/1/2023	Northwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_033_NE_Corner_WB	APS	2/1/2023	Northeast	WB	Yes	Yes	No
TSI_APS_RRFB_HAWK_034_NE_Corner_SB	APS	2/1/2023	Northeast	SB	Yes	Yes	No
TSI_APS_RRFB_HAWK_035_SE_Corner_NB	APS	2/1/2023	Southeast	NB	Yes	Yes	No
TSI_APS_RRFB_HAWK_036_NW_Corner_EB	APS	2/1/2023	Northwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_037_NE_Corner_WB	APS	1/26/2023	Northeast	WB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_038_NE_Corner_SB	APS	1/26/2023	Northeast	SB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_039_SE_Corner_NB	APS	1/26/2023	Southeast	NB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_040_SE_Corner_WB	APS	1/26/2023	Southeast	WB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_041_SW_Corner_EB	APS	1/26/2023	Southwest	EB	Yes	Yes	No
TSI_APS_RRFB_HAWK_042_SW_Corner_NB	APS	1/26/2023	Southwest	NB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_043_NW_Corner_SB	APS	1/26/2023	Northwest	SB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_044_NW_Corner_EB	APS	1/26/2023	Northwest	EB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_045_SE_Corner_WB	APS	1/26/2023	Southeast	WB	Yes	Yes	No
TSI_APS_RRFB_HAWK_046_SW_Corner_EB	APS	1/26/2023	Southwest	EB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_047_SW_Corner_NB	APS	1/26/2023	Southwest	NB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_048_NW_Corner_SB	APS	1/26/2023	Northwest	SB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_049_NE_Corner_WB	APS	1/26/2023	Northeast	WB	No	No Arrow	Yes
TSI_APS_RRFB_HAWK_050_NE_Corner_SB	APS	1/26/2023	Northeast	SB	No	No Arrow	Yes
TSI_APS_RRFB_HAWK_051_SE_Corner_NB	APS	1/26/2023	Southeast	NB	No	No Arrow	Yes
TSI_APS_RRFB_HAWK_052_SE_Corner_WB	APS	1/26/2023	Southeast	WB	No	No Arrow	Yes
TSI_APS_RRFB_HAWK_053_SW_Corner_EB	APS	1/26/2023	Southwest	EB	No	No Arrow	Yes
TSI_APS_RRFB_HAWK_054_SW_Corner_NB	APS	1/26/2023	Southwest	NB	No	No Arrow	No
TSI_APS_RRFB_HAWK_055_NW_Corner_SB	APS	1/26/2023	Northwest	SB	No	No Arrow	Yes
TSI_APS_RRFB_HAWK_056_NW_Corner_EB	APS	1/26/2023	Northwest	EB	No	No Arrow	Yes
TSI_APS_RRFB_HAWK_057_NE_Corner_WB	RRFB	1/26/2023	Northeast	WB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_058_SE_Corner_WB	RRFB	1/26/2023	Southeast	WB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_059_SW_Corner_EB	RRFB	1/26/2023	Southwest	EB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_060_NW_Corner_EB	RRFB	1/26/2023	Northwest	EB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_061_E_Corner_WB	RRFB	1/26/2023	East	WB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_062_W_Corner_EB	RRFB	1/26/2023	West	EB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_063_NE_Corner_WB	RRFB	1/26/2023	Northeast	WB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_064_SE_Corner_WB	RRFB	1/26/2023	Southeast	WB	Yes	Yes	Yes

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	APS_Crossing_Type	Field_Eval_Date	Corner	Crossing_Direction	Q1_PB_APS_Compliant	Q2_Dir_Arrow_Parallel_XWalk	Q3_PB_Height_42in_Above_PAR
TSI_APS_RRFB_HAWK_065_SW_Corner_EB	RRFB	1/26/2023	Southwest	EB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_066_NW_Corner_EB	RRFB	1/26/2023	Northwest	EB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_067_NW_Corner_SB	HAWK	1/26/2023	Northwest	SB	Yes	Yes	Yes
TSI_APS_RRFB_HAWK_068_SW_Corner_NB	HAWK	1/26/2023	Southwest	NB	Yes	Yes	Yes

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q4_PB_Height_in_Above_PAR	Q5_PB_to_CurbLine_18in_to_6Ft	Q6_PB_to_Curb_UptoMax10Ft	Q7_PB_to_XWalk_Line_Upto5Ft	Q8_PROWAG_Clear_32in_by_54in
TSI_APS_RRFB_HAWK_001_NW_Corner_SB	38	No	15'	Yes	60"x60"
TSI_APS_RRFB_HAWK_002_NW_Corner_EB	38	No	15'	Yes	60"x60"
TSI_APS_RRFB_HAWK_003_NE_Corner_WB	34	No	12'	Yes	48"x60"
TSI_APS_RRFB_HAWK_004_NE_Corner_SB	34	No	11'	Yes	48"x60"
TSI_APS_RRFB_HAWK_005_SE_Corner_NB	39	No	13'	Yes	60"x60"
TSI_APS_RRFB_HAWK_006_SE_Corner_WB	33	No	11'	Yes	52"x60"
TSI_APS_RRFB_HAWK_007_SW_Corner_EB	40	No	15'	Yes	60"x60"
TSI_APS_RRFB_HAWK_008_SW_Corner_NB	33	No	11'	Yes	52"x60"
TSI_APS_RRFB_HAWK_009_NW_Corner_SB	37	No	12'	Yes	36"x60"
TSI_APS_RRFB_HAWK_010_NW_Corner_EB	34	No	14'	Yes	60"x60"
TSI_APS_RRFB_HAWK_011_NE_Corner_WB	38	No	12'	Yes	44"x60"
TSI_APS_RRFB_HAWK_012_NE_Corner_SB	35	No	14' 6"	Yes	60"x60"
TSI_APS_RRFB_HAWK_013_SE_Corner_NB	35	No	12'	Yes	60"x60"
TSI_APS_RRFB_HAWK_014_SE_Corner_WB	34	No	13'	Yes	60"x60"
TSI_APS_RRFB_HAWK_015_SW_Corner_EB	38	No	15'	Yes	60"x60"
TSI_APS_RRFB_HAWK_016_SW_Corner_NB	35	No	15'	Yes	60"x60"
TSI_APS_RRFB_HAWK_017_NE_Corner_WB	34	No	8'	Yes	60"x60"
TSI_APS_RRFB_HAWK_018_NE_Corner_SB	34	No	21'	No-14'	36"x60"
TSI_APS_RRFB_HAWK_019_SE_Corner_NB	33	No	15'	Yes	60"x60"
TSI_APS_RRFB_HAWK_020_SE_Corner_WB	33	No	11'	Yes	60"x60"
TSI_APS_RRFB_HAWK_021_SW_Corner_EB	34	No	14'	Yes	48"x60"
TSI_APS_RRFB_HAWK_022_SW_Corner_NB	38	No	9'	Yes	24"x54"
TSI_APS_RRFB_HAWK_023_NW_Corner_SB	38	No	18'	No-12'	60"x60"
TSI_APS_RRFB_HAWK_024_NW_Corner_EB	38	No	16'	Yes	50"x60"
TSI_APS_RRFB_HAWK_025_NE_Corner_WB	34	No	12'	Yes	60"x60"
TSI_APS_RRFB_HAWK_026_NE_Corner_SB	34	No	16'	Yes	60"x60"
TSI_APS_RRFB_HAWK_027_SE_Corner_NB	34	No	9'	Yes	36"x60"
TSI_APS_RRFB_HAWK_028_SE_Corner_WB	34	No	19'	Yes	36"x60"

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q4_PB_Height_in_Above_PAR	Q5_PB_to_CurbLine_18in_to_6Ft	Q6_PB_to_Curb_UptoMax10Ft	Q7_PB_to_XWalk_Line_Upto5Ft	Q8_PROWAG_Clear_32in_by_54in
TSI_APS_RRFB_HAWK_029_SW_Corner_EB	34	No	12'	Yes	48"x60"
TSI_APS_RRFB_HAWK_030_SW_Corner_NB	34	No	14'	Yes	48"x60"
TSI_APS_RRFB_HAWK_031_NW_Corner_SB	34	No	15'	Yes	60"x60"
TSI_APS_RRFB_HAWK_032_NW_Corner_EB	34	No	10'-6"	Yes	60"x60"
TSI_APS_RRFB_HAWK_033_NE_Corner_WB	34	No	12'	Yes	40"x60"
TSI_APS_RRFB_HAWK_034_NE_Corner_SB	32	No	10'	Yes	60"x60"
TSI_APS_RRFB_HAWK_035_SE_Corner_NB	38	No	8'	Yes	40"x60"
TSI_APS_RRFB_HAWK_036_NW_Corner_EB	38	No	15'	Yes	60"x60"
TSI_APS_RRFB_HAWK_037_NE_Corner_WB	42	No Curb	11' to face of DWS	Yes	36"x54"
TSI_APS_RRFB_HAWK_038_NE_Corner_SB	42	No Curb	5' to face of DWS	Yes	72"x72"
TSI_APS_RRFB_HAWK_039_SE_Corner_NB	42	No	13'	Yes	72"x72"
TSI_APS_RRFB_HAWK_040_SE_Corner_WB	42	No	8'	Yes	42"x72"
TSI_APS_RRFB_HAWK_041_SW_Corner_EB	41	No	7'	Yes	36"x72"
TSI_APS_RRFB_HAWK_042_SW_Corner_NB	42	No	7'	Yes	40"x60"
TSI_APS_RRFB_HAWK_043_NW_Corner_SB	42	No Curb	11' to face of DWS	Yes	60"x60"
TSI_APS_RRFB_HAWK_044_NW_Corner_EB	42	No Curb	10' to face of DWS	Yes	60"x60"
TSI_APS_RRFB_HAWK_045_SE_Corner_WB	36	No	7'	Yes	60"x60"
TSI_APS_RRFB_HAWK_046_SW_Corner_EB	42	No	11'	Yes	60"x60"
TSI_APS_RRFB_HAWK_047_SW_Corner_NB	42	No	14'	Yes	60"x60"
TSI_APS_RRFB_HAWK_048_NW_Corner_SB	42	No	8'	Yes	60"x60"
TSI_APS_RRFB_HAWK_049_NE_Corner_WB	42	No	7'	Yes	48"x60"
TSI_APS_RRFB_HAWK_050_NE_Corner_SB	42	No	7'	Yes	48"x60"
TSI_APS_RRFB_HAWK_051_SE_Corner_NB	42	No	6'-6"	Yes	48"x60"
TSI_APS_RRFB_HAWK_052_SE_Corner_WB	42	Yes	6'	Yes	42"x60"
TSI_APS_RRFB_HAWK_053_SW_Corner_EB	42	No	6'-6"	Yes	44"x60"
TSI_APS_RRFB_HAWK_054_SW_Corner_NB	34	No	6'-6"	Yes	44"x60"
TSI_APS_RRFB_HAWK_055_NW_Corner_SB	42	No	6'-6"	Yes	48"x48"
TSI_APS_RRFB_HAWK_056_NW_Corner_EB	42	No	6'-6"	Yes	48"x48"
TSI_APS_RRFB_HAWK_057_NE_Corner_WB	42	No	8'	Yes	54"x60"
TSI_APS_RRFB_HAWK_058_SE_Corner_WB	42	No	8'	Yes	54"x60"
TSI_APS_RRFB_HAWK_059_SW_Corner_EB	42	No	9'	Yes	48"x60"
TSI_APS_RRFB_HAWK_060_NW_Corner_EB	42	No	9'	Yes	48"x60"
TSI_APS_RRFB_HAWK_061_E_Corner_WB	42	Yes	4'-6"	Yes	46"x60"
TSI_APS_RRFB_HAWK_062_W_Corner_EB	42	No	9'	Yes	54"x60"
TSI_APS_RRFB_HAWK_063_NE_Corner_WB	42	No	7'	Yes	54"x60"
TSI_APS_RRFB_HAWK_064_SE_Corner_WB	42	No	8'	Yes	60"x60"

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q4_PB_Height_in_Above_PAR	Q5_PB_to_CurbLine_18in_to_6Ft	Q6_PB_to_Curb_UptoMax10Ft	Q7_PB_to_XWalk_Line_Upto5Ft	Q8_PROWAG_Clear_32in_by_54in
TSI_APS_RRFB_HAWK_065_SW_Corner_EB	42	No	9'	Yes	60"x60"
TSI_APS_RRFB_HAWK_066_NW_Corner_EB	42	No	9'	Yes	60"x60"
TSI_APS_RRFB_HAWK_067_NW_Corner_SB	42	No	8'	Yes	48"x60"
TSI_APS_RRFB_HAWK_068_SW_Corner_NB	42	No	9'	No-6'	48"x60"

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q9_ADAAG_Clear_36in_by_RampW	Q10_4Ft_Min_Clear_Around_Obst	Q11_4Ft_Min_Continuous_PAR	Q12_2x4Ft_DWS_68in_from_CurbL	Q13_Audible_Message_to_Cross
TSI_APS_RRFB_HAWK_001_NW_Corner_SB	60"	8'	8'	2'x6'	Yes
TSI_APS_RRFB_HAWK_002_NW_Corner_EB	60"	8'	8'	2'x6'	Yes
TSI_APS_RRFB_HAWK_003_NE_Corner_WB	48"	6'	6'	2'x6'	Yes
TSI_APS_RRFB_HAWK_004_NE_Corner_SB	48"	4'	4'	2'x'6'	Yes
TSI_APS_RRFB_HAWK_005_SE_Corner_NB	60"	10'	10'	2'x6'	Yes
TSI_APS_RRFB_HAWK_006_SE_Corner_WB	52"	4'4"	4'4"	2'x6'	Yes
TSI_APS_RRFB_HAWK_007_SW_Corner_EB	60"	6'	6'	2'x6'	Yes
TSI_APS_RRFB_HAWK_008_SW_Corner_NB	52"	4'4"	4'4"	2'x6'	Yes
TSI_APS_RRFB_HAWK_009_NW_Corner_SB	60"	5'	5'	2'x6'	Yes
TSI_APS_RRFB_HAWK_010_NW_Corner_EB	60"	7'	7'	2'x6'	Yes
TSI_APS_RRFB_HAWK_011_NE_Corner_WB	44"	5'6"	5'6"	2'x6'	Yes
TSI_APS_RRFB_HAWK_012_NE_Corner_SB	60"	10'+	10'+	2'x6'	Yes
TSI_APS_RRFB_HAWK_013_SE_Corner_NB	60"	4'6"	4'6"	2'x6'	Yes
TSI_APS_RRFB_HAWK_014_SE_Corner_WB	60"	6'	6'	2'x6'	Yes
TSI_APS_RRFB_HAWK_015_SW_Corner_EB	60"	10'+	10'+	2'x6'	Yes
TSI_APS_RRFB_HAWK_016_SW_Corner_NB	60"	10'+	10'+	2'x6'	Yes
TSI_APS_RRFB_HAWK_017_NE_Corner_WB	60"	5'	10'+	2'x4'	No
TSI_APS_RRFB_HAWK_018_NE_Corner_SB	36"	5'	10'+	2'x4'	Yes
TSI_APS_RRFB_HAWK_019_SE_Corner_NB	60"	8'-6"	8'-6"	2'x6'	Yes
TSI_APS_RRFB_HAWK_020_SE_Corner_WB	60"	8'-6"	8'-6"	2'x6'	Yes
TSI_APS_RRFB_HAWK_021_SW_Corner_EB	48"	5'	5'	2'x4'	Yes
TSI_APS_RRFB_HAWK_022_SW_Corner_NB	24"	5'	5'	2'x4'	Yes
TSI_APS_RRFB_HAWK_023_NW_Corner_SB	60"	8'	8'	2'x4'	Yes
TSI_APS_RRFB_HAWK_024_NW_Corner_EB	60"	8'	8'	2'x4'	Yes
TSI_APS_RRFB_HAWK_025_NE_Corner_WB	60"	10'+	10'+	Old Standard DWS	Yes
TSI_APS_RRFB_HAWK_026_NE_Corner_SB	60"	10'+	10'+	Old Standard DWS	Yes
TSI_APS_RRFB_HAWK_027_SE_Corner_NB	36"	5'-6"	5'-6"	Old Standard DWS	Yes
TSI_APS_RRFB_HAWK_028_SE_Corner_WB	36"	5'-6"	5'-6"	Old Standard DWS	No

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q9_ADAAG_Clear_36in_by_RampW	Q10_4Ft_Min_Clear_Around_Obst	Q11_4Ft_Min_Continuous_PAR	Q12_2x4Ft_DWS_68in_from_CurbL	Q13_Audible_Message_to_Cross
TSI_APS_RRFB_HAWK_029_SW_Corner_EB	48"	4'	4'	Old Standard DWS	Yes
TSI_APS_RRFB_HAWK_030_SW_Corner_NB	48"	4'	4'	Old Standard DWS	Yes
TSI_APS_RRFB_HAWK_031_NW_Corner_SB	60"	10'+	10'+	Old Standard DWS	No
TSI_APS_RRFB_HAWK_032_NW_Corner_EB	60"	10'+	10'+	Old Standard DWS	Yes
TSI_APS_RRFB_HAWK_033_NE_Corner_WB	40"	5'	5'	2'x4'	Yes
TSI_APS_RRFB_HAWK_034_NE_Corner_SB	60"	5'	5'	2'x4'	Yes
TSI_APS_RRFB_HAWK_035_SE_Corner_NB	40"	6'	6'	2'x6'	Yes
TSI_APS_RRFB_HAWK_036_NW_Corner_EB	60"	10'+	10'+	2'x4'	Yes
TSI_APS_RRFB_HAWK_037_NE_Corner_WB	36"	6'	6'	2'x10'	Yes
TSI_APS_RRFB_HAWK_038_NE_Corner_SB	72"	6'	6'	2'x6'	Yes
TSI_APS_RRFB_HAWK_039_SE_Corner_NB	72"	4'	4'	2'x6'	Yes
TSI_APS_RRFB_HAWK_040_SE_Corner_WB	42"	12'	12'	2'x6'	Yes
TSI_APS_RRFB_HAWK_041_SW_Corner_EB	36"	12'	12'	2'x6'	Yes
TSI_APS_RRFB_HAWK_042_SW_Corner_NB	40"	6'	6'	2'x6'	Yes
TSI_APS_RRFB_HAWK_043_NW_Corner_SB	60"	6'	6'	2'x6'	Yes
TSI_APS_RRFB_HAWK_044_NW_Corner_EB	60"	10'	10'	2'x10'	Yes
TSI_APS_RRFB_HAWK_045_SE_Corner_WB	60"x60"-No ramp	5'	5'	No DWS	No
TSI_APS_RRFB_HAWK_046_SW_Corner_EB	60"	4'	4'	2'x5'	Yes
TSI_APS_RRFB_HAWK_047_SW_Corner_NB	60"	4'	4'	Old Standard No DWS	Yes
TSI_APS_RRFB_HAWK_048_NW_Corner_SB	60"	7'	7'	Old Standard No DWS	Yes
TSI_APS_RRFB_HAWK_049_NE_Corner_WB	48"	7'	7'	2'x5'	No
TSI_APS_RRFB_HAWK_050_NE_Corner_SB	48"	7'	7'	2'x5'	No
TSI_APS_RRFB_HAWK_051_SE_Corner_NB	48"	6'-6"	6'-6"	2'x5'	No
TSI_APS_RRFB_HAWK_052_SE_Corner_WB	42"	6'	6'	2'x5'	No
TSI_APS_RRFB_HAWK_053_SW_Corner_EB	44"	6'-6"	6'-6"	2'x5'	No
TSI_APS_RRFB_HAWK_054_SW_Corner_NB	44"	6'-6"	6'-6"	2'x5'	No
TSI_APS_RRFB_HAWK_055_NW_Corner_SB	48"	6'-6"	6'-6"	2'x4'	No
TSI_APS_RRFB_HAWK_056_NW_Corner_EB	48"	6'-6"	6'-6"	2'x4'	No
TSI_APS_RRFB_HAWK_057_NE_Corner_WB	54"	10'+	10'+	2'x4'	Yes
TSI_APS_RRFB_HAWK_058_SE_Corner_WB	54"	10'+	10'+	2'x5'	Yes
TSI_APS_RRFB_HAWK_059_SW_Corner_EB	48"	10'+	10'+	2'x4'	Yes
TSI_APS_RRFB_HAWK_060_NW_Corner_EB	48"	10'+	10'+	2'x4'	Yes
TSI_APS_RRFB_HAWK_061_E_Corner_WB	46"	12'	12'	2'x8'	Yes
TSI_APS_RRFB_HAWK_062_W_Corner_EB	43"	4'-6"	4'-6"	2'x8'	Yes
TSI_APS_RRFB_HAWK_063_NE_Corner_WB	54"	6'	4'-6"	2'x9'	Yes
TSI_APS_RRFB_HAWK_064_SE_Corner_WB	60"	10'+	10'+	2'x6'	Yes

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q9_ADAAG_Clear_36in_by_RampW	Q10_4Ft_Min_Clear_Around_Obst	Q11_4Ft_Min_Continuous_PAR	Q12_2x4Ft_DWS_68in_from_CurbL	Q13_Audible_Message_to_Cross
TSI_APS_RRFB_HAWK_065_SW_Corner_EB	60"	10'+	10'+	2'x6'	Yes
TSI_APS_RRFB_HAWK_066_NW_Corner_EB	60"	10'+	10'+	2'x6'	Yes
TSI_APS_RRFB_HAWK_067_NW_Corner_SB	48"	5'	5'	2'x4'	Yes
TSI_APS_RRFB_HAWK_068_SW_Corner_NB	48"	6'	6'	2'x4'	Yes

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q14A_Locator_Tone_Provided	Q14B_Vibrotactile_or_Percuss	Q14C_YellowLightsFlashing_2x	Q14D_Message	Q15_PB_Reach_10in_Max
TSI_APS_RRFB_HAWK_001_NW_Corner_SB	Yes	Yes	Yes-Spoken Twice	Jacobia walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_002_NW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_003_NE_Corner_WB	Yes	No	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_004_NE_Corner_SB	Yes	Yes	Yes-Spoken Twice	Jacobia walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_005_SE_Corner_NB	Yes	Yes	Yes-Spoken Twice	Jacobia walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_006_SE_Corner_WB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_007_SW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_008_SW_Corner_NB	Yes	Yes	Yes-Spoken Twice	Jacobia walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_009_NW_Corner_SB	Yes	Yes	Yes-Spoken Twice	Swenson walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_010_NW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_011_NE_Corner_WB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_012_NE_Corner_SB	Yes	Yes	Yes-Spoken Twice	Swenson walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_013_SE_Corner_NB	Yes	Yes	Yes-Spoken Twice	Swenson walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_014_SE_Corner_WB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_015_SW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_016_SW_Corner_NB	Yes	Yes	Yes-Spoken Twice	Swenson walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_017_NE_Corner_WB	Yes	No	No	No message	N/A
TSI_APS_RRFB_HAWK_018_NE_Corner_SB	Yes	No	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_019_SE_Corner_NB	Yes	No	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_020_SE_Corner_WB	Yes	No	Yes-Spoken Twice	Douglas sign is on to cross	N/A
TSI_APS_RRFB_HAWK_021_SW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Douglas walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_022_SW_Corner_NB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_023_NW_Corner_SB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_024_NW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_025_NE_Corner_WB	Yes	Yes	Yes-Spoken Twice	Center walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_026_NE_Corner_SB	Yes	No	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_027_SE_Corner_NB	Yes	No	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_028_SE_Corner_WB	No	No	No	No Message	N/A

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q14A_Locator_Tone_Provided	Q14B_Vibrotactile_or_Percuss	Q14C_YellowLightsFlashing_2x	Q14D_Message	Q15_PB_Reach_10in_Max
TSI_APS_RRFB_HAWK_029_SW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Center walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_030_SW_Corner_NB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_031_NW_Corner_SB	Yes	No	No	No Message	N/A
TSI_APS_RRFB_HAWK_032_NW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Center walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_033_NE_Corner_WB	Yes	No	Yes-Spoken Twice	Fairway walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_034_NE_Corner_SB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_035_SE_Corner_NB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_036_NW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Fairway walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_037_NE_Corner_WB	Yes	Yes	Yes-Spoken Twice	Walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_038_NE_Corner_SB	Yes	Yes	Yes-Spoken Twice	Walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_039_SE_Corner_NB	Yes	Yes	Yes-Spoken Twice	Walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_040_SE_Corner_WB	Yes	Yes	Yes-Spoken Twice	Walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_041_SW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_042_SW_Corner_NB	Yes	Yes	Yes-Spoken Twice	Walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_043_NW_Corner_SB	Yes	Yes	Yes-Spoken Twice	Walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_044_NW_Corner_EB	Yes	Yes	Yes-Spoken Twice	Walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_045_SE_Corner_WB	No	No	No	No message	Yes 8"
TSI_APS_RRFB_HAWK_046_SW_Corner_EB	Yes	Yes	Yes-Spoken Twice	State Route 202 walk sign is on	N/A
TSI_APS_RRFB_HAWK_047_SW_Corner_NB	Yes	Yes	Yes-Spoken Twice	Snoqualmie Parkway walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_048_NW_Corner_SB	Yes	Yes	Yes-Spoken Twice	Snoqualmie Parkway walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_049_NE_Corner_WB	No	No	N/A	No message	N/A
TSI_APS_RRFB_HAWK_050_NE_Corner_SB	No	No	N/A	No message	N/A
TSI_APS_RRFB_HAWK_051_SE_Corner_NB	No	No	N/A	No message	N/A
TSI_APS_RRFB_HAWK_052_SE_Corner_WB	No	No	N/A	No message	N/A
TSI_APS_RRFB_HAWK_053_SW_Corner_EB	No	No	N/A	No message	N/A
TSI_APS_RRFB_HAWK_054_SW_Corner_NB	No	No	N/A	No message	N/A
TSI_APS_RRFB_HAWK_055_NW_Corner_SB	No	No	N/A	No message	N/A
TSI_APS_RRFB_HAWK_056_NW_Corner_EB	No	No	N/A	No message	N/A
TSI_APS_RRFB_HAWK_057_NE_Corner_WB	Yes	No	Yes-Spoken Twice	Yellow light	N/A
TSI_APS_RRFB_HAWK_058_SE_Corner_WB	Yes	No	Yes-Spoken twice	Yellow light	N/A
TSI_APS_RRFB_HAWK_059_SW_Corner_EB	Yes	No	Yes-Spoken Twice	Yellow light	N/A
TSI_APS_RRFB_HAWK_060_NW_Corner_EB	Yes	No	Yes-Spoken Twice	Yellow light	N/A
TSI_APS_RRFB_HAWK_061_E_Corner_WB	Yes	No	Yes-Spoken Twice	Yellow light	N/A
TSI_APS_RRFB_HAWK_062_W_Corner_EB	Yes	No	Yes-Spoken Twice	Yellow light	N/A
TSI_APS_RRFB_HAWK_063_NE_Corner_WB	Yes	No	Yes-Spoken Twice	Yellow light	N/A
TSI_APS_RRFB_HAWK_064_SE_Corner_WB	Yes	No	Yes-Spoken Twice	Yellow light	N/A

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q14A_Locator_Tone_Provided	Q14B_Vibrotactile_or_Percuss	Q14C_YellowLightsFlashing_2x	Q14D_Message	Q15_PB_Reach_10in_Max
TSI_APS_RRFB_HAWK_065_SW_Corner_EB	Yes	No	Yes-Spoken Twice	Yellow light	N/A
TSI_APS_RRFB_HAWK_066_NW_Corner_EB	Yes	No	Yes-Spoken Twice	Yellow light	N/A
TSI_APS_RRFB_HAWK_067_NW_Corner_SB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A
TSI_APS_RRFB_HAWK_068_SW_Corner_NB	Yes	Yes	Yes-Spoken Twice	Snoqualmie walk sign is on to cross	N/A

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q16_Ped_Countdown_Present	TSI_Photo_Attachment_ID	Notes
TSI_APS_RRFB_HAWK_001_NW_Corner_SB	Yes	TSI_APS_RRFB_HAWK_001_NW_Corner_SB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_002_NW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_002_NW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_003_NE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_003_NE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum. No vibrotactile or percussive functionality
TSI_APS_RRFB_HAWK_004_NE_Corner_SB	Yes	TSI_APS_RRFB_HAWK_004_NE_Corner_SB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_005_SE_Corner_NB	Yes	TSI_APS_RRFB_HAWK_005_SE_Corner_NB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_006_SE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_006_SE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_007_SW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_007_SW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_008_SW_Corner_NB	Yes	TSI_APS_RRFB_HAWK_008_SW_Corner_NB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_009_NW_Corner_SB	Yes	TSI_APS_RRFB_HAWK_009_NW_Corner_SB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_010_NW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_010_NW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_011_NE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_011_NE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum. Directional arrow not parallel to crossing
TSI_APS_RRFB_HAWK_012_NE_Corner_SB	Yes	TSI_APS_RRFB_HAWK_012_NE_Corner_SB.jpg	Pushbutton to curb exceeds 10' maximum. Directional arrow not parallel to crossing
TSI_APS_RRFB_HAWK_013_SE_Corner_NB	Yes	TSI_APS_RRFB_HAWK_013_SE_Corner_NB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_014_SE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_014_SE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_015_SW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_015_SW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_016_SW_Corner_NB	Yes	TSI_APS_RRFB_HAWK_016_SW_Corner_NB.jpg	Pushbutton to curb exceeds 10' maximum
TSI_APS_RRFB_HAWK_017_NE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_017_NE_Corner_WB.jpg	No audible message, no vibrotactile or percussive functionality.
TSI_APS_RRFB_HAWK_018_NE_Corner_SB	Yes	TSI_APS_RRFB_HAWK_018_NE_Corner_SB.jpg	Pushbutton to curb exceeds 10' maximum. Pushbutton to crosswalk line exceeds 5' max. No vibrotactile or percussive functionality.
TSI_APS_RRFB_HAWK_019_SE_Corner_NB	Yes	TSI_APS_RRFB_HAWK_019_SE_Corner_NB.jpg	Pushbutton to curb exceeds 10' maximum. Directional arrow not parallel to crossing. Grade is steeper (9%) at buttons because of topography, no vibrotactile or percussive functionality.
TSI_APS_RRFB_HAWK_020_SE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_020_SE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum. No vibrotactile or percussive functionality. Grade is steeper (9%) at buttons because of topography.
TSI_APS_RRFB_HAWK_021_SW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_021_SW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_022_SW_Corner_NB	Yes	TSI_APS_RRFB_HAWK_022_SW_Corner_NB.jpg	Clear space less than 36" at pushbutton (too close to flare)
TSI_APS_RRFB_HAWK_023_NW_Corner_SB	Yes	TSI_APS_RRFB_HAWK_023_NW_Corner_SB.jpg	Pushbutton to curb exceeds 10' maximum. Pushbutton to crosswalk line exceeds 5' max.
TSI_APS_RRFB_HAWK_024_NW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_024_NW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_025_NE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_025_NE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_026_NE_Corner_SB	Yes	TSI_APS_RRFB_HAWK_026_NE_Corner_SB.jpg	Pushbutton to curb exceeds 10' maximum. No vibrotactile or percussive functionality.
TSI_APS_RRFB_HAWK_027_SE_Corner_NB	Yes	TSI_APS_RRFB_HAWK_027_SE_Corner_NB.jpg	No vibrotactile or percussive functionality.
TSI_APS_RRFB_HAWK_028_SE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_028_SE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum. No audible message, no vibrotactile or percussive functionality.

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q16_Ped_Countdown_Present	TSI_Photo_Attachment_ID	Notes
TSI_APS_RRFB_HAWK_029_SW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_029_SW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_030_SW_Corner_NB	Yes	TSI_APS_RRFB_HAWK_030_SW_Corner_NB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_031_NW_Corner_SB	Yes	TSI_APS_RRFB_HAWK_031_NW_Corner_SB.jpg	Pushbutton to curb exceeds 10' maximum. No audible message, no vibrotactile or percussive functionality.
TSI_APS_RRFB_HAWK_032_NW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_032_NW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_033_NE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_033_NE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum. No vibrotactile or percussive functionality.
TSI_APS_RRFB_HAWK_034_NE_Corner_SB	Yes	TSI_APS_RRFB_HAWK_034_NE_Corner_SB.jpg	<Null>
TSI_APS_RRFB_HAWK_035_SE_Corner_NB	Yes	TSI_APS_RRFB_HAWK_035_SE_Corner_NB.jpg	<Null>
TSI_APS_RRFB_HAWK_036_NW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_036_NW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum. Steep slope at button
TSI_APS_RRFB_HAWK_037_NE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_037_NE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_038_NE_Corner_SB	Yes	TSI_APS_RRFB_HAWK_038_NE_Corner_SB.jpg	<Null>
TSI_APS_RRFB_HAWK_039_SE_Corner_NB	Yes	TSI_APS_RRFB_HAWK_039_SE_Corner_NB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_040_SE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_040_SE_Corner_WB.jpg	<Null>
TSI_APS_RRFB_HAWK_041_SW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_041_SW_Corner_EB.jpg	<Null>
TSI_APS_RRFB_HAWK_042_SW_Corner_NB	Yes	TSI_APS_RRFB_HAWK_042_SW_Corner_NB.jpg	<Null>
TSI_APS_RRFB_HAWK_043_NW_Corner_SB	Yes	TSI_APS_RRFB_HAWK_043_NW_Corner_SB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_044_NW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_044_NW_Corner_EB.jpg	<Null>
TSI_APS_RRFB_HAWK_045_SE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_045_SE_Corner_WB.jpg	Pushbutton to curb exceeds 10' maximum. No audible message, no vibrotactile or percussive functionality.
TSI_APS_RRFB_HAWK_046_SW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_046_SW_Corner_EB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_047_SW_Corner_NB	Yes	TSI_APS_RRFB_HAWK_047_SW_Corner_NB.jpg	Pushbutton to curb exceeds 10' maximum.
TSI_APS_RRFB_HAWK_048_NW_Corner_SB	Yes	TSI_APS_RRFB_HAWK_048_NW_Corner_SB.jpg	<Null>
TSI_APS_RRFB_HAWK_049_NE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_049_NE_Corner_WB.jpg	No APS - WSDOT jurisdiction
TSI_APS_RRFB_HAWK_050_NE_Corner_SB	Yes	TSI_APS_RRFB_HAWK_050_NE_Corner_SB.jpg	No APS - WSDOT jurisdiction
TSI_APS_RRFB_HAWK_051_SE_Corner_NB	Yes	TSI_APS_RRFB_HAWK_051_SE_Corner_NB.jpg	No APS - WSDOT jurisdiction
TSI_APS_RRFB_HAWK_052_SE_Corner_WB	Yes	TSI_APS_RRFB_HAWK_052_SE_Corner_WB.jpg	No APS - WSDOT jurisdiction
TSI_APS_RRFB_HAWK_053_SW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_053_SW_Corner_EB.jpg	No APS - WSDOT jurisdiction
TSI_APS_RRFB_HAWK_054_SW_Corner_NB	Yes	TSI_APS_RRFB_HAWK_054_SW_Corner_NB.jpg	No APS - WSDOT jurisdiction
TSI_APS_RRFB_HAWK_055_NW_Corner_SB	Yes	TSI_APS_RRFB_HAWK_055_NW_Corner_SB.jpg	No APS - WSDOT jurisdiction
TSI_APS_RRFB_HAWK_056_NW_Corner_EB	Yes	TSI_APS_RRFB_HAWK_056_NW_Corner_EB.jpg	No APS - WSDOT jurisdiction
TSI_APS_RRFB_HAWK_057_NE_Corner_WB	N/A	TSI_APS_RRFB_HAWK_057_NE_Corner_WB.jpg	WSDOT jurisdiction?
TSI_APS_RRFB_HAWK_058_SE_Corner_WB	N/A	TSI_APS_RRFB_HAWK_058_SE_Corner_WB.jpg	WSDOT jurisdiction?
TSI_APS_RRFB_HAWK_059_SW_Corner_EB	N/A	TSI_APS_RRFB_HAWK_059_SW_Corner_WB.jpg	WSDOT jurisdiction?
TSI_APS_RRFB_HAWK_060_NW_Corner_EB	N/A	TSI_APS_RRFB_HAWK_060_NW_Corner_WB.jpg	WSDOT jurisdiction?
TSI_APS_RRFB_HAWK_061_E_Corner_WB	N/A	TSI_APS_RRFB_HAWK_061_E_Corner_WB.jpg	WSDOT jurisdiction?
TSI_APS_RRFB_HAWK_062_W_Corner_EB	N/A	TSI_APS_RRFB_HAWK_062_W_Corner_EB.jpg	WSDOT jurisdiction?
TSI_APS_RRFB_HAWK_063_NE_Corner_WB	N/A	TSI_APS_RRFB_HAWK_063_NE_Corner_WB.jpg	WSDOT jurisdiction?
TSI_APS_RRFB_HAWK_064_SE_Corner_WB	N/A	TSI_APS_RRFB_HAWK_064_SE_Corner_WB.jpg	WSDOT jurisdiction?

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	Q16_Ped_Countdown_Present	TSI_Photo_Attachment_ID	Notes
TSI_APS_RRFB_HAWK_065_SW_Corner_EB	N/A	TSI_APS_RRFB_HAWK_065_SW_Corner_EB.jpg	WSDOT jurisdiction?
TSI_APS_RRFB_HAWK_066_NW_Corner_EB	N/A	TSI_APS_RRFB_HAWK_066_NW_Corner_EB.jpg	WSDOT jurisdiction?
TSI_APS_RRFB_HAWK_067_NW_Corner_SB	Yes	TSI_APS_RRFB_HAWK_067_NW_Corner_SB.jpg	<Null>
TSI_APS_RRFB_HAWK_068_SW_Corner_NB	Yes	TSI_APS_RRFB_HAWK_068_SW_Corner_NB.jpg	Pushbutton to crosswalk line exceeds 5' max.

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	ADA_Compliant	July2023_Snoq_Parkwy_Rehab	Alt_ID_Number
TSI_APS_RRFB_HAWK_001_NW_Corner_SB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	3
TSI_APS_RRFB_HAWK_002_NW_Corner_EB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	4
TSI_APS_RRFB_HAWK_003_NE_Corner_WB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	8
TSI_APS_RRFB_HAWK_004_NE_Corner_SB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	7
TSI_APS_RRFB_HAWK_005_SE_Corner_NB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	6
TSI_APS_RRFB_HAWK_006_SE_Corner_WB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	5
TSI_APS_RRFB_HAWK_007_SW_Corner_EB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	1
TSI_APS_RRFB_HAWK_008_SW_Corner_NB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	2
TSI_APS_RRFB_HAWK_009_NW_Corner_SB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_010_NW_Corner_EB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_011_NE_Corner_WB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_012_NE_Corner_SB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_013_SE_Corner_NB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_014_SE_Corner_WB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_015_SW_Corner_EB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	9
TSI_APS_RRFB_HAWK_016_SW_Corner_NB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	10
TSI_APS_RRFB_HAWK_017_NE_Corner_WB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_018_NE_Corner_SB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_019_SE_Corner_NB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_020_SE_Corner_WB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_021_SW_Corner_EB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_022_SW_Corner_NB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_023_NW_Corner_SB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_024_NW_Corner_EB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_025_NE_Corner_WB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	27
TSI_APS_RRFB_HAWK_026_NE_Corner_SB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	28
TSI_APS_RRFB_HAWK_027_SE_Corner_NB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	32
TSI_APS_RRFB_HAWK_028_SE_Corner_WB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	31

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	ADA_Compliant	July2023_Snoq_Parkwy_Rehab	Alt_ID_Number
TSI_APS_RRFB_HAWK_029_SW_Corner_EB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	30
TSI_APS_RRFB_HAWK_030_SW_Corner_NB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	29
TSI_APS_RRFB_HAWK_031_NW_Corner_SB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	25
TSI_APS_RRFB_HAWK_032_NW_Corner_EB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	26
TSI_APS_RRFB_HAWK_033_NE_Corner_WB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_034_NE_Corner_SB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_035_SE_Corner_NB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_036_NW_Corner_EB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_037_NE_Corner_WB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	47
TSI_APS_RRFB_HAWK_038_NE_Corner_SB	Yes	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	48
TSI_APS_RRFB_HAWK_039_SE_Corner_NB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_040_SE_Corner_WB	Yes	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	51
TSI_APS_RRFB_HAWK_041_SW_Corner_EB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_042_SW_Corner_NB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_043_NW_Corner_SB	No	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	45
TSI_APS_RRFB_HAWK_044_NW_Corner_EB	Yes	Pedestrian pushbutton pole relocated to ADA-compliant location with pre-existing salvaged pushbutton and display with enough clear space and under 2% slope.	46
TSI_APS_RRFB_HAWK_045_SE_Corner_WB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_046_SW_Corner_EB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_047_SW_Corner_NB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_048_NW_Corner_SB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_049_NE_Corner_WB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_050_NE_Corner_SB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_051_SE_Corner_NB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_052_SE_Corner_WB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_053_SW_Corner_EB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_054_SW_Corner_NB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_055_NW_Corner_SB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_056_NW_Corner_EB	No	<Null>	<Null>
TSI_APS_RRFB_HAWK_057_NE_Corner_WB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_058_SE_Corner_WB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_059_SW_Corner_EB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_060_NW_Corner_EB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_061_E_Corner_WB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_062_W_Corner_EB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_063_NE_Corner_WB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_064_SE_Corner_WB	Yes	<Null>	<Null>

City of Snoqualmie
2023 ADA APS/RRFB/HAWK Inventory

TSI_APS_RRFB_HAWK_ID	ADA_Compliant	July2023_Snoq_Parkwy_Rehab	Alt_ID_Number
TSI_APS_RRFB_HAWK_065_SW_Corner_EB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_066_NW_Corner_EB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_067_NW_Corner_SB	Yes	<Null>	<Null>
TSI_APS_RRFB_HAWK_068_SW_Corner_NB	No	<Null>	<Null>